Leica TS03/TS07



User Manual Version 1.0 English

- when it has to be **right**



Introduction

Purchase	Congratulations on the purchase of the Leica TS03/TS07.		
[]i	This manual contains important safety directions as well as instructions for set- ting up the product and operating it. Refer to "1 Safety Directions" for further information.		
	Read carefully throu	igh the User Manual before you switch on the product.	
Product identification	The model and serial number of your product are indicated on the type plate.		
	Always refer to this Leica Geosystems a	Always refer to this information when you need to contact your agency or Leica Geosystems authorised service centre.	
Trademarks	 Windows is a registered trademark of Microsoft Corporation in the United States and other countries Revete attraction is a registered trademark of Rivets ath SIC. Inc. 		
	All other trademarks	s are the property of their respective owners.	
-			
Validity of this manual	This manual applies to TS03 and TS07 instruments. Where there are differences between the various instruments they are clearly described.		
	For the Tunnel application, refer to the separate manual "Leica TS03/TS07 Tun- nel Application".		
	For the Mining appli ing Application".	cation, refer to the separate manual "Leica TS03/TS07 Min-	
Leica Geosystems address book	On the last page of this manual, you can find the address of Leica Geosystems headquarters. For a list of regional contacts, please visit http://leica-geosystems.com/contact-us/sales_support .		
[™] w⊚rld	myWorld@Leica Geosystems (https://myworld.leica-geosystems.com) offers		
	With direct access to whenever it is conve	o myWorld, you are able to access all relevant services enient for you.	
	Service	Description	
	myProducts	Add all products that you and your company own and explore your world of Leica Geosystems: View detailed information on your products and update your products with the latest software and keep up- to-date with the latest documentation.	
	myService	View the current service status and full service his- tory of your products in Leica Geosystems service centres. Access detailed information on the services performed and download your latest calibration cer- tificates and service reports.	

Service	Description
mySupport	Create new support requests for your products that will be answered by your local Leica Geosystems Support Team. View the complete history of your support requests and view detailed information on each request in case you want to refer to previous support requests.
myTraining	Enhance your product knowledge with Leica Geosys- tems Campus - Information, Knowledge, Training. Study the latest online training material on your products and register for seminars or courses in your country.
myTrustedServices	Add your subscriptions and manage users for Leica Geosystems Trusted Services, the secure software services, that assist you to optimise your workflow and increase your efficiency.

Table of Contents

1	Safet	ty Directions	8
	1.1	General	8
	1.2	Definition of Use	9
	1.3	Limits of Use	9
	1.4	Responsibilities	9
	1.5	Hazards of Use	10
	1.6	Laser Classification	13
		1.6.1 General	13
		1.6.2 Distancer, Measurements with Reflectors	14
		1.6.3 Electronic Guide Light EGL	14
		1.6.4 Laser Plummet	15
		1.6.5 AutoHeight Laser Plummet	16
	1.7	Electromagnetic Compatibility EMC	17
	1.8	FCC Statement, Applicable in U.S.	18
	1.9	ICES-003 Statement, Applicable in Canada	20
2	Desc	ription of the System	21
	2.1	System Components	21
	2.2	Container Contents	22
	2.3	Instrument Components	23
3	User	Interface	25
	3.1	Keyboard	25
	3.2	Screen	26
	3.3	Status Icons	26
	3.4	Icon Pop-up Bubbles	29
	3.5	Softkeys	30
	3.6	Operating Principles	31
	3.7	Pointsearch	32
	3.8	Graphic Symbols	33
4	Opera	ation	35
	4.1	Instrument Setup	35
	4.2	Batteries	38
		4.2.1 Operating Principles	38
		4.2.2 Battery for the TS Instrument	39
	4.3	Data Storage	39
	4.4	Main Menu	40
	4.5	Distance Measurements - Guidelines for Correct Results	42
5	Settings		
	5.1	Work Settings	44
	5.2	Regional Settings	46
	5.3	Data Settings	49
	5.4	Screen & Audio Settings	50
	5.5	EDM Settings	52
	5.6	Interface Settings	57
	5.7	FIP Client	58
	5.8	Internet Settings	60
	5.9	Adjust	61
	5.10	Startup Sequence	62
	5.11	System Information	62
	5.12	Licence Keys	65
	5.13	Instrument Protection with PIN	65
	5.14	Loading Software	66

6	Apps	- Getting	Started	68
	6.1	Overview		68
	6.2	Starting a	an App	68
	6.3	Setting th	ne Job	69
	6.4	Station S	etup	70
7	Apps			72
	7.1	Common	Fields	72
	7.2	Station S	etup	72
		7.2.1	Starting	72
		7.2.2	Measuring the Target Points	75
		7.2.3	Station Setup Results	77
	7.3	Surveying		80
	7.4	Setout		80
	7.5	Reference	e Line	84
		7.5.1	Overview	84
		7.5.2	Defining the Base Line	84
		7.5.3	Defining the Reference Line	85
		7.5.4	Measure Line & Offset	86
		7.5.5	Stakeout	87
		7.5.6	Grid Stakeout	89
	_ /	/.5./	Line Segmentation	91
	7.6	Reference	e Arc	94
		7.6.1	Overview	94
		7.6.2	Defining the Reference Arc	94
		7.6.3	Measure Line & Offset	96
		7.0.4	Stakeout	97
	7.7	Reference	2 Plane	100
	7.8		ICE	102
	7.9			104
		7.9.1		104
		7.9.2	2D / 3D Aled Area to Reference Plane	100
		7.9.3		107
		7.9.4		100
	7 10	Pomoto H	Alea Division loight	111
	7.10			113
	,	7 11 1	Starting	114
		7 11 2	Inverse and Traverse	115
		7 11 3	Intersections	115
		7.11.4	Offsets	 117
		7.11.5	Line - Extension	118
	7.12	Road 2D		118
	7.13	Road 3D		121
		7.13.1	Starting	121
		7.13.2	Basic Terms	122
		7.13.3	Creating or Uploading Alignment Files	126
		7.13.4	Stake	128
		7.13.5	Check	129
		7.13.6	Stake Slope	130
		7.13.7	Check Slope	133
	7.14	Traverse		134
		7.14.1	Overview	134
		7.14.2	Starting and Configuring Traverse	135
		7.14.3	Measuring Traverse	137
		7.14.4	Moving ahead	139

		7.14.5 Closing a Traverse	140
	7.15	Tunnel	143
8	Favou	urites	144
	8.1	Overview	144
	8.2	Target Offset	145
		8.2.1 Overview	145
		8.2.2 Cylindrical Offset	146
	8.3	Hidden Point	148
	8.4	Check Tie	149
	8.5	EDM Tracking	150
	8.6	Backsight Check	151
	8.7	SKETCHPad	151
9	Codin	ıg	153
	9.1	Coding	153
	9.2	Quick Coding	154
10	MapV	/iew Interactive Display Feature	156
	10.1	Overview	156
	10.2	Accessing MapView	156
	10.3	Configuring MapView	156
	10.4	MapView Components	157
		10.4.1 Screen Area	157
		10.4.2 Keys, Softkeys and Toolbar	157
		10.4.3 Point Symbols	158
	10.5	Selecting Points	159
11	Imagi	ing & Sketching	160
	11.1	Screenshot	160
	11.2	Sketching	160
	11.3	Image Management	161
12	Data	Management	163
	12.1	Manage	163
	12.2	Exporting Data	164
	12.3	Importing Data	168
	12.4	Working with a USB Memory Stick	170
	12.5	Working with the SD Card	171
	12.6	Working with the Internal Memory	172
	12.7	Working with Bluetooth	173
	12.8	Working with the SIM Card	1/3
13	Check	k & Adjust	175
	13.1	Overview	175
	13.2	Preparation	175
	13.3	Adjusting Line-of-Sight and Vertical Index Error	176
	13.4	Adjusting the Compensator	178
	13.5	Adjusting the Tilting Axis Error	1/9
	13.6	Adjusting the Circular Level of the Instrument and Tribrach	180
	13./	Adjusting the Lincular Level of the Prism Pole	181
	13.8	Inspecting the Laser Plummet of the Instrument	181
	13.9	כפואוכווצ נוופ וווףטט	182
14	mySe	ecurity	183
15	Care a	and Transport	185
	15.1	Transport	185
	15.2	Storage	185
	15.3	Cleaning and Drying	186

16	Techni	cal Data	187
	16.1	Angle Measurement	187
	16.2	Distance Measurement with Reflectors	187
	16.3	Distance Measurement without Reflectors (Non-Prism mode)	188
	16.4	Distance Measurement Reflector (>4.0km)	189
	16.5	Conformity to National Regulations	190
		16.5.1 TS03	190
		16.5.2 TS07	190
		16.5.3 Dangerous Goods Regulations	191
	16.6	General Technical Data of the Product	191
	16.7	Scale Correction	195
	16.8	Reduction Formulas	196
17	Softwa	are Licence Agreement	199
Арр	endix A	Menu Tree	200
Арр	endix B	Directory Structure	201

÷	Safety Directions		
1.1	General	General	
Description	The following directions enable the person responsible for the product, and the person who actually uses the equipment, to anticipate and avoid operational hazards.		
	The person responsible these directions and adl	for the product must ensure that all users understand nere to them.	
About warning messages	Warning messages are a ment. They appear whe	In essential part of the safety concept of the instru- rever hazards or hazardous situations can occur.	
	Warning messages		
	make the user alert of the product.contain general rule	about direct and indirect hazards concerning the use as of behaviour.	
	For the users' safety, all safety instructions and safety messages shall be strictly observed and followed! Therefore, the manual must always be available to all persons performing any tasks described here		
	DANGER, WARNING, C identifying levels of haze damage. For your safety lowing table with the di tary safety information s well as supplementary t	AUTION and NOTICE are standardised signal words for ards and risks related to personal injury and property v, it is important to read and fully understand the fol- fferent signal words and their definitions! Supplemen- symbols may be placed within a warning message as ext.	
	Туре	Description	
	A DANGER	Indicates an imminently hazardous situation which, if not avoided, will result in death or serious injury.	
	A warning	Indicates a potentially hazardous situation or an unintended use which, if not avoided, could result in death or serious injury.	
		Indicates a potentially hazardous situation or an unintended use which, if not avoided, may result in minor or moderate injury.	
	NOTICE	Indicates a potentially hazardous situation or an unintended use which, if not avoided, may result in appreciable material, financial	
		and environmental damage.	

1.2	Definition of Use	
Intended use	 Measuring horizontal and vertical angles. Measuring distances. Recording measurements. Visualizing the aiming direction and vertical axis. Data communication with external appliances. Computing by means of software. 	
Reasonably forseeable misuse	 Use of the product without instruction. Use outside of the intended use and limits. Disabling safety systems. Removal of hazard notices. Opening the product using tools, for example screwdriver, unless this is permitted for certain functions. Modification or conversion of the product. Use after misappropriation. Use of products with recognisable damages or defects. Use with accessories from other manufacturers without the prior explicit approval of Leica Geosystems. Deliberate dazzling of third parties. Controlling of machines, moving objects or similar monitoring application without additional control and safety installations. Aiming directly into the sun. Inadequate safeguards at the working site. 	
1.3	Limits of Use	
Environment	Suitable for use in an atmosphere appropriate for permanent human habita- tion: not suitable for use in aggressive or explosive environments.	
	 Working in hazardous areas, or close to electrical installations or similar situations. Life Risk. Precautions: Local safety authorities and safety experts must be contacted by the person responsible for the product before working in such conditions. 	
1.4	Responsibilities	
Manufacturer of the product	Leica Geosystems AG, CH-9435 Heerbrugg, hereinafter referred to as Leica Geosystems, is responsible for supplying the product, including the User Manual and original accessories, in a safe condition.	

Person responsible for the product

The person responsible for the product has the following duties:

- To understand the safety instructions on the product and the instructions in the User Manual.
- To ensure that it is used in accordance with the instructions.
- To be familiar with local regulations relating to safety and accident prevention.
- To inform Leica Geosystems immediately if the product and the application becomes unsafe.
- To ensure that the national laws, regulations and conditions for the operation of the product are respected.

1.5 Hazards of Use

NOTICE

Dropping, misusing, modifying, storing the product for long periods or transporting the product

Watch out for erroneous measurement results.

Precautions:

Periodically carry out test measurements and perform the field adjustments indicated in the User Manual, particularly after the product has been subjected to abnormal use as well as before and after important measurements.

ADANGER

Risk of electrocution

Because of the risk of electrocution, it is dangerous to use poles, levelling staffs and extensions in the vicinity of electrical installations such as power cables or electrical railways.

Precautions:

Keep at a safe distance from electrical installations. If it is essential to work in this environment, first contact the safety authorities responsible for the electrical installations and follow their instructions.



Lightning strike

If the product is used with accessories, for example masts, staffs, poles, you may increase the risk of being struck by lightning.

Precautions:

• Do not use the product in a thunderstorm.

\land WARNING

Distraction/loss of attention

During dynamic applications, for example stakeout procedures, there is a danger of accidents occurring if the user does not pay attention to the environmental conditions around, for example obstacles, excavations or traffic.

Precautions:

The person responsible for the product must make all users fully aware of the existing dangers.

WARNING

Inadequate securing of the working site.

This can lead to dangerous situations, for example in traffic, on building sites and at industrial installations.

Precautions:

- Always ensure that the working site is adequately secured.
- Adhere to the regulations governing safety, accident prevention and road traffic.

Pointing product toward the sun

Be careful when pointing the product toward the sun, because the telescope functions as a magnifying glass and can injure your eyes and/or cause damage inside the product.

Precautions:

Do not point the product directly at the sun.

Not properly secured accessories.

If the accessories used with the product are not properly secured and the product is subjected to mechanical shock, for example blows or falling, the product may be damaged or people can sustain injury.

Precautions:

- When setting up the product, make sure that the accessories are correctly adapted, fitted, secured, and locked in position.
- Avoid subjecting the product to mechanical stress.

Inappropriate mechanical influences to batteries

During the transport, shipping or disposal of batteries it is possible for inappropriate mechanical influences to constitute a fire hazard.

Precautions:

- Before shipping the product or disposing it, discharge the batteries by the product until they are flat.
- When transporting or shipping batteries, the person in charge of the product must ensure that the applicable national and international rules and regulations are observed.
- Before transportation or shipping, contact your local passenger or freight transport company.

Exposure of batteries to high mechanical stress, high ambient temperatures or immersion into fluids

This can cause leakage, fire or explosion of the batteries.

Precautions:

 Protect the batteries from mechanical influences and high ambient temperatures. Do not drop or immerse batteries into fluids.

WARNING

Short circuit of battery terminals

If battery terminals are short circuited e.g. by coming in contact with jewellery, keys, metallised paper or other metals, the battery can overheat and cause injury or fire, for example by storing or transporting in pockets.

Precautions:

 Make sure that the battery terminals do not come into contact with metallic objects.

Improper disposal

If the product is improperly disposed of, the following can happen:

- If polymer parts are burnt, poisonous gases are produced which may impair health.
- If batteries are damaged or are heated strongly, they can explode and cause poisoning, burning, corrosion or environmental contamination.
- By disposing of the product irresponsibly you may enable unauthorised persons to use it in contravention of the regulations, exposing themselves and third parties to the risk of severe injury and rendering the environment liable to contamination.
- Improper disposal of silicone oil may cause environmental contamination.
- The product does include parts of Beryllium inside. Any modification of some internal parts can release Beryllium dust or fragments, creating a health hazard.

Precautions:



The product must not be disposed with household waste. Dispose of the product appropriately in accordance with the national regulations in force in your country. Always prevent access to the product by unauthorised personnel.

Product-specific treatment and waste management information can be received from your Leica Geosystems distributor.

Improperly repaired equipment

Risk of injuries to users and equipment destruction due to lack of repair knowledge.

Precautions:

 Only authorised Leica Geosystems Service Centres are entitled to repair these products.

1.6	Laser Classification
1.6.1	General
General	The following chapters provide instructions and training information about laser safety according to international standard IEC 60825-1 (2014-05) and technical report IEC TR 60825-14 (2004-02). The information enables the person responsible for the product and the person who actually uses the equipment, to anticipate and avoid operational hazards.

According to IEC TR 60825-14 (2004-02), products classified as laser F class 1, class 2 and class 3R do not require: laser safety officer involvement, protective clothes and eyewear, special warning signs in the laser working area if used and operated as defined in this User Manual due to the low eye hazard level. F National laws and local regulations could impose more stringent instructions for the safe use of lasers than IEC 60825-1 (2014-05) and IEC TR 60825-14 (2004-02). 1.6.2 Distancer, Measurements with Reflectors General The EDM module built into the product produces a visible laser beam which emerges from the telescope objective. The laser product described in this section is classified as laser class 1 in accordance with: IEC 60825-1 (2014-05): "Safety of laser products" These products are safe under reasonably foreseeable conditions of operation and are not harmful to the eyes provided that the products are used and maintained in accordance with this User Manual.

Description	Value
Wavelength	658 nm
Pulse duration	800 ps
Pulse repetition frequency	100 MHz
Maximum average radiant power	0.34 mW
Beam divergance	1.5 mrad x 3 mrad

Labelling



1.6.3 Electronic Guide Light EGL

General

The Electronic Guide Light built into the product produces a visible LED beam which emerges from the front side of the telescope.

The product described in this section, is excluded from the scope of IEC 60825-1 (2014-05): "Safety of laser products". The product described in this section, is classified as exempt group in accordance with IEC 62471 (2006-07) and does not pose any hazard provided that the product is used and maintained in accordance with



1.6.4	Laser Plummet	
General	The laser plummet built into the pro which emerges from the bottom of	oduct produces a visible red laser beam the product.
	The laser product described in this s accordance with: • IEC 60825-1 (2014-05): "Safety	section is classified as laser class 2 in y of laser products"
	These products are safe for moment deliberate staring into the beam. Th and after-images, particularly under	tary exposures but can be hazardous for le beam may cause dazzle, flash-blindness low ambient light conditions.
	Description	Value

Description	Value
Wavelength	640 nm
Maximum average radiant power	0.95 mW
Pulse duration	0.1 ms - cw
Pulse repetition frequency (PRF)	1 kHz
Beam divergance	< 1.5 mrad

F

Class 2 laser product

From a safety perspective, class 2 laser products are not inherently safe for the eyes.

Precautions:

- Avoid staring into the beam or viewing it through optical instruments.
- Avoid pointing the beam at other people or at animals.



Laser beam
 Exit for laser beam

AutoHeight Laser Plummet

General

1.6.5

The laser plummet built into the product produces a visible red laser beam which emerges from the bottom of the product.

The laser product described in this section is classified as laser class 2 in accordance with:

IEC 60825-1 (2014-05): "Safety of laser products"

These products are safe for momentary exposures but can be hazardous for deliberate staring into the beam. The beam may cause dazzle, flash-blindness and after-images, particularly under low ambient light conditions.

Description	Value
Wavelength	640 nm
Maximum average radiant power	0.95 mW
Pulse duration	< 1 ns
Pulse repetition frequency (PRF)	320 MHz
Beam divergance	<1.5 mrad

Class 2 laser product

From a safety perspective, class 2 laser products are not inherently safe for the eyes.

Precautions:

- Avoid staring into the beam or viewing it through optical instruments.
- Avoid pointing the beam at other people or at animals.

Class 2 laser product

Use of controls or adjustments or performance of procedures other than those specified herein may result in hazardous radiation exposure.

Precautions:

 Use controls or adjustments or performance of procedures only as specified.



Electromagnetic Compatibility EMC

Description

1.7

The term Electromagnetic Compatibility is taken to mean the capability of the product to function smoothly in an environment where electromagnetic radiation and electrostatic discharges are present, and without causing electromagnetic disturbances to other equipment.

Electromagnetic radiation

Electromagnetic radiation can cause disturbances in other equipment. **Precautions:**

Although the product meets the strict regulations and standards which are in force in this respect, Leica Geosystems cannot completely exclude the possibility that other equipment may be disturbed.

Use of the product with accessories from other manufacturers. For example field computers, personal computers or other electronic equipment, non-standard cables or external batteries

This may cause disturbances in other equipment.

Precautions:

- Use only the equipment and accessories recommended by Leica Geosystems.
- When combined with the product, they meet the strict requirements stipulated by the guidelines and standards.
- When using computers, two-way radios or other electronic equipment, pay attention to the information about electromagnetic compatibility provided by the manufacturer.

Intense electromagnetic radiation. For example, near radio transmitters, transponders, two-way radios or diesel generators

Although the product meets the strict regulations and standards which are in force in this respect, Leica Geosystems cannot completely exclude the possibility that function of the product may be disturbed in such an electromagnetic environment.

Precautions:

Check the plausibility of results obtained under these conditions.

Electromagnetic radiation due to improper connection of cables

If the product is operated with connecting cables attached at only one of their two ends, for example external supply cables, interface cables, the permitted level of electromagnetic radiation may be exceeded and the correct functioning of other products may be impaired.

Precautions:

While the product is in use, connecting cables, for example product to external battery, product to computer, must be connected at both ends.

Radios or digital cellular phones

1.8

Use of product with radio or digital cellular phone devices:

Electromagnetic fields can cause disturbances in other equipment, in installations, in medical devices, for example pacemakers or hearing aids and in aircraft. It can also affect humans and animals.

Precautions:

- Although the product meets the strict regulations and standards which are in force in this respect, Leica Geosystems cannot completely exclude the possibility that other equipment can be disturbed or that humans or animals can be affected.
 - Do not operate the product with radio or digital cellular phone devices in the vicinity of filling stations or chemical installations, or in other areas where an explosion hazard exists.
 - Do not operate the product with radio or digital cellular phone devices near to medical equipment.
 - Do not operate the product with radio or digital cellular phone devices in aircraft.

FCC Statement, Applicable in U.S.

The greyed paragraph below is only applicable for products without radio.

This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to part 15 of the FCC rules.

These limits are designed to provide reasonable protection against harmful interference in a residential installation.

This equipment generates, uses and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation.

If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures:

- Reorient or relocate the receiving antenna.
- Increase the separation between the equipment and the receiver.
- Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.
- Consult the dealer or an experienced radio/TV technician for help.

Changes or modifications not expressly approved by Leica Geosystems for compliance could void the user's authority to operate the equipment.







1.9 ICES-

ICES-003 Statement, Applicable in Canada

AWARNING

This Class (B) digital apparatus complies with Canadian ICES-003. Cet appareil numérique de la classe (B) est conforme à la norme NMB-003 du Canada.

Canada Compliance Statement

This device complies with Industry Canada's license-exempt RSSs. Operation is subject to the following two conditions:

- 1. This device may not cause interference; and
- 2. This device must accept any interference, including interference that may cause undesired operation of the device.

Canada Déclaration de Conformité

Le présent appareil est conforme aux CNR d'Industrie Canada applicables aux appareils radio exempts de licence. L'exploitation est autorisée aux deux conditions suivantes:

- 1. l'appareil ne doit pas produire de brouillage;
- 2. l'appareil doit accepter tout brouillage radioélectrique subi, même si le brouillage est susceptible d'en compromettre le fonctionnement.

Description of the System

2 2.1

System Components

Main components

	c→ C→ C→ C→ C→ C→ C→ C→ C→ C→ C	TS03/TS07 instrument with FlexField firmware Computer with Leica Infinity software Data transfer	
Component	Description		
TS03/TS07	An instrument for measuring Ideally suited for tasks from cations. Equipped with a Flex plete these tasks.	g, calculating and capturing data. simple surveys to complex appli- xField firmware package to com-	
	The various lines have a rang port different features. All lin Infinity to view, exchange ar	ge of accuracy classes and sup- nes can be connected with Leica nd manage data.	
FlexField firmware	The firmware package install of a standard base operating features.	led on the instrument. Consists g system with optional additional	
Leica Infinity software	An office software consisting of a suite of standard and extended programs for the viewing, exchanging, managing and post processing of data.		
Data transfer	Data can be transferred betw puter via USB cable, USB-stic cable.	ween a TS03/TS07 and a com- ck, SD card and data transfer	

Container Contents

Container contents part 1 of 2



- a GEB331 or GEB361 battery
- b GZT4 target plate
- c GRZ101 mini prism, GAD103 and GAD105 adapter
- d GLS115 mini prism pole
- e Leica industrial grade USB memory stick
- f Stylus**
- g GFZ3 and GOK6 diagonal eyepiece*
- h Tip for mini prism
- i Adjustment tool
- j Allen key
- k GPR111 and GPR121 round prism
- I Manuals
- m GRZ101 360° mini prism
- n GMP101 and GMP111 mini prism*
- o Counterweight for diagonal eyepiece*
- * Optional
- ** For TS07

2.2

Container contents part 2 of 2



0016355_001

- a SD card
- b CPR105 flat prism*
- c GHT196 holder for height metre*
- d GHM007 height metre*
- e GLI115 clip-on bubble*
- f GKL311 charger
- g Protective cover / Lens hood / Cleaning cloth
- h Data cable
- * Optional

2.3

Instrument Components

TS03 Instrument components part 1 of 2



- a Compartment for SD card, USB memory stick and USB cable ports
- b Optical sight
- c Detachable carrying handle with mounting screw
- d Objective with integrated Electronic Distance Measurement (EDM). Exit for EDM laser beam
- e Vertical drive
- f Loudspeaker
- g Trigger key
- h Serial interface RS232, located behind keyboard on rotation part
- i Horizontal drive

TS03 Instrument components part 2 of 2



- j Focusing telescope image
- k Eyepiece; focusing graticule
- Battery cover
- Foot screw m
- Keyboard with display n

TS07 Instrument components part 1 of 2



- Compartment for SD card, USB memory stick а and USB cable ports
- Optical sight Ь
- Detachable carrying handle with mounting С screw
- Electronic Guide Light (EGL)* d
- Objective with integrated Electronic Distance е Measurement (EDM). Exit for EDM laser beam
- f Vertical drive
- Loudspeaker g
- h Trigger key
- Serial interface RS232, located behind keyi board on rotation part
- Horizontal drive j
- Keyboard with display k
- * Optional

TS07 Instrument components part 2 of 2



- LTE antenna* L
- Focusing telescope image m
- n Evepiece; focusing graticule
- Battery cover 0
- Foot screw Ρ
- Stylus q
- Keyboard with display r
- * Optional

3	User Interface	
3.1	Keyboard	
Keyboard	TS03 with Greyscale display	TS07 with Color&Touch display
	The second secon	d e f d c d c d c d c d c d c d c d c d c d

- Function keys **F1** to **F4** Navigation keys **ENTER** key Alphanumeric keypad **ON/OFF** key Fixed keys а
- Ь
- С
- d
- е
- f

Keys

Кеу	Description
	If the instrument is already off: Turns on the instrument when held for 2 s. If the instrument is already on: Turns to Power Options menu when held for 2 s.
P	Page key Displays the next screen when several screens are available.
\checkmark	Favourites key Quick-access to measurement supporting functions.
	User key 1 Programmable with a function from the Favourites menu.
2 2	User key 2 Programmable with a function from the Favourites menu.
	Navigation key Controls the focus bar within the screen and the entry bar within a field.
ОК	ENTER key Confirms an entry and continues to the next field.
	Pressing ESC short: Returns to next higher level. Quits a screen or edit mode without saving changes.
	Pressing ESC long: Returns to the Main Menu . Quits a screen or edit mode without saving changes.
	Home key Returns to the main menu.

	Кеу	Description
	F1	Function keys that are assigned the variable functions dis- played at the bottom of the screen.
		Alphanumeric keypad for entry of text and numerical values.
Sidecover keys	Кеу	Description
		Trigger key. Quick key programmable with functions Meas , Dist or Store if desired.
		The trigger key can be programmed in the Settings screen. Refer to "5.1 Work Settings".
3.2	Screen	
Screen	The TS03 is available with Greyscale (G) screen.	
	The TS07 is	available with Color&Touch (C&T) screen.
	The look an	d feel is the same for both types.
	کی All fir	screens shown in this manual are examples. It is possible that local mware versions are different to the basic version.
	a b	
	Survey	
	PtID	
	hr Code	1.400 m e a Quit
	Hz V	100.000 g c Status icons
		f d Tabs
	Meas	σ f Fields
	016207_001	g Softkeys

Tap on an icon, field or tab to run a function.

Status Icons

Description

The icons provide status information related to basic instrument functions. Depending on the display type, different icons are displayed.

lcons

3.3

lcon	Description
	Non-prism EDM mode for measuring to all targets. For TS07: Tapping the icon opens the EDM & Target bubble.
Ō	Leica standard prism is selected. For TS07: Tapping the icon opens the EDM & Target bubble.
\bigcirc	Leica mini prism is selected. For TS07: Tapping the icon opens the EDM & Target bubble.
	Leica mini 0 prism is selected. For TS07: Tapping the icon opens the EDM & Target bubble.

lcon	Description			
	Leica sliding basic mini prism is se For TS07: Tapping the icon opens	elected. the EDM & Ta	arget bubl	ole.
Ĩ	Leica 360° prism is selected. For TS07: Tapping the icon opens	the EDM & Ta	arget bubl	ole.
	Leica 360° mini prism is selected. For TS07: Tapping the icon opens	the EDM & Ta	arget bubl	ole.
	Leica 360° MPR122 prism is selec For TS07: Tapping the icon opens	ted. the EDM & T a	arget bubl	ole.
\oplus	Leica reflector tape is selected. For TS07: Tapping the icon opens	the EDM & Ta	arget bubl	ole.
	User defined prism is selected. For TS07: Tapping the icon opens	the EDM & Ta	arget bubl	ole.
- Ali	A running vertical line left beside urement activity.	the prism indic	ates EDM	meas-
•	Indicates an active laser pointer. For TS07: Tapping the icon opens	the EDM & Ta	arget bubl	ole.
X	Indicates that Meas. Mode : Average is active.			
>4	Indicates that Meas. Mode: Pris	Indicates that Meas. Mode : Prism (>4.0km) is active.		
Ğ	Indicates that Meas. Mode: Prec	i se&Fast is a	ctive.	
↓	Indicates that Meas. Mode: Trac	king is active.		
Ι	Indicates telescope position in fa- For TS07: Tapping the icon opens	ce I. the Instrume	nt bubble.	
\mathbf{II}	Indicates telescope position in fa- For TS07: Tapping the icon opens	ce II. the Instrume	nt bubble.	
Ι	Compensator is on. For TS07: Tapping the icon opens the Instrument bubble.			
\mathbf{II}				
⊕ ∕	Compensator is off. For TS07: Tapping the icon opens the Level & Plummet screen.			
\oplus	Compensator is out of range. For TS07: Tapping the icon opens the Level & Plummet screen.			
*	Bluetooth configured and paired			
		Bluetooth	RS232	LTE
	Selected	\checkmark	-	-
	Active	\checkmark	-	-

lcon	Description			
	For TS07: Tapping the icon opens on Interface settings to open th	the Connectiv ne Interface S	ity bubble ettings so	e. Click creen.
*	Bluetooth configured but not pair	ed		
		Bluetooth	RS232	LTE
	Selected	\checkmark	-	-
	Active	-	-	-
	Modem configured and connected	l with the Inter	net	
		Bluetooth	RS232	LTE
	Selected	-	-	\checkmark
	Active	-	-	\checkmark
	Modem configured but not conne	cted with the II	nternet	
		Bluetooth	RS232	LTE
	Selected	-	-	\checkmark
	Active	-	-	-
	Bluetooth configured but not pair Modem configured but not conne	ed. cted with the II	nternet	
		Bluetooth	RS232	LTE
	Selected	\checkmark	-	\checkmark
	Active	-	-	-
	Bluetooth configured and paired. Modem configured but not conne	cted with the II	nternet	
		Bluetooth	RS232	LTE
	Selected	\checkmark	-	\checkmark
	Active	\checkmark	-	-
:*	Bluetooth configured but not pair Modem configured and connected	ed. I with the Inter	net	
		Bluetooth	RS232	LTE
	Selected	\checkmark	-	\checkmark
	Active	-	-	\checkmark
.*	Bluetooth configured and paired. Modem configured and connected	l with the Inter	net	
		Bluetooth	RS232	LTE
	Selected	\checkmark	-	\checkmark
	Active	\checkmark	-	\checkmark
¢	RS232 configured and connected			
		Bluetooth	RS232	LTE
	Selected	-	\checkmark	-
	Active	-	\checkmark	-

	lcon	Description				
	• İ	RS232 configured and cor Modem configured and co	nnected nnected with the Inte	ernet		
			Bluetooth	RS232	LTE	
		Selected	-	\checkmark	\checkmark	
		Active	-	\checkmark	\checkmark	
		RS232 configured and cor Modem configured but no	nected t connected with the	Internet		
			Bluetooth	RS232	LTE	
		Selected	-	\checkmark	\checkmark	
		Active	-	\checkmark	-	
The battery symbol indicates the leve capacity. For TS07: Tapping the icon status of the battery and the interna			tes the level of the re g the icon opens a b the internal memory.	emaining ba ubble show	attery ving the	
		Battery level is 100% full.				
	-	Battery level is critical.				
3.4	Icon P	op-up Bubbles				
Description	Status ir instrume is indica	nformation helps using the in ent functions. All fields are di ted by	strument by showing splay only fields. Una	the state vailable inf	of many formation	
	Frequen is applie	tly used functionality can be d immediately. The workflow	accessed and change is not interrupted.	ed quickly. ⁻	The change	
Access	Tap a sta	atus icon in the icon area. An	icon pop-up bubble	opens.		
	An icon • Stat • Fund	pop-up bubble shows: us information ctionality related to the icon	which was tapped			
	Tap a bu	Ibble icon to use the functior	nality.			
	To close pop-up	an icon pop-up bubble, touc bubble.	h the screen anywhe	re outside	of the icon	



Description of the icon pop-up bubbles

Refer to the individual chapters for more information.

Status Information	Functionality	
Current target with defined constantsType of distance measurement	 Switch between non-priam and prism mode Turn the red laser of the reflec- torless EDM on/off Select targets 	
nstrument Status Information	Functionality	

•	Current setup ID, instrument	•	Electronic level bubble and com-
	height and level status		pensator settings

Connectivity

Status Information		Functionality	
•	Current interface setting	•	Start Interface Settings

Battery and date

Status Information	Functionality
 Date Remaining power capacity for the battery Active internal memory 	 View the system information Create a sketch on a virtual piece of paper

3.5 Softkeys

Description

Softkeys are selected using the relevant **F1** to **F4** function key. This chapter describes the functionality of the common softkeys used by the system. The more specialised softkeys are described with the apps where they appear.

Common softkey	Кеу	Description			
Tunctions	Cont	If entry screen: Confirms measured or entered values and continues the process. If message screen: Confirms message and continues with selected action or returns to the previous screen to reselect an option.			
	Back	To return to the last active screen.			
	Default	To reset all editable fields to their default values.			
	Dist	To start distance and angle measurements without saving the measured values.			
	EDM	To view and change EDM settings. Refer to "5.5 EDM Set- tings".			
	New	To open the manual coordinate entry screen.			
	Find	To search for an entered point.			
	List	To display the list of available points.			
	Meas	To start distance and angle measurements and save the measured values.			
	Exit	To exit the screen or app.			
	Store	To save the displayed values.			
	View	To display the coordinate and job details of the selected point.			
	-> ABC	To change the keypad operation to alphanumerical.			
	-> 345	To change the keypad operation to numerical.			
	ţ	To display the next softkey level.			
	Ť	To return to the first softkey level.			
3.6	Operating	Principles			

	<u> </u>	
Turn instrument on/off	Button	Description
	۲	To turn the instrument on or off, use the On/Off key on the keyboard of the instrument. Press the key for 2 seconds to display the Power Options menu.
 Selection of language	After switching on the instrument the user is able to choose their preferred language. The language choice screen is only shown if multiple languages ar loaded onto the instrument and Lang.Choice : On is set in the instrument so tings. Refer to "5.2 Regional Settings".	
Alphanumeric keypad	The alphanun fields.	nerical keypad is used to enter characters directly into editable

- **Numeric fields**: Can only contain numerical values. By pressing a key of the keypad the number will be displayed.
- Alphanumeric fields: Can contain numbers and letters. By pressing a key of the keypad the first character written above that key will be displayed. By pressing several times you can toggle through the characters. For example: 1->S->T->U->1->S....

When the alphanumeric mode is active, numbers are not selectable. For example: T=>U=>V=>T...

Edit fields	Button	Description
	(A)	ESC Deletes any change and restores the previous value.
		Moves the cursor to the left
		Moves the cursor to the right.
		Inserts a character at the cursor position.
	T	Deletes the character at the cursor position.

P

In edit mode the position of the decimal place cannot be changed. The decimal place is skipped.

Special characters

Character	Description
*	Used as wildcards in search fields for point numbers or codes. Refer to "3.7 Pointsearch".
+/-	In the alphanumeric character set "+" and "-" are treated as normal alphanumeric characters with no mathematical func- tion.

🗂 Programs 🖉 I 🕴 📼) 15:31		
Survey	Survey+		Ref.El.		Road	
1		2		3	Ę	
Stn.Setup		Sur	vey	s	etout	:

In this example selecting 2 on an alphanumeric keyboard would start the Survey app.

3.7	Pointsearch			
Description	Pointsearch is a function to find measured points or fixpoints in the memory storage.			
	It is possible to limit the point search to a particular job or to search the whole storage. The search procedure always finds fixpoints before measured points that fulfil the same search criteria. If several points meet the search criteria, then the results are ordered according to the entry date. The instrument finds the most recent fixpoint first.			

Direct search

By entering an actual point number, for example 402, and pressing **Find**, all points within the selected job and with the corresponding point number are found.

Pointse		٩	Ι	¢) 15:42	
General						
Job			D	efa	ult	<>
PtID				2	00	

Select job or enter point coordinates manually!

	List	Find ENH=0 New				
	Key	Description				
	Find	To search for matching points within the selected job.				
	ENH=0	To set all ENH coordinates for the point ID to 0.				
Wildcard search	The wildcard search is indicated by a "*". The asterisk is a place holde following sequence of characters. Wildcards should be used if the poid ber is not fully known, or to search for a batch of points.					
Examples of point	* All	All points are found.				
searches	A All	points with exactly the point number "A" are found.				
	A* All A2	All points starting with "A" are found, for example, A9, A15, ABCD, A2A.				
	*1 All	All points containing only one "1" are found, for example, 1, A1, AB.				
	A*1 All points starting with "A" and containing only one "1" are found, for example, A1, AB1, A51.					
3.8	Graphic S	Symbols				
Graphic symbols	In some app • provide • allows • measur	ps, a graphical display is shown. The graphical display as a guide to find the point to be staked out. for a better overall understanding of how the data being used and red relates to each other.				
	Element	Description				
	₿	Point to be staked / known point				
		Instrument				
	Ī	Current position of prism (measurement with Dist)				
	1 J	Forward/backwards distance to point				
	← ⇒	Side distance to point				
		Height distance to point				

Element	Description
\checkmark	The stakeout point is the same as the measured point. The difference between stakeout point and measured point is ≤ 0.03 m.
	Circle around the stake out point, supporting the detail view, radius = 0.5 m
A	Fixpoint
	Fixpoint active
•	Station
	Station active
×	Centre point of an arc or circle
•	Measured point
	Measured point active
	Black squares around the point symbol indicate the plane points.
6	Connection between last measured/selected point and first point of an area
	Breaklines of an area

4	Operation		
4.1	Instrument Setup		
Description	This topic describes an instrument setup over a marked ground point using the laser plummet. It is always possible to set up the instrument without the need for a marked ground point.		
	 Important features It is always recommended to shield the instrument from direct sunlight and avoid uneven temperatures around the instrument. The laser plummet described in this topic is built into the vertical axis of the instrument. It projects a red spot onto the ground, making it appreciably easier to centre the instrument. The laser plummet cannot be used with a tribrach equipped with an optical plummet. 		
Tripod	When setting up the tripod pay attention to ensuring a horizontal position of the tripod plate. Slight corrections of inclination can be made with the foot screws of the tribrach. Larger corrections must be done with the tripod legs.		



TSOX_0120

Loosen the clamping screws on the tripod legs, pull out to the required length and tighten the clamps.

- a In order to guarantee a firm foothold sufficiently press the tripod legs into the ground.
- b When pressing the legs into the ground note that the force must be applied along the legs.

Careful handling of tripod.

- Check all screws and bolts for correct fit.
- During transport, always use the cover supplied.
- Use the tripod only for surveying tasks.

Setup step-by-step	016137.001	3 2 $4/6$ 7 7 $4/6$ 5 b		
	1.	Extend the tripod legs to allow for a comfortable working posture. Position the tripod over the marked ground point, centring it as best as possible.		
	2.	Fasten the tribrach and instrument onto the tripod.		
	3.	 Turn on the instrument, and, if tilt correction is set to On, the laser plummet will be activated automatically, and the Level & Plummet screen appears. Otherwise, press the key from within any app and select Level & Plummet. For TS07, use the optional AutoHeight laser plummet for vertically setting up the instrument over a ground point and for measuring the instrument height when setting up the station. 		
	4.	Move the tripod legs and use the tribrach footscrews (a) to centre the plummet over the ground point (c).		
	5.	Adjust the tripod legs to level the circular level (c).		
	6.	By using the electronic level, turn the tribrach footscrews to precisely level the instrument. Refer to "Level up with the electronic level step-by-step".		
	7.	Centre the instrument precisely over the ground point by shifting the tribrach on the tripod plate .		
	8.	Repeat steps 6. and 7. until the required accuracy is achieved.		
Level up with the electronic level step-	The electron	ctronic level can be used to precisely level up the instrument using the ews of the tribrach.		
by-step	1.	Turn the instrument until it is parallel to two footscrews.		
	2.	Centre the circular level approximately by turning the footscrews of the tribrach.		
- 3. Turn on the instrument, and, if tilt correction is set to On, the laser plummet will be activated automatically, and the Level & Plummet screen appears. Otherwise, press the Favourites key from within any app and select Level & Plummet.
 - P For TS07, use the optional AutoHeight laser plummet for vertically setting up the instrument over a ground point and for measuring the instrument height when setting up the station.
 - F The bubble of the electronic level and the arrows for the rotating direction of the footscrews only appear if the instrument tilt is inside a certain levelling range.
- 4. Centre the electronic level of the first axis by turning the two footscrews. Arrows show the direction of rotation required. The first axis is levelled, when the bubble is exactly between the squared brackets [] of the single axis bubble tube.



F When levelled correctly, checkmarks are displayed. For the Color and Color&Touch screens: If the instrument is not levelled to one axis, then the icons for the single axis bubble tube and the circular bubble are framed red, else they are black.



Change the intensity of the laser plummet

External influences and the surface conditions may require the adjustment of the intensity of the laser plummet.

In the Level & Plummet screen, adjust the intensity of the laser plummet using the navigation key.

The laser can be adjusted in 20% steps as required.



Position over pipes or holes



Under some circumstances the laser dot is not visible, for example over pipes. In this case, using a transparent plate enables the laser dot to be seen and then easily aligned to the centre of the pipe.

4.2	Batteries				
4.2.1	Operating Principles				
First-time use/ charging batteries	 The battery must be charged before using it for the first time because it is delivered with an energy content as low as possible. The permissible temperature range for charging is from 0 °C to +40 °C/+32 °F to +104 °F. For optimal charging, we recommend charging the batteries at a low ambient temperature of +10 °C to +20 °C/+50 °F to +68 °F if possible. It is normal for the battery to become warm during charging. Using the chargers recommended by Leica Geosystems, it is not possible to charge the battery once the temperature is too high. For new batteries or batteries that have been stored for a long time (> three months), it is effectual to make only one charge/discharge cycle. For Li-lon batteries, a single discharging and charging cycle is sufficient. We recommend carrying out the process when the battery capacity indicated on the charger or on a Leica Geosystems product deviates significantly from the actual battery capacity available. 				
Operation/ discharging	 The batteries can be operated from -20 °C to +55 °C/-4 °F to +131 °F. Low operating temperatures reduce the capacity that can be drawn; high operating temperatures reduce the service life of the battery. 				



 Face the instrument so that the vertical drive screw is on the left. The battery compartment is below the vertical drive. Turn the knob to the vertical position, opening the lid of the battery compartment.

2.	Pull out the battery housing.
3.	Pull the battery out of the battery housing.
4.	At the top of the battery is a notch which corresponds to the inner surface of the battery housing. This notch helps you to place the battery correctly. Place the battery into the battery housing, ensuring that the contacts are facing outward. Click the battery into position.
5.	Place the battery housing into the battery compartment. Push the battery housing in until it fits completely into the battery compartment.
6.	Turn the knob to lock the battery compartment. Ensure that the knob is returned to its original horizontal position.

4.3	Data Storage			
Description	An internal memory is included in all instruments. The FlexField firmware stores all data in jobs in a database in the internal memory.			
	Data can be transferred from the internal memory to a computer or other device via:			

4.2.2

step-by-step

Change the battery

Main Menu	Default 🕑 I 0 💼					
3	If desired, the instrument can be configured to start in a user-defined place after the Level/Plummet screen, instead of the Main Menu . Refer to "5.10 Startup Sequence".					
Description	The Main Menu is the starting place for accessing all functionality of the instrument.					
4.4	Main Menu					
12	SD cards can directly be used in an OMNI drive as supplied by Leica Geosys- tems. Other PC card drives can require an adaptor.					
Transfer data	Data can be transferred in various ways. Refer to "12 Data Management".					
3	Unplugging connecting cables or removing the SD card or USB stick during the measurement can cause loss of data. Only remove the SD card or USB stick or unplug connecting cables when the TS instrument is switched off.					
	 Refer to "12 Data Management" for further information on data management and data transfer. While other SD cards/USB sticks can be used, Leica Geosystems recommends to only use Leica SD cards/USB sticks and is not responsible for data loss or any other error that can occur while using a non-Leica SD card/USB stick. 					
	 a LEMO cable connected to the serial interface RS232 port an SD card an USB stick inserted into the USB host port, an USB cable connected to the USB device port, or a Bluetooth connection. WLAN an LTE antenna (TS07) 					



Description of the Main Menu functions

Function	Description
Start page	
R Setup	Setup app to determine the station coordinates and station orientation when setting up a station. Refer to "7.2 Station Setup".

Function	Description					
Q	Survey app to begin measuring. Refer to "7.3 Surveying".					
Survey						
Ę	Setout app to place marks in the field at predetermined points. Refer to "7.4 Setout".					
Setout						
	To select and start apps. Refer to "7 Apps".					
Apps						
عر	To change EDM configurations, communication parameters					
Settings	To access instrument-related tools such as check and adjust, personal startup settings, PIN code settings, licence keys, system information and firmware upload. Refer to "5 Settings".					
⊕	To create a new job.					
New Job						
Manage page Contains all fu field. Refer to	nctions for entering, editing, checking and deleting data in the "12 Data Management".					
Job	To select, view, create and delete jobs. Jobs are a summary of data of different types, for example, fixed points, measurements or codes. The job definition consists of the job name and user. The system generates time and date at the time of creation.					
A Fixpoints	To view, create, edit and delete fixpoints. Fixpoints can have full coordinates (E, N, H) or position only or height only. To select a code from the existing codelist. To view all screenshots linked to the fixpoint.					
www.Meas.Data	To view, edit and delete measurement data. Measurement data available in the internal memory can be searched for via a specific point search, or by viewing all points within a job. The PtID, hr, code and code details can be edited. If the details of a point have been edited, any new calculations will use the new point details. How-ever, any previously stored calculation results based on the original coordinates of the point will not be updated.					
	To export and import data. Refer to "12.2 Exporting Data".					
fer						
×	To delete individual jobs, fixpoints and measurements of a specific job or all jobs in the memory.					
Del.Data	Deleting the memory cannot be undone. After confirming the message all data is permanently deleted.					

Function	Description					
USB-Stick	To view, delete, rename and create folders and files stored on the USB memory stick. Refer to "12.4 Working with a USB Memory Stick"and "B Directory Structure".					
	To view, delete, rename and create folders and files stored on the SD card.					
SD Card						
	To view, delete, rename and create folders and files stored in the internal memory. The internal memory has same folder					
Int. Memory						
E	To view, create, edit and delete codes. To each code a description and a maximum of 8 attributes with up to 16 characters each can be assigned.					
	Io view and delete data format files.					
Formats						
	To view, delete, link, unlink, sketch or view information of screenshots taken and stored. Refer to "11.2 Sketching" for					
ScrShots	sketching.					

4.5Distance Measurements - Guidelines for Correct ResultsDescriptionAn EDM is incorporated into the instrument. In all versions, the distance can be

An EDM is incorporated into the instrument. In all versions, the distance can be determined by using a visible red laser beam which emerges coaxially from the telescope objective. There are two EDM modes:

- Prism measurements
- Non-Prism measurements



- When a distance measurement is triggered, the EDM measures to the object which is in the beam path at that moment. If a temporary obstruction, for example a passing vehicle, heavy rain, fog or snow is between the instrument and the point to be measured, the EDM may measure to the obstruction.
- Be sure that the laser beam is not reflected by anything close to the line of sight, for example highly reflective objects.
- Avoid interrupting the measuring beam while taking Non-Prism measurements or measurements using reflective foils.
- Do not measure with two instruments to the same target simultaneously.

Non-prism measurements

Prism measurements	 Accurate measurements to prisms should be made in Precise+ mode. Measurements to strongly reflecting targets such as traffic lights in Prism mode without a prism should be avoided. The measured distances may be wrong or inaccurate. When a distance measurement is triggered, the EDM measures to the object which is in the beam path at that moment. If for example people, cars, animals, or swaying branches cross the laser beam while a measurement is being taken, a fraction of the laser beam is reflected from these objects and may lead to incorrect distance values. Measurements to prisms are only critical if an object crosses the measuring beam at a distance of 0 to 30 m and the distance to be measured is more than 300 m. In practice, because the measuring time is very short, the user can always find a way of avoiding unwanted objects from interfering in the beam path. 					
	Due to laser safety regulations and measuring accuracy, using the Long Range Reflectorless EDM is only allowed to prisms that are more than 1000m (3300ft) away.					
Red laser to prism	• Prism (>4.0km) mode enables distance measurements of over 4.0 km to standard prisms using the visible red laser beam.					
Red laser to reflector tape	 The visible red laser beam can also be used to measure to reflective foils. To guarantee the accuracy the red laser beam must be perpendicular to the reflector tape and it must be well adjusted. Make sure the additive constant belongs to the selected target (reflector). 					

5	Settings				
5.1	Work Settings				
Access	1.	Select Settings from the Main Menu .			
	2.	On the General page, select Work .			

Work Settings

Description of fields

Field	Optio	n	Description				
Trigger Key 1	,		Quick key programmable with one of the functions:				
	Off		The trigger key is deactivated.				
	Meas Dist Store		Sets the trigger key with the same function as Meas .				
			Sets the trigger key with the same function as Dist .				
			Sets the trigger key with the same function as Store .				
USER Key 1 USER Key 2	Selectable list		Configures the M / A keys with a function from the Favourites menu. Refer to "8 Favourites".				
Tilt Correct	Off		Tilting compensation deactivated.				
	On		2 -axis compensation. Vertical angles refer to the plummet line and the horizontal direc- tions are corrected by the standing axis tilt. For corrections depending on the Hz Corr. setting, refer to the table "Tilt and horizon- tal corrections".				
	- A	If the i examp sator s pensat interru an erro	nstrument is used on an unstable base, for le a shaking platform or ship, the compen- should be deactivated. This avoids the com- tor drifting out of its measuring range and pting the measuring process by indicating or.				
Hz Corr.	On		Horizontal corrections are activated. For nor- mal operation the horizontal correction should remain active. Each measured hori- zontal angle will be corrected, depending on the vertical angle. For corrections depending on the Tilt Cor- rect setting, refer to the table "Tilt and hori- zontal corrections".				
	Off		Horizontal corrections are deactivated.				
Line1			Fixed to Point ID Shown on a page in Sur- vey .				
Line2 to Line14			The settings define the parameters shown on a page in Survey .				

Field Option Description						
	Target Height	Input field for prism height.				
	Code	Editable field for codes.				
	Hz angle	Display only field for the horizontal angle.				
	V angle	Display only field for vertical angle.				
	Hor. dist.	Display only field for horizontal distance.				
	Slope dist.	Display only field for measured slope dis- tance.				
	Height diff.	Display only field for the height difference between station and reflector.				
	Easting	Display only field for Easting coordinate of measured point.				
	Northing	Display only field for Northing coordinate of measured point.				
	Height	Display only field for the height coordinate of the measured point.				
	Line space	Insert full line space.				
Show in Map	Measure- ments	To display only measured points.				
	Fixpoints	To display only fixpoints.				
	Meas & Fixpts	To display measured points and fixpoints.				
Show PtID	Yes	The ID of a point is displayed in the map.				
	No	Display of point IDs in the map is deactiva- ted.				
Show PtCode	Yes	The code of a point is displayed in the map.				
	No	Display of point codes in the map is deacti- vated.				
Only 50 Pts	Yes	Only the first 50 point labels are displayed in the map.				
	No	All point labels are displayed in the map, regardless of the number of points in the job.				
Centre to		The selection changes the behaviour of the icon on the Mapview toolbar and the naming of the corresponding softkey.				
	Station	To centre the map on the instrument.				
	Target	To centre the map on the target.				

Tilt and horizontal corrections

Setting		Correction				
Tilt cor- rection	Horizon- tal cor- rection	Incline longitudi- nal	Incline transver- sal	Horizon- tal colli- mation	Tilting axis	
Off	On	No	No	Yes	Yes	
On	On	Yes	Yes	Yes	Yes	
Off	Off	No	No	No	No	
On	Off	Yes	Yes	No	No	

5.2 **Regional Settings**

Access

1.	Select Settings from the Main Menu .
2.	On the General page, select Regional . 😂
3.	Press the 🗊 button to scroll through the screens of available set- tings.

Regional Settings

ings	⊵	I	0 🛄 16:30
s Ti	ime		
		Rig	ht <>
	7	Zeni	th < >
		Нο	ld < >
	E	nglis	sh < >
		0	ff < >
	ings s Ti	ings 🕑 s Time Z	ings 🕑 I s Time Rig Zeni Ho Englis O

Default	Cont
Delault	

Кеу	Description
Delete	To delete an inactive language. Available when the language is highlighted.

Description of fields

Field	Option	Description
Hz Incre- ment	Right	Set horizontal angle to clockwise direction measurement.
	Left	Set horizontal angle to counter-clockwise direction measurement. Counter-clockwise directions are displayed but are saved as clockwise directions.
V-Setting		Sets the vertical angle.



Field	Option	Description		
Language	Selectable list	Sets the chosen language. Several languages can be uploaded onto the instrument. The current loaded language(s) are shown. A selected language can be deleted by press- ing Delete . This function is available if more than one language is installed, and the selec- ted language is not the chosen operating language.		
Lang.Choice		If multiple languages are loaded, a screen to choose the language can be shown directly after switching on the instrument.		
	On	The language screen is shown as the startup screen.		
	Off	The language screen is not shown as the startup screen.		
Angle Unit		Sets the units shown for all angular fields. The setting of the angle units can be changed at any time. The current displayed values are converted according to the selec- ted unit.		
	0111	Degree sexagesimal. Possible angle values: 0° to 359°59'59''		
	dec. deg	Degree decimal. Possible angle values: 0° to 359.999°		
	gon	Gon. Possible angle values: 0 to 399.999 gon		
	mil (6000)	Mil. Possible angle values: 0 to 5999.99 mil.		
	mil (6400)	Mil. Possible angle values: 0 to 6399.99 mil.		
Min. Read- ing		Sets the number of decimal places shown for all angular fields. This is for data display and does not apply to data export or storage.		
	0111	(0° 00' 0.1"/0° 00' 01"/0° 00' 05"/ 0° 00' 10")		
	dec. deg	(0.0001 / 0.0005 / 0.001)		
	gon	(0.0001 / 0.0005 / 0.001)		
	mil (6000)	(0.01 / 0.05 / 0.1)		
	and mil (6400)			
Dist. Unit	(,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	Sets the units shown for all distance and coordinate related fields.		
	metre	Metres [m].		
	US-ft	US feet [ft].		
	INT-ft	International feet [fi].		
	ft-in/16	US feet-inch-1/16 inch [ft].		
Dist.Deci- mal		Sets the number of decimal places shown for all distance fields. This is for data display and does not apply to data export or storage.		
	3	Displays distance with three decimals.		

Field	Option	Description	
	4	Displays distance with four decimals.	
Temp. Unit		Sets the units shown for all temperature fields.	
	°C	Degree Celsius.	
	°F	Degree Fahrenheit.	
Press.Unit		Sets the units shown for all pressure fields.	
	hPa	Hecto Pascal.	
	mbar	Millibar.	
	mmHg	Millimeter mercury.	
	inHg	Inch mercury.	
Grade Unit		Sets how the slope gradient is calculated.	
	h:v	Horizontal : Vertical, for example 5 : 1.	
	v:h	Vertical : Horizontal, for example 1 : 5.	
	%	(v/h x 100), for example 20 %.	
Time (24h)		The current time.	
Date		Shows an example of the selected date for- mat.	
Format	dd.mm.yyyy , mm.dd.yyyy or yyyy.mm.dd	How the date is shown in all date-related fields.	

5.3	Settings	
Access	1.	Select Settings from the Main Menu .
	2.	On the General page, select Data .
	3.	Press the 🔲 button to scroll through the screens of available set- tings.

-				
Data Settings	Description of fields			
	Field	Option	Description	
	Double PtID		Sets if multiple points are able to be recor- ded with the same point ID in the same job.	
		Allowed	Allows multiple points with the same point ID.	
		Not Allowed	Does not allow multiple points with the same point ID.	
	Sort Type	Time	Lists are sorted by time of entry.	
		PtID	Lists are sorted by Point IDs.	
	Sort Order	Descending	Lists are ordered in descending order of sort type.	

Field	Option	Description
	Ascending	Lists are ordered in ascending order of sort type.
Code Record	Before Meas. or After Meas.	Sets if the codeblock is saved before or after the measurement. Refer to "9 Coding".
Code		Sets if the code will be used for one, or many, measurements.
	Reset after Rec	The set code is cleared from the measure- ment screen after Meas or Store is selected.
	Permanent	The set code remains in the measurement screen until manually deleted.
Data Output		Sets the location for data storage.
	Internal Memory	All data is recorded in the internal memory.
	Interface	Data which is normally stored in the onboard data base will be sent to the interface selec- ted in the Interface Settings screen This Data Output setting is only required if an external storage device is connected and measurements are started at the instrument with Dist/Store or Meas. This setting is not required if the instrument is totally controlled by a datalogger.
GSI-Format		Sets the GSI output format.
	GSI 8	8100+12345678
	GSI 16	8100+1234567890123456
GSI-Mask		Sets the GSI output mask.
	Mask 1	PtID, Hz, V, SD, ppm+mm, hr, hi
	Mask 2	PtID, Hz, V, SD, E, N, H, hr
	Mask 3	StationID, E, N, H, hi (Station) StationID, Ori, E, N, H, hi (Station Result) PtID, E, N, H (Control) PtID, Hz, V (Set Azimuth) PtID, Hz, V, SD, ppm+mm, hr, E, N, H (Meas- urement)

5.4	Screen & Audio Settings		
Access	1.	Select Settings from the Main Menu .	
	2.	On the General page, select Screen .	
	3.	Press the 🗐 button to scroll through the screens of available set- tings.	

Screen & Audio Set-	Description of f	ields	
tings	Field	Option	Description
	Display Illum.	Off to 100%	Sets the display illumination in 20% steps.
	Reticle Illum.	Off to 100%	Sets the reticle illumination in 10% steps.
	Touch Screen		Available for Color and Color&Touch screen only.
		On	The touch screen is activated.
		Off	The touch screen is deactivated.
			Press Calib. to calibrate the touch screen. Follow the instructions on the screen
	Screensaver	after 1 min, after 2 min, after 5 min, after 10 min	The screensaver is activated and starts after the selected time.
		Off	The screensaver is deactivated.
	Appl.Descrip.	All	To switch on the app description in the app pre-settings. Refer to "Starting an App".
		Standard	To switch off the app description in the app pre-settings. Refer to "Starting an App".
			The method descriptions for apps with different methods, for example COGO, cannot be switched off.
	Веер		The beep is an acoustic signal after each key stroke.
		Normal	Normal volume.
		Loud	Increased volume.
		Off	Beep is deactivated.
	Sector Beep	On	Sector beep sounds at right angles (0°, 90°, 180°, 270° or 0, 100, 200, 300 gon).
			$ \begin{array}{c} 1 \\ 0 \\ 0 \\ 0 \\ 0 \\ 0 \\ 0 \\ 0 \\ 0 \\ 0 \\ 0$
			 No beep Fast beep; from 95.0 to 99.5 gon and 105.0 to 100.5 gon. Permanent beep; from 99.5 to 99.995 gon and from 100.5 to 100.005 gon.
		Off	Sector Beep is deactivated.

	Field	Option	Description
	Setout Beep	On	The instrument beeps when the distance from the current position to the point to be staked is ≤ 0.5 m. The closer the prism is to the point to be staked the faster the beeps will be.
		Off	Beep is deactivated.
5.5	EDM Setting	[S	
Description	The settings on M easurement. [Prism (NP) and [this screen defi Different setting Prism (P) EDM n	ne the active EDM, E lectronic D istance s for measurements are available with Non- nodes.
Access	1. Select	Settings from t	he Main Menu .
	2. On the	General page,	select EDM.
	3. Press t tings.	he 🗊 button to	scroll through the screens of available set-
EDM Settings	C EDM Settings EDM Ligh EDM Mode Target Meas. Mode Leica Const. Abs. Const.	ts Round (GF Precis 0.0 n -34.4 n	
	Kev	Description	
	Atmos	To enter atmos	spheric data ppm.
	Ind.PPM	To enter an inc	dividual ppm value.
	↓ Scale	To enter projec	ction scale details.
	↓ Signal	To view EDM S	ignal reflection value.
	↓ Freq.	To view the ED	0M frequency.
	Description of	fields	
	Field	Description	Description
	EDM Mode	Prism	For distance measurements using prisms.
		Non-Prism	For distance measurements without prisms.
		Таре	For distance measurements using Retro reflective targets (3 mm + 2 ppm).

Field	Description	Description	
Target	Round (GPR)		Standard prism GPR121/GPR111 Leica Const. : 0.0 mm
	Mini (GMP) Mini0 (GMP111-0)		GMP111 Leica Const. : +17.5mm
			GMP111-0 Leica Const.: 0.0 mm
	360° (GRZ4)	86 64 78 78	GRZ4/GPZ122 Leica Const.: +23.1mm
	360°Mini(G RZ101)		GRZ101 Leica Const.: +30.0mm
	Tape (GZM)	\bigcirc	Leica Const. : +34.4mm
	360° (MPR122)		MPR122 Leica Const.: +28.1mm
	None	Without prism	Leica Const. : +34.4mm
	User 1 / User 2	For any prism modes, two of their own prisn Constants can be ente Leica Const. or Abs.	the user can define ns. red in mm in either Const. . For example:
		User prism constant	= -30.0mm
		Leica Const.	= +4.4 mm (34.4 + -30 = 4.4)
		Abs. Const.	= -30.0mm
Meas. Mode	Precise+	Fine measuring mode measurements with pr (1 mm + 1.5 ppm).	for highest precision isms
	Pre- cise&Fast	Quick measuring mode higher measuring spee (2 mm + 1.5 ppm).	e with prisms, with ed and high accuracy
	Precise	For distance measuren (2 mm + 2 ppm; >500	nents without prisms m: 4 mm + 2 ppm).

Field	Description	Description
	Average	Repeats measurements in standard measur- ing mode. Define the number of repetitions in No. of Meas. The average distance and the standard deviation for the averaged dis- tance are calculated.
		During the measurement, a status bar, the calculated slope distance and the standard deviation are displayed. Use Back to return to the previous screen without storing the data. Use Re-meas to omit all previous measurements and to restart. Use Cont to cancel the measurement process and to calculate the average from the available measurements.
	Tracking	For continuous distance measurements with prisms (3 mm + 1.5 ppm) or without prisms (5 mm + 3 ppm).
	Prism (>4.0km)	For long range distance measurements with prisms (5 mm + 2 ppm).
No. of Meas.	Editable field	The number of repeated measurements. Limit value: 2 to 99
Leica Const.	Display only	This field displays the Leica prism constant for the selected Prism Type .
	Editable field	Where Prism Type is User 1 or User 2 this field becomes editable to set a user defined constant. Input can only be made in mm. Limit value: -999.9mm to +999.9mm.
Abs. Const.	Display only	This field displays the absolute prism con- stant for the selected Prism Type .
	Editable field	Where Prism Type is User 1 or User 2 this field becomes editable to set a user defined constant. Input can only be made in mm. Limit value: -999.9mm to +999.9mm.
Laser-Point	Off	Visible laser beam is deactivated.
	On	Visible laser beam for visualising the target point is activated.
Guide Light	Off	Guide Light is deactivated.
	On	Guide Light is activated. The person at the prism can be guided by the flashing lights directly to the line of sight. The light points are visible up to a distance of 150 meters. This is useful when staking out points.



The refraction correction is taken into account in the calculation of the height differences and the horizontal distance. Refer to "16.7 Scale Correction" for the application of the values entered in this screen.

When **PPM=0** is selected, the Leica standard atmosphere of 1013.25mbar, 12°C, and 60% relative humidity is applied.

	Description of	fields		
	Field	Option	Description	
	Temp.Meas.	Auto	When a distance is me Dist , the temperature instrument temperatur displayed in the Temp eratur atmospheric ppm is rec played in the Atmos P distances are corrected pheric ppm.	asured using Meas or is read from the e sensor. The value is erature field. The calculated and dis- PM field. Measured I with the new atmos-
		Single	When pressing Temp , read from the instrume sor. The value is displa ture field. The atmosp ted and displayed in th	the temperature is ent temperature sen- yed in the Tempera- heric ppm is recalcula- ne Atmos PPM field.
		Manual	The temperature value ually.	can be entered man-
EDM Settings - Enter Projection Scale	This screen enat with the PPM pa the values enter	bles entry of th rameter. Refer ed on this scre	ne scale of projection. Coo to "16.7 Scale Correction een.	ordinates are corrected " for the application of
EDM Settings - Enter Individual PPM	This screen enat tance measurem Scale Correction	oles the entry ents are corre ' for the applic	of individual scaling factor cted with the PPM param cation of the values enter	rs. Coordinates and dis- eter. Refer to "16.7 ed on this screen.
EDM Settings - EDM Signal Reflection	This screen tests Enables optimal a beeping sound stronger the refl	the EDM sigr aiming at dist , indicate the ection.	al strength (reflection stream) ant, barely visible, targets reflection strength. The fa	ength) in steps of 1%. . A percentage bar and aster the beep the
ppm handling	General handli	ng		
	Handling of	Geom.pp	om Atmos. ppm	Indiv. ppm
	Slope distance	Not appli	ed Applied	Not applied
	Horizontal distance	Not appli	ed Applied	Applied
	Coordinates	Applied	Applied	Applied
	Exceptions Setout Geometric zontal dist found corr 	reduction valu ance difference	ues are applied to calculat are so that the position of	e and display the hori- points to be staked is

• LandXML Data and HeXML

To import and use the measurements into Leica Infinity, the distances recorded in LandXML differ from the distances on the instrument.

	Handling of	Geom. ppm	Atmos. ppm	Indiv. ppm	ppm tag
	Slope distance	Not applied	Applied	Not applied	Available
	Horizontal distance	Applied	Applied	Applied	Unavailable
	Coordinates	Applied	Applied	Applied	Unavailable
5.6	Interface Se	ettings			
Description	For data transfer the communication parameters of the instrument must be set.			nent must be	
Access	1. Select	Settings from	the Main Me i	nu.	
	2. On the	e Connect. pag	e, select Inte	face.	
Interface Settings	つ Interface Set	tings 🕑 I	0 =) 16:35		
	Config1				
	Port	RS			
	Baud rate Data bits	115	8		
	Parity	Ν	one <>		
	StopBits		1 <>		
	Flow Control	N	one <>		
		Default	Cont		
	Кеу	Description			
	BT-PIN	To set a PIN code for the Bluetooth connection. The default Bluetooth PIN is '0000'.			
	Default	To reset the fields to the default Leica standard settings. Available for RS232 .			
	Description of	fields			
	Field	Option	Description	n	
	Port		Instrument	port.	
		Bluetooth	Communica	tion is via Bluetoo	th.
		WLAN	Communica	tion is via WLAN.	
		RS232	Communica	tion is via RS232.	

The following fields are active only when **Port**: **RS232** is set.

Field	Option	Description
Baud rate	1200, 2400, 4800, 9600, 14400, 19200, 38400, 57600, 115200	Speed of data transfer from receiver to device in bits per second.
Data bits		Number of bits in a block of digital data.
	7	Data transfer is realised with 7 databits.
	8	Data transfer is realised with 8 databits.
Parity	Even	Even parity. Available if data bit is set to 7.
	Odd	Odd parity. Available if data bit is set to 7.
	None	No parity. Available if data bit is set to 8.
StopBits	Editable field	Number of bits at the end of a block of digi- tal data.
Flow Con- trol	RTS/CTS or None	Activates hardware handshake. When the instrument/device is ready for data, it asserts the Ready To Send line indi- cating it is ready to receive data. This line is read by the sender at the Clear To Send input, indicating it is clear to send the data.

The following fields are active only when **Port**: **WLAN** is set.

Field	Option	Description
IP address	Display only	Local IP address of
TCP/IP port	Display only	TCP/IP port number in use.

Leica standard settings

When **Default** is selected the communication parameters are reset to the default Leica standard settings:

• 115200 Baud, 8 Databit, No Parity, No Flow Control, 1 Stopbit.

a a b c d c d

- External battery
- Not connected / inactive
- GND
- d Data reception (TH_RXD)
- e Data transfer (TH_TXD)

5.7

FTP Client

Description

This functionality is to transfer jobs, codelists and other files on the data storage device with a standard and simple FTP server.

ettings

Interface plug connections

FTP protocol is used to transfer between an instrument, which has an Internet device connected, and the FTP server. The zip/unzip functionality is included.

	Configu	Configure and connect the Internet interface before using this function.		
Access	1.	Select Settings from the Main Menu .		
	2.	On the General page, select FTP .		
	3.	Press the 🗐 button to scroll through the screens of available set- tings.		

FTP Data Transfer

🕤 FTP Data Transfer		🕑 I 🛛	⊁! ⊡ 14:35
Config1			
Enter FTP conne	ction det	ails.	
Host			
Port			21
User ID			
Password			
Connect			

Кеу	Description
Connect	To connect to the FTP server entered.

Description of fields

•		
Field	Description	Description
Host	Editable field	In order to get access to the Internet, a host name is required. This host name is the name of the FTP server in the Internet.
Port	Editable field	Port to be used. Any number between 0 and 65535 is valid.
User ID	Editable field	The User ID allows connection to the FTP site. If no value is typed in, then the instru- ment logs in to the FTP server anonymously, if allowed.
Password	Editable field	The password to get access to the FTP site.

Next step

Connect. Once the connection to the FTP server is established, the **FTP Data Transfer**, **Local** page is displayed.

FTP Data Transfer,
Local pageThe files and folders on the selected data storage device of the instrument are
displayed including their size. To get into the folders, highlight the folder and
OK.

	 デ FTP Data Tra Local Off File Name 	ansfer 🕑 I lice Date	★ 15:34
	Application Codes DB Download Send	Data 24.07. 24.07. 24.07. 24.07. 24.07. 24.07.	18 18 18 18
	Key	Description	
	Send	To copy the file server.	e to its corresponding directory on the FTP
	USB	To change betw memory.	ween the data storage devices and the internal
	More	To change bet	veen date, time and size.
FTP Data Transfer, Office page	The files locate Whenever swite nected, then a	d on the FTP sen ching to this pag refresh action is	ver are displayed. e, if the connection to the server was discon- done or it reconnects to the server.
	Кеу	Description	
	Get	To download tl local downloac Downloaded fi	ne highlighted file list on the FTP server to the I folder. les are stored in the selected directory.
	More	To change bet	veen date, time and size.
5.8 Access	Internet Select	ttings	he Main Menu
	. Select		
	2. On the	e Connect. page	, select Internet .
	3. Press tings.	the 回 button to	scroll through the screens of available set-
Internet Settings	Description of	f fields	
	Field	Option	Description
	Device	Selectable list	The device for the connection to the Inter- net.
	Name	Display only	The name of the selected device.
	PIN-Code	Editable field	To enter the P ersonal Identification N umber of the SIM card.
	PUK-Code	Editable field	If the PIN is locked for any reason, for example the wrong PIN was entered, input the P ersonal U nbloc K ing code for access to the PIN.

	Field	Option	Description		
	Auto select	Yes or No	Select this option for a manual or automatic provider selection.		
	APN	Editable field	APN (Access Point Name of a server from the network provider). Contact your provider to get the correct APN.		
	APN cont.	Editable field	Access Point Name of a server from the net- work provider. The APN can be thought of as the home page of a provider supporting data transfer.		
	User ID	Yes	A user identification for the APN service can be typed in.		
		No	A user identification for the APN service is not required.		
	User ID	Editable field	Enter the User identification number.		
	Password	Editable field	Password for User ID .		
5.9	Adjust				
Description	The Adjustments Menu contains tools to be used for the electronic adjust- ment of the instrument and for setting adjustment reminders. Using these tools helps to maintain the measuring accuracy of the instrument.				
Access	 Select Settings from the Main Menu. 				
	2. On the Tools page, select Adjust . €				
	3. Select an adjustment option from the Adjustments screen.				
Adjustment options	In the Adjustm	ents screen, the	ere are several adjustment options.		
	Menu selectio	on	Description		
	Hz-Collimation		Refer to "13.3 Adjusting Line-of-Sight and Vertical Index Error".		
	Vertical Index		Refer to "13.3 Adjusting Line-of-Sight and Vertical Index Error".		
	Compensator	Index	Refer to "13.4 Adjusting the Compensator".		
	Tilting Axis		Refer to "13.5 Adjusting the Tilting Axis Error".		

	Menu selection	Description		
	View Current Adj. Data	Displays the current adjustment values that have been set for Hz-Collimation, V-index and Tilt Axis.		
	Adjustment Reminder	Defines the time period from the last adjust- ment to when a reminder message should display to do another adjustment. Options are: Never , 2 weeks , 1 month , 3 months , 6 months , 12months . The message will display the next time the instrument is switched on after the time period has been reached.		
5.10	Startup Sequence			
Description	Through the Startup tool, it is p key presses so that, after switch be displayed after the Level & For example, the general Settir tings.	possible to record a user-defined sequence of hing on the instrument, a particular screen can Plummet screen instead of the Main Menu . Ings screen for configuring the instrument set-		
Access	1. Select Settings from the Main Menu .			
	2. On the Tools page, se	lect Startup .		
Auto start step-by-	1. Press Record in the S	tartup screen.		
step	2. Press Cont to confirm the information message and begin the recording process.			
	3. The next key presses a recording press ESC .	The next key presses are stored, up to a maximum of 64. To end the recording press ESC .		
	4. If the auto start Statu be executed automatic	s is set to Active , the stored key presses will cally after switching on the instrument.		
	The automatic start sequence has the same effect as pressing the keys man- ually. Certain instrument settings cannot be made in this way. Relative entries such as automatically setting EDM Mode : Precise&Fast upon switching on the instrument, are not possible.			
5.11	System Information			
Description	 The Info screen displays: Instrument, system and firm Maintenance and service date Memory usage Settings for the date and ti Please provide the instatype, serial number and version and build number 	nware information ates me trument-related information, such as instrument id equipment number, as well as the firmware ber when contacting support.		

1. Select **Settings** from the **Main Menu**.

2.	On the Tools page, select Info .
3.	Press the 回 button to scroll through the screens of available set-
	tings.

Info

Page 1/5 or System

This screen displays information about the instrument and operating system.

Info		⊵ I	₿ 10:38
System	Softw. Sensor	Mem.	Dates IS07 1"
Serial N	0.		1
Equip.N NP-Typ	lo. e		 R1000
Instr.Te Battery	mp.		20 °C 70%
Reset	Options		Back

Кеу	Description
Reset	To reset all settings to the system default.
Options	To display hardware related options.

Page 2/5 or Softw.

🗂 Info			🕑 I	⊁! ⊡ 10:39
System	Softw.	Sensor	Mem.	Dates
InstrFirmware				V 0.94
Build Number			972.8	311012
EDM-Firmware			VC).00 (0)
Oper. Sy	ystem			

Apps	Legal Back
Кеу	Description
Apps	To display a list of the apps available on the instrument. A check mark is display in the check box beside each app that is licenced.
Legal	To display the Software Licence Agreement.

Description of fields

Field	Option	Description
InstrFirm- ware	Display only	Displays the firmware version number instal- led on the instrument.
Build Num- ber	Display only	Displays the build number of the firmware.

Field	Option	Description
Active Lan- guage	Display only	Displays the current language and version number selected for the instrument.
EDM-Firm- ware	Display only	Displays the version number of the EDM firmware.
Oper. Sys- tem	Display only	Displays the operating system of the instru- ment.

Page 3/5 or Sensor

Field	Option	Description
Loader Angle Hz	Display only	Loader version for the horizontal angle sys- tem
Loader Angle V	Display only	Loader version for the vertical angle system
Loader Incli- nat.	Display only	Loader version for the inclination system
Angle Hz	Display only	Software version of the horizontal angle sys- tem
Angle V	Display only	Software version of the vertical angle system
Inclination	Display only	Software version of the inclination system
AutoHeight	Display only	Displays the firmware version of the AutoHeight laser plummet. Available for TS07.

Page 4/5 or Mem.

Displays job-specific memory information such as the number of stored stations and fixpoints within a job, the number of recorded data blocks, for example measured points, or codes within a job, and the memory space occupied.

- Before pressing **Format**, to format the internal memory, ensure that all important data is first transferred to a computer. Jobs, formats, codelists, configuration files, uploaded languages and firmware are deleted by formatting.
- Despite an automatic defragmentation, the memory gets fragmented after a while. Please format the internal memory periodically to maintain the instrument performance.

Field	Option	Description
MaintEnd Date	Display only	Displays the end date of the maintenance agreement for the instrument firmware.
mySec.Rene wal Date	Display only	The date when the instrument must be con- nected to mySecurity in oder to renew the security functionality.
Next Service Date	Display only	Displays the date of the next service check required. The field can be invisible if turned off by the service reminder.

Page 5/5 or Dates

5.12	Licence Keys			
Description	To fully activate hardware functionality, firmware applications and firmware contracts, licence keys may be required on the instrument. Licence keys can be uploaded via Leica Infinity, the USB memory stick or the SD card.			
Access	1.	Select S	Settings from t	he Main Menu .
	2.	On the	Tools page, se	ect Licence .
Upload Licence Key	Кеу		Description	
	Delete		Deletes all firm firmware main	ware licence keys on the instrument and the tenance licence.
	Descript	tion of	fields	
	Field		Option	Description
	Methoo	d	USB-Stick or SD Card	The licence key file is uploaded from the data storage device.
5.13	Instrur	ment F	Protection w	vith PIN
Description	The instrument can be protected by a Personal Identification Number. If PIN protection is activated, the instrument will always prompt for a PIN code entry before starting up. If a wrong PIN has been entered five times, a Personal UnblocKing (PUK) code is required. This can be found on the instrument delivery papers.			
Activate PIN code step-by-step	1.	Select S	Settings from t	he Main Menu .
	2. On the Tools page, select PIN .			
	3. Activate PIN protection by setting Use PIN-Code : On .			
	4. Enter a personal PIN Code (max. 6 numerics) in the New PIN-Code field.			
	5. Accept with Cont .			
-	Now the instrument is protected against unauthorised use. After switching on the instrument, a PIN code entry is necessary.			
Lock instrument step- by-step	If PIN protection is activated, it is possible to lock the instrument from within any app without switching off the instrument.			
	1. Press the Favourites key when within any app.			
	 Select PIN-lock from the Favourites Menu. 			
Entering the PUK code	If a wrong PIN has been entered five times, the system will prompt for a Per- sonal UnblocKing code. The PUK code must be ordered from your Leica Geo- systems representative.			

If the PUK code entered is correct then the instrument will start up and reset the PIN code to default value **0** and **Use PIN-Code**: **Off**.

Deactivate PIN code step-by-step	1.	 Select Settings from the Main Menu. 		
	2.	On the Tools page, select PIN .		
	3.	Enter the current PIN in PIN-Code: .		
	4.	Accept with Cont .		
	5.	Deactivate PIN protection by setting Use PIN-Code: Off.		
	6.	Accept with Cont .		
	The ins	trument is now no longer protected against unauthorised use.		
5.14	Loadi	ng Software		
Description	Upload	s are possible from the USB memory stick or the SD card.		
	Alterna	tively use myWorld to upload files.		
Access	1.	Select Settings from the Main Menu .		
_	2.	On the Tools page, select Load FW .		
	Never disconnect the power supply during the system upload process. The bat- tery must be at least 80% capacity before commencing the upload.			
Loading firmware and languages step-by- step	129	All firmware and language files must be stored in the \SYSTEM folder to be transferred to the instrument. The upload file has the extension *.fw.		
	To loa	d firmware and languages at once		
		All freely available languages are installed automatically with a firm- ware upload.		
	1.	Select F1 Firmware. The Select File! screen will appear.		
	2.	Select the firmware file from the \SYSTEM folder of the USB memory stick or SD card.		
	3.	Press Cont .		
	4.	Once successfully loaded, the system will shut down and restart again automatically.		
	To loa	d language files separately		
	1.	Select F2 Language.		
	2.	Select the language file from the \SYSTEM folder of the USB memory stick or SD card.		

4.	The Upload Languages! screen will appear displaying all language
	files. Select Yes or No for a language file to be uploaded. At least
	one language must be set to Yes .

D. Pless CC	DIL.
6. Once su	ccessfully loaded, the system will shut down and restart Itomatically.

6	Apps - Getting Started					
6.1	Overvi	Overview				
Description	Apps are and facil app pack	Apps are predefined programs, that cover a wide spectrum of surveying duties and facilitate daily work in the field. The following apps are available, although app packages for each instrument may vary from that stated below:				
	Арр		TS03	TS07		
	Station	Setup	\checkmark	\checkmark		
	Survey		\checkmark	\checkmark		
	Setout		\checkmark	\checkmark		
	Tie Dist	ance	\checkmark	\checkmark		
	COGO	COGO		\checkmark		
	Area &	Area & DTM Volume		\checkmark		
	Remote	Remote Height		\checkmark		
	Traverse	Traverse		Optional		
	Referen	ce Line	\checkmark	\checkmark		
	Referen	Reference Arc		\checkmark		
	Referen	Reference Plane		\checkmark		
	Road 21)	Optional	\checkmark		
	Road 31)	Optional	Optional		
	Tunnel		Optional	Optional		
	Solution	Refer to the separate manual "Leica TS03/TS07 Tunnel Application".				
	Mining		Optional	Optional		
		Refer to the separate manual "Leica TS03/TS07 Mining Application".				
6.2	Startir	ig an App				

0.2	Star	Starting an App		
Access	1.	Select Apps from the Main Menu .		
	2.	Press the 回 button to scroll through the screens of available apps.		
	3.	Press the number of the app (for TS03) or tab on an icon (for TS07) to select the specified app in the Programs Menu .		
Pre-settings screens	Pre-settings for Survey is shown as an example. Any additional settings for pa ticular apps are explained within the chapters for those apps.			

ា Survey ្រ	᠑I 봤 <mark>□</mark>	
Descrip Config.		
Measure unli number of po Pre-settings job and statio can be done.	mited bints. for on	Page key for TS03 or tap on page for TS07 to change to another page. Refer to "5.4 Screen & Audio Set- tings" to turn off the app descrip- tion.
	Cont	Cont To change to the next screen.
ら Survey	❷ I 📮	
Descrip Config.		
[·]F1 Set Job	(1)	
[·]F2 Station Setup	(2)	
E4 Start	(4)	• = Setting has been made.
	(4)	[] = Setting has not been made.

Description of fields			
Field	Description		
F1 Set Job	To define the job where data will be saved. Refer to "6.3 Set- ting the Job".		
F2 Station Setup	To determine the station coordinates and station orientation. Refer to "6.4 Station Setup".		
F4 Start	Starts the selected app.		

6.3 Setting the Job

All data is saved in Jobs, like file directories. Jobs contain measurement data of different types, for example measurements, codes, fixpoints or stations. Jobs are individually manageable and can be exported, edited or deleted separately.

Access

Select F1 Set Job in Config. screen.



Description



Кеу	Description
Cont	To continue with the selected job.
New	To create a new job.
List	To display the list of available jobs.

Description of fields

Field	Option	Description
Job	Selectable list	Name of an existing job to be used.
Operator	Editable field	Name of operator, if entered.
Date	Display only	Date the selected job was created.
Time	Display only	Time the selected job was created.

Job list

└ Select	Job 1/1	e :	I 🔭 📼
Data			
Default		24.0	7.18
Search	▲ Name	▲ Date	Cont
14	D		
кеу	De	scription	

	-	-		
	Search	To search for a job. Refer to "3.7 Pointsearch".		
	▼ Name and ▲ Name	To sort the list according to ascending or descending job names.		
	▼ Date and ▲ Date	To sort the list according to ascending or descending job cre- ation dates.		
	Description of	columns		
	Column	Description		
	First column	Name of an existing job.		
	Second col- umn	Date the jobs were created.		
Recorded data	Once a job is se The last used jo	et up, all subsequent recorded data will be stored in this job. b is the active job.		
	If no job was de creates a new j	If no job was defined and an app was started, then the system automatically creates a new job and names it "Default".		
Next step	Press Cont to c	Press Cont to confirm the job and return to the Config. screen.		
6.4	Station Set	Station Setup		
Description	All measurements and coordinate computations are referenced to the set sta- tion coordinates and orientation.			

Station coordinate calculation



Station orientation calculation



Directions

- X Easting
- Y Northing
- Z Height

Station coordinates

- X0 Easting coordinate of station
- Y0 Northing coordinate of station
- Z0 Height of station

Known coordinates

- P0 Instrument station
- P1 Target point
- P2 Target point
- P3 Target point

Calculations

Hz1 Station orientation

Access

Select F2 Station Setup in Config. screen.

Next step

The Station Setup app begins. Refer to "7.2 Station Setup" for information on the Station Setup process.

B

If no station was set and an app was started, then the last station is set as the current station and the current horizontal direction is set as the orientation.

7	Apps			
7.1	Common Fields			
Description of fields	The following ware apps. Th chapters unle	table describes common fields that are found within the firm- nese fields are described here once and not repeated in the app ress the field has a specific meaning within that app.		
	Field	Description		
	PtID, Point, Point 1	Point ID of the point.		
	hr	Height of the reflector.		
	Remark / Code	Remark or Code name depending on the coding method. Three coding methods are available:		
		 Remark coding: This text is stored with the correspond- ing measurement. The code is not related to a codelist, it is just a simple remark. A codelist on the instrument is not necessary. 		
		 Expanded coding with codelist: Code The code that was entered is searched for within the code list and it is possible to see, change and/or add attributes to the code. To toggle through the codelist, change to page 4/4 for TS03 or to page Code for TS07. Quick coding: Q-Code Enter the shortcut to the code. The code is selected and the measurement starts. 		
	Hz	Horizontal direction to the point.		
	V	Vertical angle to the point.		
		Horizontal distance to the point.		
		Slope distance to the point.		
		Height to the point.		
	East	Easting coordinate of the point.		
	North	Northing coordinate of the point.		
	Height	Height coordinate of the point.		
7.2	Station Se	tup		
7.2.1	Starting	Starting		

Description

Station Setup is an app used when setting up a station, to determine the station coordinates and station orientation. A maximum number of 10 known points can be used to determine the position and orientation.


Setup methods

The following setup methods are available:

Setup method	Description		
Orientation with Angle	The station is known. Aim at a target to set the orientation.		
Orientation with Coordinates	The station and target coordinates are known. Aim at a target to set the orientation and height.		
Height Transfer	The station is known, a new station height must be computed. Measure to one or more known targets to compute new height for the station.		
Resection	The station is unknown. Measure to two or more target points to compute station coor- dinates and orientation. Scale setting is con- figurable.		
Helmert Resection	The station is unknown. Measure to two or more target points to compute station coor- dinates and orientation. The measured angles and distances are adjusted, based on coordinates of a local and global system.		
	A 2D Helmert transformation is used, with four (shift x, shift y, rotation and scale) or three (shift x, shift y, rotation) parameters, depending on the scale setting in the config- uration. Points can be defined as 1D, 2D or 3D.		
Local Resection	The station is unknown. Measure distances to two points:		
	 To the origin (E = 0, N = 0, H = 0) of the coordinate system To a point the North or East direction of the coordinate system 		
	Scale and standard deviation are not calcula-ted.		
Fach setup method requires diff	ferent input data and a different number of tar-		

Each setup method requires different input data and a different number of target points. Access

1. Select **Apps** from the **Main Menu**.

2.	Select Setup from the Programs Menu .
3.	Select a job. Refer to "6 Apps - Getting Started".
	Salact E2 Sattings:

4. Select F2 Settings:

• Set the standard deviation limits for the position, height, Hz orientation, and the Face I-II difference. For Local Resection, define the positive North or positive East axis. For Resection Helmert, set the distance weighting that is used in the calculation of the station height in the Resection. The height weighting can be configured.

Set **Calc.new Scale**: **Yes** to calculate the scale for the setup methods Resection and Resection Helmert. The scale can then be set at the end of the Resection calculation. Measured distances are always reduced with the scale set on the instrument. The computed scale is applied on the coordinates.

- Press **Cont** to save the limits and return to the **Station Setup** screen.
- 5. Select **F4 Start** to begin the app.

Enter Station Data

🗂 Enter S	tation Data	🕑 I 将 🛄
Data		
Ori. with A	ngle	
Station		Stn001
hi		1.500 m

|--|

Key	Description
Meas	 Optional for TS07. To measure the instrument height using the integrated AutoHeight laser plummet. Refer to "Measure Station Height".
1.	Select the desired setup method.
2.	Enter the station number or press Find or List to select an existing point. If the entered station number can not be found in the current job, then the Point Search screen appears. Select a different job to search or press New to enter the coordinates manually. New is only available for the methods Ori. with Angle, Ori. with Coord. and H-Trans.
3.	For all methods except Ori. with Angle and Local Resection, press Cont to continue to the Enter Target Point screen.
	For the Ori. with Angle method, Cont continues to the Manual Angle Setting screen. Refer to "7.2.2 Measuring the Target Points", "Manual Angle Setting".

For the Local Resection method, **Cont** continues to the **Meas. Pt1: Origin (0/0/0)** screen. The first point measured is the origin of the coordinate system. The second point measured is, depending on the setting, either the North or East direction of the coordinate system.

4. **Enter Target Point**: Enter the PtID of the target. Press **Cont** to search for the point in the current job. Select the desired point or enter new coordinates and continue to the **Sight target point**! screen. Refer to "7.2.2 Measuring the Target Points", "Sight target point".

Measure Station Height

Optional for TS07.

🗂 Measure Station	Height 🕑 I 将 💻
Data	
Intensity	90% <mark><></mark>
Measured height Height Offset Instrument height	1.357 m 0.000 m 1.357 m
OK Dist	
Key D	escription

Кеу	Description
ОК	The measured instrument height is displayed and used in the setup app.
Dist	To measure the instrument height.

Description of fields

!		
Field	Option	Description
Intensity	Scroll bar	External influences and the surface condi- tions may require the adjustment of the intensity of the plummet. Adjust the intensity of the plummet using the navigation key. The laser can be adjusted in 20% steps as required.
Measured height	Display only	The height measured by the laser plummet.
Height Off- set	Editable field	The entered value is added to the measured vertical distance.
Instrument height	Display only	The sum of Measured height and Height Offset .

7.2.2

Measuring the Target Points

Manual Angle Setting Available for Method: Ori. with Angle only.

	1. Enter the point ID and height of the target.		
	2. Measu face: Face	ire the Hz angle and repeat the measurement in the ohter e	
	3. Press	Set to set the new orientation. The station setup is complete.	
Sight target point	The remaining s Local Resection	The remaining screens are available for all methods except Ori. with Angle and Local Resection.	
	Sight the target target target point.	t point and select Meas , or Dist and Store to measure to the	
Station Setup Result	C Station Setup Select Accur. Posit. Accur. Height Accur. Hz F1 Measure mo F2 Measure in o F3 Access Toler F4 Compute F1 F2	P Result I I I $\dots,\dots,\dots,\dots,\dots,\dots,\dots,\dots,\dots,\dots,\dots,\dots,\dots,\dots,\dots,\dots,\dots,\dots,\dots,$	
	Key Description		
	F1 Measure more points	To return to the Enter Target Point screen to measure more points.	
	F2 Measure in other face	To measure the same target point in another face.	
	F3 Access Tolerances	To change the accuracy limit values.	
	F4 Compute	To calculate and display the station coordinates.	
	Description of symbolsSymbolDescription		
	~	Standard deviation/value within the defined limit	
	×	Standard deviation/value exceeds the defined limit	
	_	No value calculated	

	Description of	f fields	
	Field	Option	Description
	Accur. Posit.	Display only	If the standard deviation for position in East and North is calculated, a checkbox is dis- played. The checkbox is checked if the calcu- lated position is within the standard devia- tion limits or crossed if it is not.
	Accur. Height	Display only	If the standard deviation for Height is calcu- lated, a checkbox is displayed. The checkbox is checked if the calculated Height is within the standard deviation limits or crossed if it is not.
	Accur. Hz	Display only	If the standard deviation for the Hz Orienta- tion angle is calculated, a checkbox is dis- played. The checkbox is checked if the calcu- lated Hz Orientation is within the standard deviation limits or crossed if it is not.
7.2.3	Station Setu	p Results	
Computation procedure	 The computation of the station position is done via the Method selected in Enter Station Data. If more than the minimum required measurements are performed, the procedure uses a least squares adjustment to determine the 3D position and averages orientation and height measurements. The original averaged face I and face II measurements are used for the computation process. All measurements are treated with the same accuracy, whether these are measured in single or dual face. Easting and Northing are determined by the least squares method, which includes standard deviation and improvements for horizontal direction and horizontal distances. The final height (H) is computed from averaged height differences based on the original measurements. For the methods Ori. with Coord. and H-Trans the height can be selected from old, average and new. The horizontal direction is computed with the original averaged face I and face II measurements and the final computed plan position. 		
Access	Press F4 Comp	oute in the Stat	ion Setup Result screen.
Station Setup Result	This screen disp depend on the	plays calculated Method selecte	station coordinates. The final computed results ed in Enter Station Data .
	Standard deviat	tions and residu	als for accuracy assessments are provided.
	چې اf the the sta	instrument heig ation height refe	ht was set to 0.000 in the setup screen, then ers to the height of the tilting axis.

Station	ı Setup Result 1/2 🕑 ፲ ᅟ 🚛
Result1	Result2
Station	Stn001
hi	1.500 m
East	0.000 m —
North	0.000 m —
Height	-0.152 m 🗸
Hz	200.024 g 🗸
Δ_	m
Add Pt	Resid. Std.Dev Set

Кеу	Description
Add Pt	To return to the Enter Target Point screen to enter the next point.
Resid.	To display residuals and to define the use of points as 1D, 2D or 3D. Refer to "Residuals".
Std.Dev	To display the standard deviation of the station coordinates and orientation.
Set	To set the station coordinates and/or orientation.

Field	Option	Description
Station	Display only	Current station ID.
hi	Display only	Current instrument height.
East	Display only	Calculated Easting coordinate of the station.
North	Display only	Calculated Northing coordinate of the sta- tion.
Height	Display only	Calculated Height coordinate of the station.
Hz	Display only	Current Hz angle with the new orientation.
Δ 🚄	Display only	Available for Method : H-Trans or Ori. with Coord. with only 1 target point. Difference between the calculated and measured hori- zontal distance from the station to the design target.
Scale	Display only	Available for Method : Resection and Method : Res.Helm. . The calculated scale, if available.
Apply Scale	Display only	Yes or No . Select Yes to use the calculated scale as the system PPM scale. This over- writes any PPM scale previously set in the EDM Settings screens. Select No to keep the existing PPM value in the system and not apply the calculated scale.

Residuals

The screen displays the computed residuals for the horizontal and vertical distances and the horizontal direction.

Residual = Calculated value - Measured value.

Description of fields			
Field	Option	Description	
Use		Indicates if and how a target point is used in the station calculation.	
	3D	Easting, Northing and Height coordinates are used for the calculation.	
	2D	Easting and Northing coordinates are used for the calculation.	
	1D	Only the height of the point is used for the calculation.	
	Off	The point is not used for the calculation.	
Δ Hz	Display only	Difference in direction	
Δ	Display only	Difference in horizontal distance	
Δ	Display only	Difference in height	

Messages

The following are important messages or warnings that may appear.

Messages	Description
Selected point has invalid data! Check data and try again!	This message occurs if the selected target point has no Easting or Northing coordinate.
Max. 10 points supported!	10 points have already been measured and another point is selected. The system supports a maximum of 10 points.
No position computed due to bad data!	The measurements may not allow final sta- tion coordinates (Eastings, Northings) to be computed.
No height computed due to bad data!	Either the target height is invalid or insuffi- cient measurements are available to compute a final station height.
Face I-II limit exceeded! Re-measure point in both	This error occurs if a point was measured in one face and the measurement in the other face differs by more than the specified accu- racy limit for the horizontal or vertical angle.
No data measured! Meas- ure point again!	There is insufficient data measured to be able to compute a position or height. Either there are not enough points used or no dis- tance measured.

Next step

Press **Set** to set the station coordinates and/or orientation and return to the **Apps Menu**.

	 If a target point is measured several times in the same face, only the last valid measurement is used for computation. For Method: Resection: The prism used for face I and face II measurements must be the same. If different codes for face I and II are used, then the code of face I is used. If only face II is measured with a code, then the code of face II is assigned to the point. If the scale is calculated, then the standard deviation of the position with two targets is 0.0000. With flexible scale, the resection is fitted perfectly into the geometry without redundancy. 		
7.3	Surveying		
Description	Survey is an app used for the measurement of an unlimited number of points. It includes pre-settings for the job, station and orientation prior to beginning a survey.		
Access	1. Select Apps from the Main Menu .		
	 Select Survey from the Programs Menu. 		
	3. Complete app pre-settings. Refer to "6 Apps - Getting Started".		
Survey	Survey Map PtiD 451 hr 1.500 m Code ✓> Hz 200.037 g V 11.000 g I 1.719 m Meas Dist		
	Key Description		
	Q-Code To activate quick coding. Refer to "9.2 Quick Coding".		
	IndivPt To switch between individual and running point numbers.		
7.4	Setout		
Description	Setout is an app used to place marks in the field at predetermined points. These predetermined points are the points to be staked. The points to be staked may already exist in a job on the instrument, or be manually entered. The app can continuously display differences, between current position and desired stake out position.		
Stakeout modes	Points can be staked using different modes: Polar mode, Orthogonal to statio mode and Cartesian mode.		

Polar Stakeout mode



- P0 Instrument station
 - Current position

Ρ1

a-

C+

- P2 Point to be staked
 - $\Delta \mathbf{\underline{}}$: Difference in horizontal distance
- b+ ΔHz: Difference in direction
 - ∆ 🚽: Difference in height

Orthogonal to Station Stakeout mode



Cartesian Stakeout mode

P1 P0 P1 P2 c c b

- P0 Instrument station
- P1 Current positionP2 Point to be staked
- d1- Δ L: Difference in longitudinal distance
- d2+ Δ T: Difference in perpendicular distance
- d3+ Δ H: Difference in height
- P0 Instrument station
- P1 Current position
- P2 Point to be staked
- a ΔE: Difference in Easting coordinate
- b ΔN: Difference in Northing coordinate
 - ∆H: Difference in height

Access

Select Apps from the Main Menu.
 Select Setout from the Programs Menu.
 Complete app pre-settings. Refer to "6 Apps - Getting Started".

С

Setout Settings

Description of fields		
Field	Option	Description
Pre-/Suffix		Only used for the Setout app.
	Prefix	Adds the character entered for Identifier in front of the original point number of the point to be staked.
	Suffix	Adds the character entered for Identifier at the end of the original point number of the point to be staked.
	Off	The staked point is stored with the same point number as the point to be staked.
Identifier	Editable field	Only used for the Setout app.
		The identifier can be up to four characters and is added at the start, or end, of a point number of a point to be staked.
Setout Beep	On	The instrument beeps when the distance from the current position to the point to be staked is ≤ 0.5 m. The closer the prism is to the point to be staked the faster the beeps will be.
	Off	Beep is deactivated.
Filter	Off	No filter is active
	Nearest	Searches the job for points close to the cur- rent position. The points are selected as the points to be staked. After staking and storing the first nearest point, the next nearest point is suggested for staking out. The app algorithm sorts the points according to the minimum walking distance in all direc- tions to each point.
	Radius	Shows points within the defined radius from a particular point. The radius is the horizontal distance.
	PtId Range	Shows points with point IDs between the entered start and end ID.
Centre Point	Editable field	The point to which the radius is applied. Available for Filter : Radius .
Radius	Editable field	The radius of the circle within which the points are shown. Available for Filter : Radius .
From	Editable field	The first point to be displayed. Available for Filter : PtId Range .

Setout		🕑 I 将 🛄
Polar	Local Co	oord 1 Coord 2
Find Pt Type/ID) Meas	0.000
	4.1 <	≥∕ ▮ ∢∖ ╹
nr ∆Hz	0.000 n -0.000 g	
Δ_	0.000 n	
Δ	0.000 n	n 0.000
Meas	Dist S	Store 🖡

Кеу	Description
↓ B&Dist	To enter the direction and horizontal distance to a stake out point.
↓ Manual	To manually enter coordinates of a point.
I Survey To switch to the Survey app. Press ESC to return to the Solution Solution Solutio	
Refer t ments.	o "3.8 Graphic Symbols" for a description of the graphic ele-

Field	Option	Description
Find	Display only	Available when no filter is applied. Value for Point ID search. After entry, the firmware searches for matching points, and displays these in PtID : If a matching point doesn't exist the pointsearch screen opens.
Radius	Selectable list	Available when the point filter is active. the defined radius from a particular point.
Range	Display only	Available when the range is active. The defined range of points. For long point IDs, the last digits are be shown and the first digits are cut.
Pt Type/ID	Display only	 Displays the type of point selected. Fixpt., or Meas.
∆Hz	Display only	Angle offset: Positive if stake out point is to the right of the measured point.
Δ 🚄	Display only	Horizontal offset: Positive if stake out point is further away than the measured point.
Δ	Display only	Height offset: Positive if stake out point is higher than the measured point.
ΔL	Display only	Longitudinal offset: Positive if stake out point is further away than the measured point.
ΔΤ	Display only	Perpendicular offset: Positive if stake out point is to the right of the measured point.
Δ H	Display only	Height offset: Positive if stake out point is higher than the measured point.

Field	Option	Description
$\Delta \mathbf{E}$	Display only	Easting offset: Positive if stake out point is to the right of the measured point.
$\Delta \mathbf{N}$	Display only	Northing offset: Positive if stake out point is further away than the measured point

7.5	Reference Line		
7.5.1	Overview		
Description	 Reference Line is an app that facilitates the easy stake out or checking of lines, for example, for buildings, sections of road, or simple excavations. It allows the user to define a reference line and then complete the following tasks with respect to that line: Line & offset Stake out points Grid stake out Line segmentation stake out 		
Access	 Select Apps from the Main Menu. Select Ref.Line from the Programs Menu. 		
	3. Complete app pre-settings. Refer to 6 Apps - Getting started .		
Next step	Define the base line for the reference line.		
7.5.2	Defining the Base Line		
Description	A reference line can be defined by referencing a known base line. The reference line can be offset either longitudinally, in parallel or vertically to the base line, or be rotated around the first base point as required. Furthermore the refer- ence height can be selected as the first point, second point or interpolated along the reference line.		
Define the base line	The base line is fixed by two base points. All points can be either measured, manually entered, or selected from the memory.		
	Image: Weight of the second		

Define the base line by measuring or selecting the start and end points of the line.

Next step

After defining the base line the **Reference Line** - **Info** screen will appear for defining the reference line.

7.5.3 Defining the Reference Line

Description

The base line can be offset from, either longitudinally, in parallel or vertically, or be rotated around the first base point. This new line created from the offsets is called the reference line. All measured data refers to the reference line.



Access

Reference Line - Info

After completing the measurements required for defining the base line, the **Reference Line** - **Info** screen will appear.

つ Reference Line		🕑 I 👌 📴
Info	Shifts	
Point 1		412
Point 2		413 35 497 m
Length 33.497 m		55.497 m
Select Height Reference!		
Ref. Heigl	nt	Point 1 <>
Crid	Meas Dt	Setout

Кеу	Description
Grid	To stake out a grid relative to the reference line.
Meas Pt	To measure Line & Offset.
Setout	To stake out points orthogonal to the reference line.

Кеу	Description
NewBL	To define a new base line.
Shift=0	To reset all offset values to 0.
Segment	To subdivide a reference line into a definable number of seg- ments and stake out the new points on the reference line.

Field	Ontion	Description
	Disala	
Length	Display only	Length of the base line.
Ref. Height	Point 1	Height differences are computed relative to the height of the first reference point.
	Point 2	Height differences are computed relative to the height of the second reference point.
	Interpolated	Height differences are computed along the reference line.
	No Height	Height differences are not computed or shown.
Offset	Display only	Parallel offset of the reference line relative to the base line (P1-P2). Available on page 2/2 for TS03 or on page Shifts for TS07. Positive values are to the right of the base line.
Line	Display only	Longitudinal offset of the start point, refer- ence point (P3), of the reference line in the direction of base point 2. Available on page 2/2 for TS03 or on page Shifts for TS07. Positive values are towards base point 2.
Height	Display only	Height offset of the reference line to the selected reference height. Available on page 2/2 for TS03 or on page Shifts for TS07. Positive values are higher than the selected reference height.
Rotate	Display only	Rotation of the reference line clockwise around the reference point (P3). Available on page 2/2 for TS03 or on page Shifts for TS07.

Next step

Select a softkey option, **Meas Pt**, **Setout** or **↓ Segment**, to proceed to a sub-app.

7.5.4	Measure	Line &	Offset

Description

The Measure Line & Offset subapp calculates from measurements or coordinates, longitudinal offsets, parallel offsets and height differences of the target point relative to the reference line.

	ток 035	P4 d2 d1 P3	 P0 Instrument station P1 Start point P2 End point P3 Measured point P4 Reference point d1 Δ Offset d2 Δ Line
Example of height dif- ference relative to first reference point	dl P2 P1 Toxo20	P3 d3 d2	
_	 P1 Start poi P2 Target poi P3 Target poi a Reference d1 Height d d2 Height d d3 Height d 	nt oint oint ifference between start p ifference between P2 and ifference between P3 and	oint and the reference height the reference height the reference height
Access	Press Meas in	the Reference Line - Inf	o screen.
Measure line & offset	Description o	f fields	
	Field	Description	
	$\Delta \mathbf{L}$	Calculated distance long	gitudinal to the reference line.
	ΔΟ	Calculated distance per	pendicular from the reference line.
	Δ Η	Calculated height different height.	ence relative to the defined reference
Next step	Either, presOr, press	ss Meas to measure and Back to return to the Re	record. Eference Line - Info screen.
7.5.5	Stakeout		
Description	The stakeout so the calculated differences are	ubapp calculates the diffe point. The orthogonal (ΔL displayed.	rence between a measured point and , $\Delta \mathbf{O}$, $\Delta \mathbf{H}$) and polar ($\Delta \mathbf{Hz}$, $\Delta \underline{a}$, $\Delta \underline{a}$)

Example orthogonal stakeout



Access

Press Setout from the Reference Line - Info screen.

Orthogonal stakeout

Enter the stake out elements for the target points to be staked out relative to the reference line.

Decription of fields

Field	Option	Description
Line	Display only	Longitudinal offset: Positive if stake out point is further away from the reference line.
Offs	Display only	Perpendicular offset: Positive if stake out point is to the right of the reference line.
Height	Display only	Height offset: Positive if stake out point is higher than the reference line.

Next step

Press **Cont** to proceed to measurement mode.

Reference Line - Setout

The signs for the distance and angle differences are correction values (required minus actual). The arrows indicate the direction to move to get to the stake out point.

🗂 Reference Line - Setout 🕐 I 👌 🗔		
Polar		
PtID	414	
hr	1.500 m _{20.291}	
ΔHz	-90.057 g	
Δ	4.607 m	
Δ0	-0.000 m 49.126	
ΔL	-35.497 m	
Δ	1.943 m	
Meas	Dist Store 🖡	
Kov	Description	

Кеу	Description
Next Pt	To add the next point to be staked out.

	Description	n of fields
	Field	Description
	ΔHz	Horizontal direction from the measured point to the stake out point. Positive if the telescope must be turned clockwise to the stake out point.
	ΔL	Longitudinal distance from the measured point to the stake out point. Positive if stake out point is further away than the measured point.
	ΔΟ	Perpendicular distance from the measured point to the stake out point. Positive if stake out point is to the right of the measured point.
	Δ	Horizontal distance from the measured point to the stake out point. Positive if the stake out point is further away than the measured point.
		Height difference from the measured point to the stake out point. Positive if the stake out point is higher than the meas- ured point.
Next step	Either, pOr, pres	press Meas to measure and record. s J Back to return to the Reference Line - Info screen.
7.5.6	Grid Stakeout	
Description	The Grid sub on the grid, defined with points of the	papp calculates and displays the stake out elements for the points orthogonal (ΔL , ΔO , ΔH) and polar (ΔHz , $\Delta \perp$, $\Delta \perp$). The grid is nout boundaries. It can be extended over the first and second base e reference line.
	Example Gr	id Stakeout
		P2
	dl Pl d3	a Reference line P0 Instrument station P1 Start point P2 End point d1 Start distance
	T50X,039	PO d2 Increment d3 Line offset
Access	Press Grid f	rom the Reference Line - Info screen.
Grid definition	Enter the ch tion of the r	ainage and the increment of grid points in length and cross direc- reference line.

「 Reference Grid		⊵ I	⊁ , ⊡ 13:30
Config.			
Enter start chai	inage of grid	!	
Start Chain		100).000 m
Increment grid points by			
Increment		3	3.500 m
Offset		0).500 m
Back			Cont

Field	Options	Description
Start Chain	Editable field	Distance from the reference line start point to the beginning grid start point.
Increment	Editable field	Length of incrementation.
Offset	Editable field	Offset distance from the reference line.

Next step

Press Cont to proceed to the Reference Grid - Setout screen.

Reference Grid - Setout

The signs for the distance and angle differences are correction values (required minus actual). The arrows indicate the direction to move to get to the stake out point.

C Reference Grid - Setout O I ♣ □ 13:32		
Polar	Local	
PtID	414	
hr	1.500 m _{0.651}	
Chn	100.000	
Offs	0.000 <>	
ΔHz	-0.032 g 🚽 0.041	
Δ_	-0.651 m	
Δ	-0.548 m	
Meas	Dist Store EDM	

Description of fields

Field	Option	Description
Chn	Selectable field	The chainage of the grid stakeout point.
Offs	Selectable field	Offset increment values. The stake out point is to the right of the reference line.
ΔHz	Display only	Horizontal direction from the measured point to stake out point. Positive if the telescope must be turned clockwise to the stake out point.

	Field	Option	Description
	Δ 🚄	Display only	Horizontal distance from the measured point to stake out point. Positive if the stake out point is further away than the measured point.
	Δ 🛋	Display only	Height difference from the measured point to the stake out point. Positive if the stake out point is higher than the measured point.
	Line	Display only	Grid increment values. The stake out point is in the direction from the first to the second reference point.
	ΔL	Display only	Longitudinal distance from the measured point to the stake out point. Positive if stake out point is further away than the measured point.
	Δ Ο	Display only	Perpendicular distance from the measured point to the stake out point. Positive if stake out point is to the right of the measured point.
Next step	 Either, press Meas to measure and record. Or, press ESC to return to the Enter start chainage of grid! screen and from there, press Back to return to the Reference Line - Info screen. 		
7.5.7	Line Segm	entation	
Description	The line segmentation subapp calculates and displays the stake out elements for the points along the line, orthogonal (Δ L, Δ O, Δ H) and polar (Δ Hz, $\Delta (A, \Delta (A,$		
		a	
	T50X,040	dl P	PO Instrument station P1 First reference point P2 Second reference point a Reference line d1 Segment length
		-	dz Misciosure
Access	Press 🖡 Seg	ment from the Ref	erence Line - Info screen.
Segment Definition	Enter either the number of segments, or the length of segments and define how the remaining line length is treated. This misclosure can be placed at the start, at the end, at the start and the end or distributed evenly along the line		

Line Segment	🕑 I 将 💻
Config.	
Define Line Segment	
Line Length	35.497 m
Segment Length	3.500 m
Segment No.	11
Misclosure	0.497 m
Distrib.	At start <>
Back	Cont

Field	Option	Description
Line Length	Display only	Calculated length of the defined reference line.
Segment Length	Display only	Length of each segment. Updated automati- cally if the number of segments is entered.
Segment No.	Display only	Number of segments. Updated automatically if the segment length is entered.
Misclosure	Display only	Any remaining line length after segment length has been entered.
Distrib.		Method of misclosure distribution.
	None	All of the misclosure will be placed after the last segment.
	At start	All of the misclosure will be placed before the first segment.
	Equal	The misclosure will be equally distributed between all segments.
	StartEnd	The misclosure is equally distributed at the start and at the end of the segment line.

Next step

Press Cont to proceed to the Line Segment - Setout screen.

Line Segment - Setout

The signs for the distance and angle differences are correction values (required minus actual). The arrows indicate the direction to move to get to the stake out point.



Description of fields				
Field	Option	Description		
Segm	Selectable list	Segment number. Includes the misclosure segment, if applicable.		
CumL	Selectable list	Cumulation of the segment lengths. Changes with the current number of segments. Includes the misclosure segment length if applicable.		
ΔHz	Display only	Horizontal direction from the measured point to the stake out point. Positive if the tele- scope must be turned clockwise to the stake out point.		
Δ	Display only	Horizontal distance from the measured point to the stake out point. Positive if the stake out point is further away than the measured point.		
	Display only	Height difference from the measured point to the stake out point. Positive if the stake out point is higher than the measured point.		
ΔL	Display only	Longitudinal distance from the measured point to the stake out point. Positive if stake out point is further away than the measured point.		
ΔΟ	Display only	Perpendicular distance from the measured point to the stake out point. Positive if stake out point is to the right of the measured point.		

Messages

The following are important messages or warnings that may appear.

Messages	Description
Baseline too short!	Base line is shorter than 1 cm. Choose base points such that the horizontal separation of both points is at least 1 cm.
Coordinates invalid!	No coordinates or invalid coordinates for a point. Ensure that points used have at least Easting and Northing coordinates.
Recording to interface!	Data Output is set to Bluetooth in the Data Settings Menu . To be able to success- fully start reference line, Data Output must be set to Internal Memory .

Next step

- Either, press **Meas** to measure and record.
- Or, press **ESC** to return to the **Define Line Segment** screen and from there, press **Back** to return to the **Reference Line** screen.
- Or, continue selecting **ESC** to exit the app.

7.6	Reference Arc		
7.6.1	Overview		
Description	 The Reference Arc app allows the user to define a reference arc and then complete the following tasks with respect to the arc: Line & offset Stakeout (Point, Arc, Chord, Angle) 		
Access	1. Select Apps from the Main Menu .		
	2. Select Ret.Arc from the Programs Menu .		
	3. Complete app pre-settings. Refer to "6 Apps - Getting Started".		
Next step	Define the reference arc.		
7.6.2	Defining the Reference Arc		
Description	The reference arc can be defined by; • a center point and start point, • a start point, end point, and radius, or • by three points. All points can be either measured, manually entered, or selected from the memory. P2 P2 P2 Reference arc P0 Instrument station P1 Start point P2 End point P3 Center point P3 Center point P3 Center point P3 Center point P3 Center point		
	All arcs are defined in a clockwise direction and all calculations are made in two dimensions.		
Access	 Select Ref.Arc. Select the method to define the arc by: Centre & Start 		
	 Start, End & Radius 		

• 3 Points

Reference Arc - Measure to start point

Description of	TIEIOS			
Field	Option	Description		
Start Pt	Editable field	Point ID of the start point.		
Centre Pt	Editable field	Point ID of the center point.		
Mid Pt	Editable field	Point ID of the mid point.		
End Pt	Editable field	Point ID of the end point.		
Radius	Editable field	Radius of the arc.		
		A positive value, for example 100 m, is for a clockwise direction of the reference arc. A negative value, for example -100 m, is for an anticlockwise direction of the reference arc.		
Radius: 100 m Clockwise	Radius: -100 m Anti-clock- wise	Legend		
Solution 1				
P3 P1 P2 P2	P3 P1 P2 P2 P2	P1 Start point P2 End point		
Solution 2		P3 Centre point 1 P4 Centre point 2		
P1 P2 P2 d	d P3 P1 P4 P4	d Direction of the arc		
Solution 1				
P3 (1) P2 P2 P2	P3 d P4	P1 End point P2 Start point		
Solution 2		P3 Centre point 1 P4 Centre point 2		
		P4 Centre point 2 d Direction of the arc		

Next step

F

. .

After defining the reference arc the **Reference Arc** - **Info** screen will appear.

Reference Arc - Info

In certain cases, there are two mathematical solutions, as shown in the screenshot. In the subapps Measure and Stakeout, the appropriate solution can be selected.

└☐ Reference A	Arc 🕑 I 🗞 🗐			
Info				
Start Pt	410			
End Pt	411			
Radius	32.000 m			
Arc Length 1	41.081 m			
Arc Length 2	159.981 m			
Select Height Reference!				
Ref. Height	Interpolated <>			
New Arc	Cont			

Field	Option	Description	
Ref. Height		 Depending on the task chosen this parameter determines the design height. When measuring to a line, it affects the height difference value. When staking, it affects the delta height value. 	
	Start Point	Heights are computed relative to the height of the starting point of the line.	
	End Point	Heights are computed relative to the height of the end point of the line.	
	Interpolated	Heights are computed along the line.	
	No Height	Heights are ignored	

Next step

Select **Cont** and then **Meas Pt** or **Setout** to proceed to a subapp.

7.6.3

Description

Measure Line & Offset

The Measure Line & Offset subapp calculates from measurements or coordinates, longitudinal and orthogonal offsets and height differences of the target point relative to the reference arc.

Example reference arc - measure line & offset



Access

Press Meas from the Reference Arc - Info screen.

Measure Line & Off-	Description of fields			
set	Field	Option	Description	
	ΔL	Display only	Calculated di ence arc.	stance longitudinal to the refer-
	ΔΟ	Display only	Calculated di reference arc	stance perpendicular from the c.
	ΔH	Display only	Calculated he start point o	eight difference relative to the freference arc.
Next step	 Either, press Meas to measure and record. Or, press J Back to return to the Reference Arc - Info screen. 			
7.6.4	Stakeout			
Description	The Stakeou point and th stake out: • Stake ou • Stake ou • Stake ou • Stake ou	nt subapplication ca ne calculated point. ut point ut arc ut chord ut angle	lculates the di The Reference	fference between a measured Arc app supports four ways to
Stake out point	To stake out	a point by entering	P4 P4 P0 P1 P2 P3 P4 a b+ C-	Center point of arc Start point of arc Measured point Stake out point End point of arc Radius of arc Line offset Perpendicular offset
Stake out arc	To stake out	a series of equidis	P0 P0 P0 P0 P0 b	ong the arc. Center point of arc Start point of arc Stake out point Stake out point End point of arc Radius of arc Arc length

Stake out chord

To stake out a series of equidistant chords along the arc.



closure.

Field	Option	Description
	None	All of the misclosure will be added to the last arc-section.
	Equal	The misclosure will be equally distributed between all sections.
	Start Arc	All of the misclosure will be added to the first arc-section.
	Start & End	The misclosure will be added half to the first arc-section and half to the last arc-section.
Arc Length	Editable field	For stakeout arc: The length of the arc-seg- ment to stake out.
Chord Length	Editable field	For stakeout chord: The length of the chord to stake out.
Angle	Editable field	For stake out angle: The angle around the center point of the arc, of the points to be staked out.

Next step

Press **Cont** to proceed to measurement mode.

Reference Arc - Setout

The signs for the distance and angle differences are correction values (required minus actual). The arrows indicate the direction to move to get to the stake out point.

To allow a better visibility, for example if the arc is very long and the target close to the line, the scale for x and y can be different in the graphic. If the instrument is far off the arc, the instrument in the graphic is placed in the corner and marked red/grey.

To define the next point to be staked out, type in a point ID, the reflector height, the distance along the arc and an offset.

句 Refe	erence Arc - Setout	🕑 I 粘 🛄
Polar		
PtID	414	_
hr	1.500 m	0.468
Line	6.500 <>	\bullet
Offs	0.250 m	
ΔHz	-3.571 g 📢	1.618
Δ	-0.423 m	•
Δ	0.082 m	
		<u>A</u>
Meas	: Dist Sto	re EDM

	Description of fields			
	Field	Option	Description	
	∆Hz	Display only	Horizontal direction from the measured point to the stake out point. Positive if the tele- scope must be turned clockwise to the stake out point.	
	Δ	Display only	Horizontal distance from the measured point to the stake out point. Positive if the stake out point is further away than the measured point.	
		Display only	Height difference from the measured point to the stake out point. Positive if the stake out point is higher than the measured point.	
Next step	 Either, press ↓ Meas to measure and record. Or, press ↓ Back to return to the Reference Arc - Info screen. Or, continue selecting ESC to exit the app. 			
1.1	Reference			
Description	 Reference Plane is an applicate to measure points relative to a reference plane. It can be used for the following tasks: Measuring a point to calculate and store the perpendicular offset to the plane. Calculating the perpendicular distance from the intersection point to the local X- and Z-axis. The intersection point is the footprint point of the perpendicular vector from the measured point through the defined plane. Viewing, storing and staking out the coordinates of the intersection point. 			
	 A reference plane is created by measuring three points on a plane. These three points define a local coordinate system: The first point is the origin of a local coordinate system. The second point defines the direction of the local Z-axis. 			

• The third point defines the plane.



- X X-axis of local coordinate system.
- Y Y-axis of local coordinate system.
- Z Z-axis of local coordinate system.
- P1 First point, origin of local coordinate system.
- P2 Second point
- P3 Third point
- P4 Measured point. This point is probably not located on the plane.
- P5 Intersection point of the perpendicular vector from P4 to the defined plane. This point is definitely located on the defined plane.
- d+ Perpendicular distance from P4 to the plane.
- ΔX $\,$ Perpendicular distance from P5 to the local Z-axis.
- ΔZ $\,$ Perpendicular distance from P5 to the local X-axis.

The perpendicular distance to the plane can be positive or negative.



3. Complete app pre-settings. Refer to "6 Apps - Getting Started".

Access

Measure plane and target points

1.

- Once the plane has been defined by three points, the **Measure tar**get point! screen appears.
- 2. Measure and record the target point. The results are displayed in the **Reference Plane Result** screen.

Reference Plane Result

 ← Reference 	Plane Result 🕑 I 🗏 🛄	
Result		
Int.PtID:	441	
Offset	0.693 m	
ΔX	2.191 m	
ΔZ	5.806 m	
East	30.101 m	
North	4.901 m	
Height	7.153 m	
NewTgt S	etout NewPlan End	
Кеу	Description	
NewTgt	To record and save the intersection point and to proceed to	
	measure a new target point.	
Setout	To display stake out values and a graphic for the intersection point. Refer to "3.8 Graphic Symbols" for an explanation of	

the graphic symbols.

To define a new reference plane.

Description of fields

NewPlan

Field	Option	Description	
Int.PtID	Display only	Point ID of the intersection point, the per- pendicular projection of the target point on the plane.	
Offset	Display only	Calculated perpendicular distance between target point and plane (intersection point).	
$\Delta \mathbf{X}$	Display only	Perpendicular distance from the intersection point to the local Z-axis.	
ΔZ	Display only	Perpendicular distance from the intersection point to the local X-axis.	
East	Display only	Easting coordinate of the intersection point.	
North	Display only	Northing coordinate of the intersection point.	
Height	Display only	Height of the intersection point.	

7.8	Tie Distance
Description	Tie Distance is an app used to compute slope distance, horizontal distance, height difference and azimuth of two target points which are either measured, selected from the memory, or entered using the keypad.
Tie distance methods	 The user can choose between two different methods: Polygonal: P1-P2, P2-P3, P3-P4. Radial: P1-P2, P1-P3, P1-P4.

Radial method



Access

1.	Select Apps from the Main Menu .
2.	Select Tie Dist. from the Programs Menu .
3.	Complete app pre-settings. Refer to "6 Apps - Getting Started".
4.	Select Polygonal or Radial.

Tie distance measurements

Tie Distance Result -Polygonal method After completing the measurements required, the **Tie Distance Result** screen will appear.

🗂 Tie Dista	nce Result	Q	I 1 👫 🛄
Result			
Point 1			415
Point 2			416
Bearing		1	36.997 g
Grade		1.000:	0.029 h:v
Δ			3.533 m
Δ			3.534 m
Δ			0.104 m
NewPt 1	NewPt 2	End	Radial

	Кеу	Description		
	NewPt 1	To calculate an additional line. The app starts again at point 1.		
	NewPt 2	To set point 2 as the starting point of a new line. A new point 2 must be measured.		
	Radial	To switch to r	adial method.	
	Description	of fields		
	Field	Option	Description	
	Bearing	Display only	Azimuth between point 1 and point 2.	
	Grade	Display only	Grade between point 1 and point 2.	
	Δ	Display only	Slope distance between point 1 and point 2.	
	$\Delta \blacksquare$	Display only	Horizontal distance between point 1 and point 2.	
		Display only	Height difference between point 1 and point 2.	
Next step	Press ESC to	Press ESC to exit the app.		
7.9	Area & DT	Area & DTM Volume		
7.9.1	Overview			
Description	Area & DTM \ 50 points cor selected from calculated are the sloped re can be compu division is als	Area & DTM Volume is an app used to compute online areas to a maximum of 50 points connected by straights. The target points have to be measured, selected from memory, or entered via the keypad in a clockwise direction. The calculated area is projected onto the horizontal plane (2D) or projected onto the sloped reference plane defined by three points (3D). Furthermore a volume can be computed by automatically creating a digital terrain model (DTM). Area division is also possible for 2D areas.		

	P1 P4
	TSGX.949 PO
	 P0 Instrument station P1 Target point which defines the sloped reference plane P2 Target point which defines the sloped reference plane P3 Target point which defines the sloped reference plane P4 Target point a Perimeter (3D), polygonal length from the start point to the current measured point of the area (3D) b Area (3D), projected onto the sloped reference plane c Perimeter (2D), polygonal length from the start point to the current measured point of the area (2D) d Area (2D), projected onto the horizontal plane
Access	1. Select Apps from the Main Menu .
	 Select Area&Vol. from the Programs Menu.
	3. Complete app pre-settings. Refer to "6 Apps - Getting Started".
	4. Select an Area&Vol. subapp from the Area & DTM Volume Main Menu.
Map contents	The graphic on the Polar page shows the area projected onto the reference plane. The points used for defining the reference plane are indicated by:
	Icon Description
	Measured point
	Measured point active
	Manually entered point
	Manually entered point active
	Station
	Station active
	Points defining the reference plane

Map c

The graphic on the **Plot** page shows additionally the area projected onto the reference plane, the horizontal distance between the points the perimeter and the area.



2D / 3D Area

- 1. Measure or select existing points to define the area.
- 2. The 2D and 3D areas are calculated automatically and displayed once three points have been measured or selected.

2D / 3	D Area	🕑 I 将 🛄
Polar	Plot	
PtID	451	
hr	1.500 m	<u>←</u>
4	m	
Pts	4	
A 2D	156.591 m2	
A 3D	157.371 m2	

Meas | Calc | 1 PtBack | 👃

Кеу	Description
Calc	To display and record additional results.
1PtBack	To undo measurement or selection of the previous point.

Description	Description of fields		
Field	Option	Description	
A 2D	Display only	Two-dimensional area calculated by projec- tion onto a horizontal plane.	
A 3D	Display only	 Three-dimensional area calculated by projection onto an automatically defined horizontal reference plane. The 3D area is calculated based on the following: The system will use the three points which cover the largest area. If there are two or more equal largest areas, the system will use the area with the shortest perimeter. If the largest areas have equal perimeters, the system will use the area with the last measured point. 	

Next step

. . .

C C

Press **Calc** to calculate area and volume and proceed to the **2D / 3D Area Results** screen.

In the 2D / 3D Area Results screen.

- View the area in ha and m^2 as well as the perimeter of the area.
- Press NewArea to define a new area.
- Or, press **End** to exit the app.

Area to Reference Plane

- 1. Measure three new points or select three existing points to define the reference plane.
- 2. Then measure or select existing points to define the area.
- 3. The 2D and 3D areas are calculated automatically and displayed once three points have been measured or selected.

🕤 Area to Reference Plane 🕑 I 📑			
Polar	Plot		
PtID	447		
hr	1.500 m	<u>م</u>	
4	m		
Pts	4		
A 2D	156.591 m2		
A 3D	157.373 m2	b	

Meas | Calc | 1PtBack | 👃

Кеу	Description
Calc	To display and record additional results.
1PtBack	To undo measurement or selection of the previous point.

7.9.3

Area to Reference Plane

Description	of fields
-------------	-----------

Field	Options	Description
A 2D	Display only	Two-dimensional area calculated by projec- tion onto a horizontal plane.
A 3D	Display only	Three-dimensional area calculated by projec- tion onto the manually defined reference plane. The 3D area is calculated automatically after measuring or selecting three points.

Next step

1. Press **Calc** to calculate area and volume and proceed to the **Area to Ref. Plane Results** screen.

In the Area to Ref. Plane Results screen. View the area in ha and m² as well as the perimeter of the area.

- Press **NewArea** to define a new area.
- Or, press **End** to exit the app.

7.9.4	DTM Volume		
	The breakline points must be located within the boundary of the defined area.		
DTM Volume	1.	Measure or select existing points to define the area.	
	2.	The 2D and 3D areas are calculated automatically and displayed once three points have been measured or selected.	
	3.	Press Calc.	
	4.	Press @BLPt.	
	5.	Measure or select points on the breakline. These points are then used to calculate a volume.	
	6.	Press Calc .	
つ DTM Volume Results		ults 🕑 I 🔭 🛄	
--------------------------------------	--	------------------------------------	
2D	3D	Volume	
Pts Area Area Per. DTM-V	0.016 156.591 r 50.695 57.119 r	8 ha m2 m3	
NewArea	New BL	@BLPt End &Weigh⊕ I \$: 14:41	
2D	3D	Volume	
DTM-Grd	.Area	157.710 m2	
BreakLn /	Area	39.307 m2	
DTM-Volu	ume l	57.119 m3	
Swell Fac	tor	1.200	
DIM-Volu	ume II	68.543 m3	
Weight Fa		i/m3	
weight		0.000 t	

Кеу	Description
NewArea	To define a new area.
New BL	To define a new breakline area and calculate a new volume.
@BLPt	To add a new point to the existing breakline area and calcu- late a new volume.
End	To exit the app.

Description of fields

Field	Option	Description
A 2D	Display only	Two-dimensional area calculated by projec- tion onto a horizontal plane.
A 3D	Display only	 Three-dimensional area calculated by projection onto an automatically defined horizontal reference plane. The 3D area is calculated based on the following: The system will use the three points which cover the largest area. If there are two or more equal largest areas, the system will use the area with the shortest perimeter. If the largest areas have equal perimeters, the system will use the area with the last measured point.
Per.	Display only	The perimeter of the area.
DTM-V	Display only	Volume as calculated by by T riangulated Irre- gular N etwork (TIN).

Field	Option	Description
DTM- Grd.Area	Display only	Area defined by ground points, calculated by TIN.
BreakLn Area	Display only	Area defined by breakline points, calculated by TIN.
DTM-Volume I	Display only	Volume as calculated by TIN.
Swell Factor	Editable field	Factor that gives the relationship between the volume of a material as found in nature, to the volume of the same material after excavation. Refer to the table "Swell Factor" for more information on swell factors.
DTM-Volume II	Display only	Volume of the material after excavation from its original location. DTM-Volume II = DTM- Volume I x Swell Factor .
Weight Fac- tor	Display only	Weight in tons per m ³ of material. Editable field.
Weight	Display only	Total weight of material after being excava- ted. Weight = DTM-Volume II × Weight Factor.

Swell Factor

According to DIN18300, the following soil classes have the given swell factors.

Soil class	Description	Swell Factor
1	Topsoil containing unorganic material, as well as humus or organic animals.	1.10 - 1.37
2	Fluent soil types of fluid to semi-fluid consis- tency.	n/a
3	Easily degradable soil types. Cohesionless to hardly cohesive sands.	1.06 - 1.32
4	Moderately degradable soil types. Mixture of sand, silt and clay.	1.05 - 1.45
5	Hard to degrade soil types. Same soil types as classes 3 and 4, but with a greater ratio of stones bigger than 63mm and between 0.01 m ³ to 0.1 m ³ in volume.	1.19 - 1.59
6	Rock types that have an inner mineral cohe- siveness, however are fragmented, slaty, soft or weathered.	1.25 - 1.75
7	Hard to degrade rock types with a strong inner mineral cohesiveness and minimal fragmenting or weathering.	1.30 - 2.00

Swell factor examples: The values given are approximate only. Values may be different depending on various soil factors.

Soil type	Swell factor	Weight per cubic metre
Silt	1.15 - 1.25	2.1 t
Sand	1.20 - 1.40	1.5 - 1.8 t

Soil type	Swell factor	Weight per cubic metre
Clay	1.20 - 1.50	2.1 t
Topsoil, humus	1.25	1.5 - 1.7 t
Sandstone	1.35 - 1.60	2.6 t
Granite	1.35 - 1.60	2.8 t

Description

7.9.5 Area Division

Area division methods

The diagrams show the area division methods.

_	
	Area Division method
	Parallel line(%)

The border will be parallel to a line defined
by two points. The division is calculated
using a defined percentage split.



Area	Division method Descrip	tion
Swin	g line(%) The area an exist calculate	a is divided by a line rotated around ing point of the area. The division is ed using a defined percentage split.
	P1 007473.002 P0 Se P1 Ne Q Az	Poor Poor A N N N N N N N N N N N N N N N N N N
1.	Measure or select existing point	s to define the area.
2.	The 2D area is calculated autom points have been measured or s Only the 2D area is use	atically and displayed once three selected. d for area division.
3.	Press Calc.	
4.	2D Area Results screen:	
	C 2D Area Results 2D Pts 4 Area 0.016 ha Area 156.591 m2 Per. 50.695 m NewArea MeasDiv End	 NewArea To measure or define a new area. MeasDiv To define the area division according to the previous selected method. End To exit the app.
5.	Press MeasDiv .	
6.	For Parallel line(%) and Per- pend. line(%) : Measure or select existing point to define the area division line.	For Swing line(%) : Select an existing point of the area to define the rotation point of the swing line.
7.	Press Calc .	
8.	For Parallel line(%) and Per- pend. line(%) : Enter the percantage of the are division ALeft for the new left area.	For Swing line(%) : Enter the percantage of the area division ALeft for the new left area.
9.	Press Calc.	

Area Division

☆ Area Division Results _ ④ Ⅰ [♣] [■] 14:43		
Left	Right I	Plot
Left	50%	8
Area	~6 m2	\sim
Per.	~55 m	$-\Delta$
		$\langle \rangle$
Ptn1	AD3	\rightarrow
Ptn2	AD4	$\rightarrow \lambda$
Azim.		\vee
NewArea New Div Setout End		

Кеу	Description
NewArea	To measure or define a new area.
New Div	To define a new area division.
Setout	To stake out the calculated points.
End	To store the intersection points as fixpoints and to exit the app.

Description of fields

Field	Option	Description
Left and Right	Display only	The size of the sub areas in percent.
Area	Display only	The size of the sub area in m ² .
Per.	Display only	The perimeter of the sub area in m.
Ptn1	Display only	The first intersection point of the new boarder with the original area.
Ptn2	Display only	The first intersection point of the new boarder with the original area.
Azim.	Display only	The angle of the new border from rotation point to the new point.

7.10

Remote Height

Description

Remote Height is an app used to compute points directly above the base prism without a prism at the target point.



- PO Instrument station
- P1 Base point
- P2 Remote point
- d1 Slope distance
- a Height difference from P1 to P2
- α Vertical angle between base point and remote point

Access	1. Sele	ct Apps from the	Main Menu.
	2. Sele	ct Remote Ht fro	m the Programs Menu .
	3. Com	plete app pre-set	tings. Refer to "6 Apps - Getting Started".
Remote height measurement	Measure to theight.	ne base point or p	press hr=? to determine an unknown target
	Next step		
	After measur	ng, the Aim at re	emote point! screen appears.
Remote Height - Result - Aim at remote point!	Aim the instr	ument at the inac	cessible remote point.
	Description	of fields	Description
		Display only	Height difference between the base point and the remote point.
	Height	Display only	Height of the remote point.
	East	Display only	Calculated Easting coordinate for the remote point.
	North	Display only	Calculated Northing coordinate for the remote point.
	∆East	Display only	Calculated difference in Easting coordinate between the base point and the remote point.
	∆North	Display only	Calculated difference in Northing coordinate between the base point and the remote point.
	∆Height	Display only	Calculated difference in Height between the base point and the remote point.
Next step	 Either, pr coordina Or, press Or, press 	ess Cont to save tes of the remote Base to enter an ESC to exit the a	the measurement and record the calculated point. d measure a new base point. pp.
7.11	COGO		
7.11.1	Starting		
Description	COGO is an a coordinates c The COGO ca	pp used to perfor of points, bearings Iculation methods	m co ordinate g e o metry calculations such as, between points and distances between points. are:
	 Invers Inters Offset Extens 	e and Traverse ections : sion	

Access	1. Select Apps from the Main Menu .				
	2. Select COGO from the Programs Menu .				
	3. Complete app pre-settings. Refer to "6 Apps - Getting Started".				
	4. Select a COGO subapp from the COGO Main Menu .				
Graphics	In the Results screen, press Setout to access the Stakeout graphic.				
	Or, in the Results screen, change to the second page for a simple graphic. Refer to "3.8 Graphic Symbols" for a description of the graphic symbols.				
7.11.2	Inverse and Traverse				
Access	Select Inverse or Traverse from the COGO Main Menu.				
Inverse	Use the Inverse subapp to calculate the distance, direction, height difference and grade between two known points.				
	Known				
	P1 First known point P2 Second known point				
	Unknown				
	d3 α Direction from P1 to P2 d1 Slope distance between P1 and P2				
	α d2 Horizontal distance between P1 and P2				
	/ P1 / d3 Height difference between P1 TSOX.098 and P2				

Traverse

Use the **Traverse** subapp to calculate the position of a new point using the bearing and the distance from a known point. Offset optional.



Known

- P1 Known point
- α Direction from P1 to P2
- d1 Distance between P1 and P2
- d2 Positive offset to the right
- d3 Negative offset to the left

Unknown

- P2 COGO point without offset
- P3 COGO point with positive offset
- P4 COGO point with negative offset

7.11.3 Intersections

Access

Select the desired COGO subapplication from the ${\bf COGO}$ Main Menu:

- Brg-Brg
- Brg-Dst
- Dst-Dst
- 4 Point

Bearing - Bearing





Bearing - Distance

Use the **Bearing - Distance** subapp to calculate the intersection point of a line and a circle. The line is defined by a point and a direction. The circle is defined by the center point and the radius.



Distance - Distance

Use the **Distance** - **Distance** subapp to calculate the intersection point of two circles. The circles are defined by the known point as the center point and the distance from the known point to the COGO point as the radius.



4 Point

Use the **4 Point** subapp to calculate the intersection point of two lines. A line is defined by two points.

To add a shift for the lines, change to page **2/2** for TSO3 or page **Shifts** for TSO7. + indicates a shift to the right. - indicates a shift to the left.



Offsets 7.11.4 Select the desired COGO subapplication from the COGO Main Menu: Access • DistOff • Set Pt • Plane **Distance Offset** Use the Distance Offset subapp to calculate the distance and offset of a known point, with the basepoint in relation to a line. 4 N P2 Known PO Instrument station P4 P1 Start point d2 P2 End point d1 P3 Offset point P٦ Unknown Ρ1 d1 ∆ Line d2 \triangle Offset P4 COGO (base) point

Set Point by Distance Offset

Use the **Set Point by Distance Offset** subapp to calculate the coordinates of a new point in relation to a line from known longitudinal and offset distances.





Use the **Plane Offset** subapp to calculate the coordinates of a new point and its height and offset, in relation to a known plane and offset point.

4		P2	Kno	wn
~	P5	23	P1 P2 P3 P4	Point 1 which defines plane Point 2 which defines plane Point 3 which defines plane Offset point
		• P4	Unk	nown
TSOX_106	Pl		Р5 d1	COGO (intersection) point Offset

7.11.5	Line - Extension			
Access	Select Extens. from the COGO Main Menu.			
Line - Extension	Use the Line - Extension subapp to calculate the extended point from a known base line.			
	N P1 P2 P3 50X.107	KnownP1Baseline start pointP3Baseline end pointΔ L2ΔL1, ΔL2 DistanceP4P2, P4Extended COGO points		
7.12	Road 2D			

Description

Road 2D is an app used to measure or stake out points relative to a defined element. The element can be a line, curve or spiral. Chainage, incremental stake outs and offsets (left and right) are supported.



Access

1. Select **Apps** from the **Main Menu**.

2.	Select Road 2D from the Programs Menu .
3.	Complete app pre-settings. Refer to "6 Apps - Getting Started".
4.	Select the element type:
	• Straight

- Curve
- Spiral •

Elements



Define the element step-by-step

For curve and spiral elements the Road 2D screen for defining the element appears.

		⁺∃ Road 2D		🕑 I 👌 🛄		
		Config. Select method and Method Radius Parameter Length Direction Type Back	enter	data! Rad/Par. <>> 400.000 m 600.000 m 900.000 m Clk-wise <>> Spir.In <>> Cont		
	3.	For a curve element:	•	Enter the radius a Press Cont .	and cu	rve direction.
		For a spiral element:		Select the metho or Rad/Len. Enter the radius a and length, dependence chosen. Select the type and ral. Press Cont .	d to be and pa nding nd dire Spi i A B	e used, Rad/Par. rameter, or radius on the method ection of the spi- ral type Spiral in Spiral out
	4.	When the element ha	is bee	n defined the Roa	d 2D ·	Config.
-		арреагу.				
Chainage and method	Enter the • Seto and poin • Che age,	e chainage values and but : to select the poin start the measuremen t is shown on the disp ck : to measure, or sele line and offset from t	press It and It. The play. ect po he de	: offset (center, left correction from a pints from memory, fined element.	or rig ctual p , to cal	nt), to stake out oint to stake out culate the chain-

Enter stakeout values

ी Road 2	D		Ľ	۵ I	*	回り 14:59
Config.						
Enter chai	nage o	f Star	rt Point!			
Chainage				0	0.00	0 m
Start Pt						402
End Pt						403
Length				19	9.45	3 m
New			Setout		Che	eck

Next step

- •
- If in stakeout mode, press **Cont** to begin staking out. Or, if in measurement mode, press **Meas** to measure and record. •

7.13	Road 3D				
7.13.1	Starting				
Description	 Road 3D is an app used to stake out points or for as-built checks relative to a road alignment, including slopes. It supports the following features: Horizontal alignments with the elements straight, curve, and spiral (entry and exit as well as partial). Vertical alignments with the elements straight, curve and quadratic parabola. Upload of horizontal and vertical alignments which are in gsi data format of Leica Infinity Road Line Editor. Creation, view and deletion of alignments onboard. Use of design height of vertical alignments or manually entered heights. Log file via Format manager of Leica Infinity. 				
Road 3D methods	 Road 3D has the following subapps: Subapp Check Subapp Stake Subapp Check Slope Subapp Stake Slope 				
	The app can be trialled 15 times. After 15 trials, it is necessary to enter the licence code.				
Road 3D step-by-step	1. Create or upload road alignments.				
	2. Select horizontal and/or vertical alignment files.				
	3. Define stake/check/slope parameter.				
	4. Select one of the Road 3D subapps.				

- The alignments must be continuous because geometrical gaps and chainage equations are not supported.
- The file name for the horizontal alignment file must have the prefix ALN, for example, ALN_HZ_Axis_01.gsi. The file name for the vertical alignment files must have the prefix PRF, for example PRF_VT_Axis_01.gsi. File names can be 16 characters long.
- The uploaded or created road alignments are permanent and stored even if the app is closed.
- Road alignments can be deleted onboard or via Leica Infinity Data Exchange Manager.
- Road alignments cannot be edited onboard. This needs to be done via Leica Infinity Road Line Editor.

7.13.2 Basic Terms

Elements of a road project

Road projects consist, in general, of a horizontal and a vertical alignment. Any project point P1 has E, N and H coordinates in a determined coordinate



TSOX_108

P1' Position on natural surface

system and has three positions.

- P1" Position on vertical alignment
- P1'" Position on horizontal alignment

With a second point P2 the alignment is defined.

	P1' P2' P1'' P2'' P1''' P2'''	Projection of the alignment onto the natural surface. Vertical alignment Horizontal alignment
	α	Grade angle between the vertical and horizontal alignment.
	a b c	Natural surface Horizontal alignment Vertical alignment
Horizontal geometry elements	For onboar alignments	d input Road 3D supports the following elements for horizontal



Description			
 Entry spiral (Spiral in = A): Spiral with a radius of infinity at the start and a given radius at the end. Exit spiral (Spiral out = B): Spiral with a given radius at the start and radius of infinity at the end. Partial/Ovoid spiral: A spiral with a given radius at the start and another given radius at the end. 			
A Entry spiral R Epitepiral			

Vertical geometry elements

For onboard input Road 3D supports the following elements for vertical alignments.

Element	Description			
Straight	 A straight has to be defined by: Start chainage and start height of P1. End chainage and end height of P2, or length (L) and slope (%). 			
	P2 +% L P1 P2 P2 P2 P2 P2 P1 Start point P2 End point L Length % Slope			
Transition curve	 A circular curve has to be defined by: Start chainage and start height of P1. End chainage and end height of P2. Radius (R). Type: Convex (crest) or Concave (sag). a Convex b Concave b Concave P1 Start point P2 End point R Radius 			
Quadratic parabola	 A quadratic parabola has the advantage that the rate of change of grade is constant, resulting in a "smoother" curve. A quadratic parabola has to be defined by: Start chainage and start height of P1. End chainage and end height of P2. Parameter, or Length (L), grade of entry straight (GradeIn) and grade of exit straight (GradeOut). 			



Start and end chainage and tangent points can be different for the horizontal and vertical alignments.



- P1 Measured point
- Horizontal alignment а
- Hinge point Ь
- Slope С
- Catch point d
- Natural surface е
- f Defined offset
- Defined height difference g
- h Cut situation for defined slope i
- Δ Offset to catch point

Explanation of the slope elements:

- Horizontal alignment at a defined chainage. а
- Ь **Hinge point**, is defined by entered offset left/right and height difference.
- **Slope** = ratio. С
- **Catch point**, or daylight point, indicates the point of intersection between d the slope and the natural surface. Both the hinge point and the catch point lie on the slope.
- Natural surface, is the undisturbed surface before project construction. е

F

Slope elements

	Cut / Fill	Description
	Cut situation	a Horizontal alignment b Hinge point c Slope d Catch point e Natural surface
	Fill situation	
		 a Horizontal alignment b Hinge point c Slope d Catch point e Natural surface
7.13.3	Creating or Uploadi	ng Alignment Files
Description	Create horizontal and v Line Editor and upload Manager.	ertical road alignment files with Instrument Tools Road them onto the instrument using the Data Exchange
	Alternatively, horizontal the instrument.	and vertical road alignments can be created onboard
Access	1. Select Apps fr	om the Main Menu .
	2. Select Road 3	D from the Programs Menu.
	3. Complete app	pre-settings. Refer to "6 Apps - Getting Started".
 Select Alignment File:	: Select Alignment File:	
	Horiz. Aln. Vertic. Aln.	ALN_A1000 <> PRF_V1000 <>



Description of fields			
Field	Descr	iption	
Horiz. Aln.	List of available horizontal alignment files.		
		Using a horizontal alignment file is mandatory.	
Vertic. Aln.	List of available vertical alignment files.		
	B.	Using a vertical alignment file is not mandatory. A height can be defined manually instead.	

Next step

- Either, press **New** to name and define a new alignment file.
- Or, press **Cont** to select an existing alignment file and proceed to the **Set-out/Check/Slope** values screen.

Setout/Check/Slope

Setout/Chec	k/Slope 🕑 I	⊁ ! 15:26	
Local Offs. Left Offs. Right Ht.Diff. Def.Chain Increment Height Manual Ht.	0.250 1.250 -1.000 10.000 40.000 Manual Hei 10.000	m m m m ght <mark><></mark>	
Key	Description	• • • • • • • • • • • • • • • • • • •	
Setout	To start the su	bapp Stake .	
Check	To start the su	bapp Check .	
Stk Slp	To start the subapp Stake Slope .		
↓ Ch Slp	To start the subapp Check Slope .		
Description o	f fields		
Field	Option	Description	
Offs. Left	Editable field	Horizontal offset to the left of the horizontal alignment.	
Offs. Right	Editable field	Horizontal offset to the right of the horizon- tal alignment.	
Ht.Diff.	Editable field	Vertical offset, either up or down, from the horizontal alignment.	
Def.Chain	Editable field	Defined chainage for stake out.	
Increment	Editable field	Value by which the defined chainage can be incremented or decremented in subapps Stake and Stake Slope.	
Height	Manual Height	Height reference for height calculations. If enabled this height is used for all subapps.	

Field	Option	Description	
	Use Design Hgt.	The height reference for height calculations is the selected vertical alignment file.	
Manual Ht.	Editable field	Height to be used for Manual Height.	

Next step

Stake

Select a softkey option, **Setout**, **Check**, **Stk Slp** or **JCh Slp**, to proceed to a subapp.

7.13.4

Description

The subapp Stake is used to stake out points relative to an existing alignment. The height difference is relative to a vertical alignment or manually entered height.



Access

Press **Setout** from the **Setout/Check/Slope** values screen.

Setout

To find/enter codes, press the Favourites key and select **Coding**.



Description of fields

Field	Option	Description
DefChain	Selectable list	Selected chainage to stake out.
ΔHz	Display only	Angle offset: Positive if the stake out point is to the right of the measured point.

	Field	Option	Description
	Δ	Display only	Horizontal offset: Positive if the stake out point is further away than the measured point.
	∆Height	Display only	Height offset: Positive if the stake out point is higher than the measured point.
	∆Chain	Display only	Longitudinal offset: Positive if the stake out point is further away than the measured point.
	∆Offset	Display only	Perpendicular offset: Positive if the stake out point is to the right of the measured point.
	Def. East	Display only	Calculated East coordinate of the stake out point.
	Def. North	Display only	Calculated North coordinate of the stake out point.
	Def. Height	Display only	Calculated Height of the stake out point.
Next step	 Either, pres Or, press E 	ss Meas to mea SC to return to	sure and record. the Setout/Check/Slope values screen.
7.13.5	Check		
Description	The subapp Che selected from the existing horizor alignment or m	eck is used for a he memory. The ntal alignment, a anually entered	es-built checks. The points can be measured or chainage and offset values are relative to an and the height difference is relative to a vertical height.
	P1 C- C- a a boxes	d-	P2 P0 Instrument station P1 Target point P2 Target point a Horizontal alignment b Chainage c+ Offset, positive c- Offset, negative d+ Height difference, positive d- Height difference, negative
	Defined chaina Check.	ge and incremer	nt values will not be considered in the subapp
-			

Access

Press **Check** from the **Setout/Check/Slope** values screen.

3D-Road Check

🕤 3D-Road Check			e	ם נ	₿ <mark>15:32</mark>	
Local	Coord	I.				
PtID				4	03	
hr	hr			1.500 m		
Offset			Centre <>			
Chainage			19	.453	m	
Offset			-0.	.000	m	
Ht.Diff.			-0.768 m			
Height			8.	.232	m	
Find	List		Map		Ļ	

Description of fields

	Field	Öption	Description	
	Offset	Left, Right or Centre.	Defined horizontal offset.	
	Chainage	Display only	Current chainage from measured point.	
	Offset	Display only	Perpendicular offset to alignment.	
	Ht.Diff.	Display only	Height difference between the measured point and the defined height.	
	∆East	Display only	Calculated difference in Easting coordinate between the measured point and the align- ment element.	
	ΔNorth	Display only	Calculated difference in Northing coordinate between the measured point and the alignment element.	
Next step	Either, prOr, press	ess Meas to mea ESC to return to	sure and record. the Setout/Check/Slope values screen.	
7.13.6	Stake Slope	Stake Slope		
Description The subsection		take Slope is used of a defined slop	d to stake out the catch point, which is the inter- e with the natural surface.	
	The slope is a	always defined as	starting from a hinge point. If the parameter	

offset right/left and height difference are not entered, the point at the defined chainage on the horizontal alignment is the hinge point.



- P1 Measured point
- a Horizontal alignment
- b Defined offset
- c Defined height difference
- d Hinge point
- e Defined slope
- f Catch point
- g Natural surface
- \tilde{h} Δ Offset to catch point
- i Cut/fill to catch point
- j Offset to hinge point
- k Offset to alignment
- I Height difference to hinge point
- m Height difference to alignment

Access

Press **Stk Slp** from the **Setout/Check/Slope** values screen.

Define Slope Setout

Road 3D	🕑 I 🗞 💻			
Config.				
Define Slope Setout				
Offset	Centre <>			
Def.Chain	10.000 <>			
SlopeType	Right down <>			
SlopeGrade	1.000: 2.000 h:v			

Description of fields

Field	Option	Description	
Offset	Selectable list	Horizontal offset from the ho ment to define the hinge poi	rizontal align- nt.
Def.Chain	Selectable list	Defined chainage for stakeou	t.
SlopeType	Selectable list	Type of slope.	
		Left up Hinge point	Right up
		TSOX.120 Left down	Right down
	Left up	Creates an upward plane exte	ending to the
		left of the defined hinge poir	it.

Field	Option	Description
	Right up	Creates an upward plane extending to the right of the defined hinge point.
	Left down	Creates a downward plane extending to the left of the defined hinge point.
	Right down	Creates a downward plane extending to the right of the defined hinge point.
SlopeGrade	Display only	Ratio of the slope. The unit for slope grade is defined in the Regional Settings screen. Refer to "5.2 Regional Settings".

Slope Setout

Slope St	takeout	🕑 I 将 🛄		
Local	Hinge	Alignmt		
PtID		434		
hr		1.500 m		
Def.Chain		10.000 <>		
∆Chain		7.072 m		
∆Offset		m		
Cut		m		
Act. Slp		-:- h:v		
Meas	Dist	Store J		

Description of fields

Field	Option	Description
DefChain	Editable field	Defined chainage for stake out.
∆Chain	Selectable list	Difference between the defined chainage and the measured chainage.
∆Offset	Display only	Horizontal offset between the catch point of defined slope and the measured position.
Cut/Fill	Display only	Vertical offset between the catch point of the defined slope and the measured posi- tion. A cut is above the slope, a fill is below the slope.
Act.Slope	Display only	Measured slope of the reflector position to the hinge point.
Offs.Hng	Display only	Measured offset to the horizontal alignment including offset right and offset left.
∆ H Hinge	Display only	Height difference to the hinge point. The ver- tical offset between the defined height at the current chainage, and the measured position, including the defined height differ- ence.
⊿ Hinge	Display only	Slope distance from the measured point to the hinge point.
Height	Display only	Height value of the measured point.
Act. Ch.	Display only	The measured chainage.
Offs.Aln	Display only	Measured offset to the horizontal alignment excluding offset right and offset left.

	Field	Option	Descript	ion	
	∆ H Aln	Display only	Height di cal offset rent chai excluding	ffere bet nage g the	ence to the alignment. The verti- ween defined height at the cur- e, and the measured position, e defined height difference.
	⊿ Aln	Display only	Slope dis the align	tanc men	e from the measured point to t.
Sign convention	Cut situation				
	P1 d C P1	b P2	ē	P1 P2 a b c d	Measured point Catch point Horizontal alignment Hinge point Cut Δ Offset to catch point
	Fill situation				
	Р2 d	P2 b P1 c	ē	P1 P2 a b c d	Measured point Catch point Horizontal alignment Hinge point Fill Δ Offset to catch point
Next step	Either, pressOr, press ES	s Meas to meas SC to return to th	ure and re ne Setout	corc / Ch	l. eck/Slope values screen.
7.13.7	Check Slope				
Description	The subapp Che about slopes, fo right and height ment is the hing	eck Slope is used or example on a c difference are r ge point.	for as-bu natural su ot entere	ilt ch rface d, th	necks and to get information e. If the parameter offset left/ ne point on the horizontal align-
	a b j	h g d i e	Pl	P1 a b c d e f g h i j	Measured point Horizontal alignment Defined offset Defined height difference Hinge point Actual slope Natural surface Offset to hinge point Offset to alignment Height difference to hinge point Height difference to align- ment

Defined chainage and increment values will not be considered.

B

Slope Check Hinge Val.

🕆 Slope Check Hinge Val. 🕑 I 💦 🛄				⊁!		
Slope	Heig	ht	Align	mt		
PtID					4	34
hr				1.	500) m
Offset					L	.eft<>
Chainage				2.	928	3 m
Offs.Hng				0.	983	3 m
∆H Hinge						- m
Act. Slp					-:-	h:v
Meas	Dist		Stor	Έ	1	1

Description of fields

Offset Chainage	Selectable list	Defined herizontal effect Left Dight on Co
Chainage		ter.
	Display only	Current chainage from measured point.
Offs.Hng	Display only	Offset to hinge. Measured offset to the ho zontal alignment including offset right and offset left.
∆H Hinge	Display only	Height difference to the hinge point. The v tical offset between the defined height at the current chainage, and the measured position including defined height difference
Act. Slp	Display only	The measured slope ratio of the measured point to the hinge point.
Hinge	Display only	Slope distance from the measured point to the hinge point.
Height	Display only	Height value of the measured point.
Offs.Aln	Display only	Measured offset to the horizontal alignme excluding offset right and offset left.
∆ H Aln	Display only	Height difference to the alignment. The vector cal offset between defined height at the corrent chainage, and the measured position excluding the defined height difference.
🚄 Aln	Display only	Slope distance from the measured point to the alignment.

Next step

7.14

P

7.14.1

Description	Traverse is an app used to establish control networks whereby other survey operations such as topographic surveys or point stake outs can be completed. The Traverse methods include 2D Helmert transformation, compass rule and transit rule.
2D Helmert transfor- mation	A Helmert transformation is calculated based on two control points. These must be the start point and the end, or closing, station. Shift, rotation and scale factor will be computed and applied to the traverse. Starting a traverse without an initial backsight measurement will automatically result in a Helmert transformation.
Compass rule	The coordinate misclosure will be distributed with respect to the length of the traverse legs. The compass rule assumes that the biggest error comes from the longest traverse observations. This method is suitable when the precision of the angles and distances are approximately equal.
Transit rule	The coordinate misclosure will be distributed with respect to the coordinate changes in Easting and Northing. Use this method if the angles were measured with a higher precision than the distances.
Traverse step-by-step	1. Start and configure Traverse.
	2. Enter station data.
	3. Select starting method.
	4. Measure a backsight point or go directly to step 5
	5. Measure a foresight point.
	6. Repeat for the number of sets.
	7. Move to the next station.
Traverse options	 It is also possible to observe sideshots and check points during the traverse, however, check points are not included in the traverse adjustment. At the end of the traverse, results are displayed and an adjustment may be calculated if desired.
7.14.2	Starting and Configuring Traverse
Access	1. Select Apps from the Main Menu .
	2. Select Traverse from the Programs Menu .
	3. Complete app pre-settings.

F1 Set Job: .

Only one traverse per job is allowed. If an adjusted or finished traverse is already part of the selected job, then select another job. Refer to "6 Apps - Getting Started".

F2 Set Tolerances: • Use Tolerances: Yes to activate the use of tolerances. Enter limits for horizontal direction (the difference between measured and calculated azimuth to the closing point), distance (the distance between known and measured closing point), and for differences in Easting, Northing and Height. If the adjustment results, or the deviation for a check point, exceed these limits a warning message appears. Press Cont to save the limits and return to the Pre-settings screen.

It is not recommended to start a traverse if the memory is almost full. Doing so, may mean the traverse measurements and results cannot be saved. Accordingly, a message is displayed if less than 10% of the memory is free.

4. Select F4 Start to begin the app.

F

Traverse configuration

Description of	Description of fields			
Field	Option	Description		
Traverse ID	Editable field	Name of the new traverse.		
Desc.	Editable field	Description, if desired.		
Operator	Editable field	Name of the user who will be using the new traverse, if desired.		
Method	B'F'F"B"	All points are measured in face I, then all points are measured in face II in reverse sequential order.		
	B'B"F"F'	The backsight point is measured in face I immediately followed by face II. Other points are measured in alternating face order.		
	B'F'	All points are measured in face I only.		
No. of Sets	Selectable list	Number of sets. Limited to 10.		
Use Face- Tol.	Selectable list	Important when measuring with face I and II. This checks if both measurements are within a defined limit. If the limit is exceeded, a warning message is displayed.		
Face-Tol.	Editable field	The limit that will be used for checking the face tolerance.		

Next step

Press Cont to confirm the traverse configuration and proceed to the Enter Station Data screen.

Measure Traverse -	Description of fields						
Enter Station Data	Field	Option	Description	tion			
	Stat.ID	Editable field	Name of the station	l.			
	hi	Editable field	Height of the instru	ment.			
	Desc. Editable field Description of the station, if desired						
	Every Traverse must start on a known point.						
Next step	Press Cont to confirm station data and proceed to the Traverse - Select screen.						
7.14.3	Measuring	Traverse					
Access	 From the Tra F1w/c sight. Th F2wit F3wit muth. 	verse - Select scr known Backsigh e measurements b h known Backsig h known Azimuth	een select one of the t: Starts the traverse egin to a foresight po ht: Starts the traverse h: Starts the traverse	following: without a known back- bint. with a known backsight. with a user-defined azi-			
Without known backsight	 Start a traverse without a known backsight Start on a known point without an initial measurement to a known backsight. Stop on a known point, or make a final foresight measurement to a known closing point. 						
	If the coordinates of the start station are unknown, the Station Setup app can be run before the traverse. A Helmert transformation will be performed at the end of the traverse. If the traverse is left open, then the calculations are based on the system azi- muth.						
	Tick 40	C2 P3 P2 TP1	C3 C1, C3 C2 TP3 P1-P3 TP1-TP3	Control points Check point Traverse points Topographic points			
With known backsight	Start a traveStart on	erse with a know a known point witl	n backsight n an initial measurem	ent to a known backsight.			

• Stop on a known point and optionally measure to a known closing point.



With known azimuth	Start a traverse with a known azimuth				
	• Start on a known point, aim to any direction (e.g. a tower) and define this direction as the reference. This method is often used to define a 0-direction.				
	• Stop/end then mea to "7.14.	the traverse eithe asure to a known o 5 Closing a Travers	r on a known point or a traverse point and losing point, or leave the traverse open. Refer .e".		
	If using the current system azimuth, for example from Setup , then simply con- firm the suggested Hz-value in the Set Horizontal Angle screen.				
Measure traverse -	Description	of fields			
	Field	Option	Description		
	BS ID	Editable field	Point ID of the backsight point.		
	Remark	Editable field	Description of the backsight point.		
	Stat.ID	Editable field	Name of the station.		
	Depending on the traverse method configured, after the measurement either the Sight Backsight! screen stays active for measuring the backsight point in a second face, or the Sight Foresight screen appears for measuring the fore- sight point.				
Measure traverse - Sight Foresight	Next step				
Sight Foresight	Depending on the traverse method configured, after the measurement either the Sight Foresight screen stays active for measuring the foresight point in a second face, or the Sight Backsight! screen appears for measuring the back- sight point.				
Interrupt a set	To interrupt a Continue wi	set, press ESC to th screen will ap	exit the backsight or foresight screen. The pear.		
Continue with	Field		Description		
	F1 Redo las	st measurement	Returns to last measured point, can be either a backsight or a foresight point. The last measurement is not stored.		
	F2 Redo wł	ole station	Returns to first sight point screen. The data from the last station is not stored.		

	Field	Description		
	F3 Exit Traverse	Returns to the Apps Menu . The traverse stays active and can be continued later. The data from the last station is lost.		
	F4 Back	Returns to the previous screen where ESC was pressed.		
Repetitive loop for the number of sets	Alternating between screens f continues according to the co	or the backsight and foresight measurements nfigured number of sets.		
	The number of sets and the face are indicated in the top right corner of the screen. For example 1/I means set 1 in face I.			
7.14.4	Moving ahead			
Number of defined sets is achieved	When the number of defined displayed automatically. The a set can be accepted or redone	sets is achieved, the Traverse - Select screen is ccuracy of the set measurements is checked. The		
Moving ahead with the traverse	From the Traverse - Select so traverse, or press ESC to redo	creen, select an option to move ahead with the the last station.		
	Field	Description		
	F1 Survey Sideshot	Enables the measurement of standard survey and topographic points. Measured points are stored with a Traverse flag. If the traverse is finally adjusted, these points will be updated.		
		Clo		
		se To exit the screen and returns to the Traverse - Select screen.		
	F2 Move to next Station	Move to the next station. The instrument can either be left on or turned off. If the instru- ment is turned off and then turned on again later, the message Last traverse not yet finished or processed! Do you really want to start a new traverse ? All exist- ing data will be overwritten! will display. Selecting Yes will re-open the Traverse to continue at the new station.		
		The start screen for the next station is similar to the Enter Station Data screen. The point ID of the foresight point of the last station is suggested as station ID automatically.		
		Run through the loop of backsight and fore- sight measurements until the number of sets is reached.		
	F3 Measure Checkpoint	By measuring a check point it is possible to check whether the Traverse is still within cer- tain deviations. A check point is excluded from the traverse calculation and adjustment, however, all measurement data and results observed from a check point are stored.		

Field	Description
	 Enter the name of the check point and the height of the reflector.
	 Press Cont to go to the next screen. Measure the check point. The differences in Easting, Northing and Height are displayed.
	A message will appear if the tolerances defined in the Traverse configuration are exceeded.

Next step

Closing a Traverse

Close the traverse by selecting **Close** in the **Sight Foresight** screen after a backsight point measurement, but before the foresight point measurement.

7.14.5

Access

Close the traverse by selecting **Close** in the **Sight Foresight** screen after a backsight point measurement, but before the foresight point measurement.

Close Traverse...

Field	Description	
F1at Known Station to Known Closing Point	To close a traverse at a known station to a known closing point. Use when setup on the closing station, and the coordinates for the station and the clos- ing point are known. If this method is chosen a distance measurement is mandatory.	
	 Input the data for both points. Measure to the closing point. The results are displayed. 	
F2to Known Closing Point	 To close a traverse to a known closing point. Use when setup on an unknown station and only the coordinates of the closing point are known. 1. Input the data for the point. 2. Measure to the closing point. 3. The results are displayed. 	
F3at Known Station Only	To close a traverse at a known station only.Use when setup on the closing station and the coordinates for it are known.1. Input the data for the closing station.2. The results are displayed.	
F4Leave Open	To leave the traverse open. There is no last traverse station. 1. The results are displayed.	

Next step

Select an option, from the **Close Traverse...** menu to proceed to the **Traverse Results** screen.

Traverse Results

🗂 Traverse Resu	ults 🕑 II	≯ !		
Result1 Resu Traverse ID Start Stn. End Stn. No.of Stn. Total Dist. 1D Accuracy 2D Accuracy	lt2 TRAV 5 23. 1/13 1/2	2_2000 Stn001 Stn001 3 920 m 3.3612 1.9479		
Adjust View ⁻	Tol S-Shot Eı	ndTrav		_
Кеу	Description			
Adjust	To calculate an left open.	adjustment.	. Unavailable when the traverse is	
ViewTol	To view the to	lerances for t	the traverse.	
S-Shot	To measure a s	sideshot.		
EndTrav	To record the r	To record the results and end the traverse.		
Description of	fields			
Field	Option	Description	n	
Traverse ID	Display only	Name of th	ne traverse.	
Start Stn.	Display only	Point ID of	the start station.	
End Stn.	Display only	Point ID of	the end station.	
No.of Stn.	Display only	Number of	stations in the traverse.	
Total Dist.	Display only	Total distan	nce of the traverse.	
1D Accuracy	Display only	Formula:	1 (Length of Traverse	
			Height Misclosure	
2D Accuracy	Display only	Formula:	1 (Length of Traverse	
			I/(Linear Misclosure)	
L of Error	Display only	Length/dista	tance error.	
Azimuth Err.	Display only	Azimuth clo	osure error.	
∆East, ∆North, ∆Height	Display only	Calculated c	coordinates.	

Next step

Press **Adjust** from the **Traverse Results** screen to calculate the adjustments.

Set Adjustment Parameter

🕤 Set Adjustment Paramete 🕑 II 👌 🖭				
Adjust				
No.of Stn.	3			
Azimuth Err.	g			
MiscDistr.	Compass <>			
Height-Distr	Equal <>			
Note:Angles adjusted equally!				
Scale				
Use Scale	No <>			
	Cont			

Description of fields

Field	Option	Description
No.of Stn.	Display only	Number of stations in the traverse.
Azimuth Err.	Display only	Azimuth closure error.
MiscDistr.		For misclosure distribution.
		Angle misclosures are distributed equally.
	Compass	For surveys where angles and distances were measured with equal precision.
	Transit	For surveys where angles were measured with a higher precision than the distances.
Height-Distr	Selectable list	The height error can be distributed equally, by distance or not at all.
Scale	Display only	PPM value defined by the calculated distance between start and end point divided by the distance measured.
Use Scale	Selectable list	Whether to use the calculated ppm.
D !'		c

- Depending on the number of measured points the calculation may take some time. A message is displayed during the processing.
- Adjusted points are stored as fixpoints with an additional prefix, for example point BS-154.B is stored as CBS-154.B.
- After the adjustment, Traverse is exited and the system returns to the **Main Menu**.

Messages

F

The following are important messages or warnings that may appear.

Messages	Description
Memory is nearly full! Do you want to continue ?	This message occurs if less than 10% of the memory is free. It is not recommended to start a traverse if the memory is almost full. Doing so, may mean that the traverse meas- urements and the results cannot be saved.
Current job contains an adjusted Traverse. Select a different job!	Only one traverse per job is allowed. Another job must be selected.

Messages	Description
Last traverse not yet fin- ished or processed! Do you want to continue ?	The Traverse app was quit without closing a traverse. The traverse can be continued on a new station, left unfinished, or a new traverse started and the old traverse data overwritten.
Do you really want to start a new traverse ? All existing data will be over- written!	Confirmation of this message will start a new traverse and the old traverse data will be overwritten.
Redo last station ? Meas- urements of this station will be overwritten!	Confirming returns to the first sight point screen for the previous station measure- ments. The data from the last station is not stored.
Exit Traverse application ? Current station data will be lost!!!	Quitting the app returns to the Main Menu . The traverse can be continued later, but the current station data will be lost.
Out of Tolerance!	The tolerance limits have been exceeded. If not accepted, the calculations can be redone.
Traverse points are re- cal-	An information message displayed while the adjustment is calculated.

F

7.15

Refer to the separate manual "Leica TS03/TS07 Tunnel Application".

8	Favourite	Favourites Overview		
8.1	Overview			
Description	Favourites car	n be accessed by:		
	Кеу	Description		
	*	Opens the Favourites Menu and a function can be selected and activated.		
		Activates the specific function assigned to the key. Any func- tion from the Favourites Menu can be assigned to these keys. Refer to "5.1 Work Settings".		
Favourites	The states of th	The symbol of an unavailable favourite is crossed out.		
	Favourite	Description		
	Â.	Returns to the Main Menu.		
	Home			
	 ⊕, 	Displays the laser plummet and electronic level. Refer to "Level up with the electronic level step-by-step".		
	Level			
	∀ • ★	Refer to "8.2 Target Offset".		
	Offset			
		Deletes the last recorded data block. This can be either a measurement block or a code block.		
	Del.Rec	Deleting the last record is not reversible! Only records recorded in Survey can be deleted.		
	*	Starts coding to select a code from a codelist or enter a new code. Same functionality as the softkey Code .		
	Coding			
		Refer to "5.13 Instrument Protection with PIN".		
	РІМ-ІОСК	Chapters between the two EDM modes. Defer to "E E EDM		
	v²≰ ≌ ∗ NP←→P	Settings".		
	€	Activates/deactivates the visible laser beam for illuminating the target point.		
	Laserpt.	Defer to "0 E EDM Trading"		
	©,	Refer to 8.5 EDM Tracking .		
	EDM Track			
	\mathcal{N}_{\star}	To view EDM Signal reflection value.		
	Sig.Refl.			
	⊥ ei∕	Height Transfer. Refer to "7.2 Station Setup".		
	H-Trans			
Favourite	Description			
------------------	---			
→ ⁸ ★	Refer to "8.3 Hidden Point".			
Hidden Pt				
N 2.00	Refer to "8.4 Check Tie".			
CheckTie				
√_0 B`★	Refer to "8.6 Backsight Check".			
BS-Check				
22	To create a sketch on a virtual piece of paper. Refer to "8.7 SketchPad"			
SketchPad				
\$ *	To deactivate/activate the touch screen. Available for TS07.			
Touch				
Distance	Sets the distance measurement unit. Available for the user keys			

8.2.1 Overview

1.

Description

8.2

This favourite calculates the target point coordinates if it is not possible to set up the reflector, or to aim at the target point directly. The offset values (length, trav. and/or height offset) can be entered. The values for the angles and distances are calculated to determine the target point.



- P0 Instrument station
- P1 Measured point
- P2 Calculated offset point
- d1+ Length offset, positive
- d1- Length offset, negative
- d2+ Trav. offset, positive
- d2- Trav. offset, negative

Access

Press the Favourites key when within any app.

2. Select **Offset** from the **Favourites Menu**. \mathbf{F}_{\star}

Enter offset values

Length Off. Height Off. Mode	2.000 0.000 0.000 Reset after F	D m D m D m REC <>
Default Cylin		Cont
Default	To reset offset	t values to 0
Cylindr	To enter cyling	trical offsets
Field	Option	Description
Trav. Off.	option	Perpendicular offset. Positive if the offset point is to the right of the measured point
Length Off.		Longitudinal offset. Positive if the offset point is further away than the measured point.
Height Off.		Height offset. Positive if the offset point i higher than the measured point.
Mode		Period for which the offset is to apply. The offset values are always reset to 0 when the app is quit.
	Reset after REC	The offset values are reset to 0 after the point is saved.
	Cylindr	The offset values are applied to all further

8.2.2 Cylindrical Offset

Description

Determines the coordinates of the centre point of cylindrical objects and their radius. The horizontal angle to points on both the left and right sides of the object are measured, and the distance to the object as well.



- PO Instrument station
- P1 Centre point of cylindrical object
- Hz1 Horizontal angle to a point on the left side of the object
- Hz2 Horizontal angle to a point on the right side of the object
- d Distance to the object in the middle between Hz1 and Hz2
- R Radius of cylinder
- α Azimuth from Hz1 to Hz2

Press **Cylindr** from the **Offset** screen.

Cylindrical Offset

Cylindrical Offse	et 🕑 I 🗞 💷
Polar	
Hz Left	52.000 g
Hz Right	95.001 g
	m
ΔHz	
PrismOffset	0.000 m

HzLeft | HzRight | Meas | 🖡

Кеу	Description
HzLeft	To trigger measurement for the left side of the object.
HzRight	To trigger measurement for the right side of the object.

Description of fields

•		
Field	Option	Description
Hz Left	Display only	Measured horizontal direction to the left side of the object. Using the verticalhair, aim at the left side of the object, then press HzLeft .
Hz Right	Display only	Measured horizontal direction to the right side of the object. Using the verticalhair, aim at the right side of the object, then press HzRight .
Δ Hz	Display only	Deviation angle. Rotate the instrument to aim in the direction of the centre point of the cylindrical object, such that Δ Hz is zero.
PrismOffset	Editable field	Prism offset distance between the centre of the prism and the surface of the object to be measured. If the EDM mode is Non-Prism, the value is set to zero automatically.

Next step

Once $\Delta \textbf{Hz}$ is zero, press Meas to complete the measurement and display the results.

Cylindrical Offset Result

句 Cylindr	ical Of	fset Res	ult 🕑 I	₿ 📑
Result				
PtID				1
Desc.				
East			65	5.178 m
North			13	3.689 m
Height			2	2.624 m
Radius			12	2.267 m
Finish				New

Кеу	Description
Finish	To record results and return to the main Offset screen.
New	To measure a new cylindrical object.

Description of fields

Field	Option	Description
PtID	Editable field	Defined point ID of the center point.
East	Display only	Easting coordinate of the centre point.
North	Display only	Northing coordinate of the centre point.
Height	Display only	Height of the point measured with the reflector.
		This is not the calculated height of the centre point.
Radius	Display only	Radius of the cylinder.

8.3

Hidden Point

Description

This favourite is used for measurements to a point that is not directly visible, using a special hidden point rod.



- P0 Instrument station
- P1 Hidden point
- 1-2 Prisms 1 and 2
- d1 Distance between prism 1 and the hidden point
- d2 Distance between prism 1 and 2

- 1. Press the Favourites key when within any app.
- 2. Select **Hidden Pt** from the **Favourites Menu**.
- 3. If necessary, press **Rod/EDM** to define the rod or EDM settings.

Hidden Point - Rod Settings

Description of fields

⇒°∓

Field	Option	Description
EDM Mode	Selectable list	Changes the EDM Mode.
Prism Type	Selectable list	Changes the prism type.
PrismConst.	Editable field	Displays the prism constant.
Rod Length	Editable field	Total length of hidden point rod.
Dist. R1-R2	Editable field	Spacing between the centres of the prisms R1 and R2.
Meas. Tol.	Editable field	Limit for the difference between the given and measured spacing of the prisms. If the tolerance value is exceeded, a warning is issued.

Next step

In the **Hidden Point** screen, measure to the first and second prisms using **Meas** and the **Hidden Point Result** screen is displayed.

Hidden Point Result

Displays Easting, Northing and Height coordinates of the hidden point.

너 Hidden Point R	lesult	🕑 I 鶨 💻
Result		
PtID		408
Desc.		
East		52.868 m
North		8.861 m
Height		5.475 m

New	End

Кеу	Description
New	To return to the Hidden Point screen.
End	To record results and return to the app where the Favourites key was selected.

8.4

Check Tie

Description

This favourite calculates and displays the slope and horizontal distance, height difference, azimuth, grade, and coordinate differences between the last two measured points. Valid distance measurements are required for the calculation.



1. Press the Favourites key when within any app.

2. Select **CheckTie** from the **Favourites Menu**. 12

Check Tie

Description of fields			
Field	Option	Description	
Bearing	Display only	Difference in bearing between the two points.	
Grade	Display only	Difference in gradient between the two points.	
4	Display only	Difference in horizontal distance between the two points.	
	Display only	Difference in slope distance between the two points.	
Δ	Display only	Difference in height between the two points.	

Messages

The following are important messages or warnings that may appear.

Messages	Description	
Two measurements	The values cannot be calculated as there are	
required!	less than two valid measurements.	

8.5	EDM	EDM Tracking		
Access	1.	Press the Favourites key when within any app.		
	2.	Select EDM Track from the Favourites Menu . ®		
Description	This fannew s	This favourite activates or deactivates the tracking measurement mode. The new setting is displayed for about one second and then set. This favourite can		

only be activated from within the same EDM mode and prism type. The following options are available.

	EDM Mode Tracking mode OFF! <=> Tracking mode ON!			
	Prism Precise+ <=> Tracking / Precise&Fast <=> Tracking			
	Non-Prism NP-Precise <=> NP-Tracking			
	The last active measurement mode remains set when the instrument is switched off.			
8.6	Backsight Check			
Description	This favourite enables the user to remeasure to the point(s) used for Station Setup. This is useful to check if the station position is still correct after measur- ing some points.			
Access	1. Press the Favourites key when within any app.			
	2. Select BS-Check from the Favourites Menu .			
Backsight Check	This screen is exactly the same as the Setout screen, except that the available PtIDs are restricted to the points used for the last orientation. Refer to "7.4 Setout" for information about the screen.			
	When setting up a station by local resection, check the coordinate system of the points used from the list.			
8.7	SketchPad			
Description	The field sketch functionality is used to create a sketch on virtual paper.			
	The sketch is stored as image in bmp format. The bmp file is stored in the \JOBS\IMAGES folder of the internal memory. The predefined template is opti- mised for A4 printout.			
Access	1. Press the Favourites key when within any app.			
	 Select SketchPad from the Favourites Menu. 			
Notes	 Notes ☑ I % I ↓ II ☑ ☑ ☑ ☑ ☑ ☑ ☑ Back Store 			

Кеу	Description
Back	To return to the last active screen.
Store	To store and link the field sketch.

Overview of keys, softkeys and icons for sketching

_

_

lcon	Key or Softkey	Description
<u>گ</u> ا	-	To activate sketching. The icon 🥹 is displayed:
ك ل	-	To quit sketching. The icon \Im is displayed.
æ	-	To change the line colour. Tap the icon to open a window displaying line colours for selection. The selected line colour is remembered.
=	-	To change the line width. Tap the icon to open a window displaying line widths for selection. The selected line width is remembered.
←	-	To undo all changes since the last saving.
⊕ `	Zoom +	To zoom into the image.
Q	Zoom -	To zoom out of the image.

9	Coding		
9.1	Coding		
Description	Codes contain information about recorded points. With the help of coding, points can be assigned to a particular group simplifying later processing. Codes are stored in codelists, with each codelist supporting a maximum of 200 codes.		
Creating a codelist	 A codelist can be created: on the instrument: Select Manage from the Main Menu. Select Codes from the Manage Menu. in Leica Infinity. 		
	Codelists can be imported and exported via USB memory stick/SD card or cop- ied as file between instrument and PC. Refer to "12.3 Importing Data" and "12.2 Exporting Data".		
	Number of codes supported in codelists:Up to 200, when created using Leica Infinity.		
GSI coding	Codes are always stored as free codes (WI41-49), that means that codes are not directly linked to a point. They are stored before or after the measurement depending on the setting made.		
	A code is always recorded for each measurement as long as the code is displayed in the Code: field. For a code not to be recorded, the Code: field must be cleared. This can be set to occur automatically. Refer to "5.1 Work Settings".		
Access	 To select a code: On Work Settings, Screen page, configure the survey display so that a Code field is shown. In the survey display, Highlight the Code field. Use the right/left navigation key to scroll through the codes. Type in a code. After entry, the firmware searches for a matching code name, and displays these in the code field. If a matching code name does not exist, then a new code name is created. Press ENTER to open the codelist. To access a list of codes: Press ↓ Code in Survey. 		
Coding	Code Enter new code Code Q-Code Info 1 Info 2 Info 3 Cont		
	Key Description		
	Cont To save the changes.		

Description	of	fields
-------------	----	--------

Field	Option	Description
Code	Editable field	Code name.
Q-Code	Editable field	Two digit quick code assigned to the code. Refer to "9.2 Quick Coding".
Desc.	Editable field	Additional remarks.
Info 1 to Info 8	Editable field	More information lines, freely editable. Used to describe attributes of the code.

Code

Code 1/7	🕑 I 将 🛄
General	
C1	
C2	
C3	
C4	
C5	
C6	
C7	
New Attrib.	Cont Cont

Кеу	Description			
New	To create a new code.			
Attrib.	To add up to 8 attributes with up to 16 characters. Existing code attributes can be overwritten with the following exceptions:			
	The codelist editor of Leica Infinity or a special TS Tools col- lection can assign a status to the attributes. Attributes with status "fixed" are write-protected. They cannot be overwrit- ten or edited.			
	For attributes with status "Mandatory" an input or a confir- mation is required. Attributes with status "Normal" can be edited freely.			
	The *.cls in the \CODES folder of the USB stick or SD card is not changed.			
Edit	To edit quick code, description and attributes.			
Description of columns				
Column	Description			
First column	Code name			
Second col- umn	Description of the code			
Ouick Codir	ισ			

9.2

Description

Using quick coding, a predefined code can be called directly via the keypad on the instrument. The code is selected by entering a two-digit number, the measurement is then triggered and the measured data and code saved.

A total of 99 quick codes can be assigned.

The quick code number can be assigned when the code is created in the **Cod-ing** screen, in the Codelist Manager in Leica Infinity or a special TS Tools collection, or it is assigned in accordance with the order in which the codes were entered, for example, 01 -> first code in the code list ... 10 -> tenth code in the code list.

Access	1. Select Apps from the Main Menu .				
	2.	Select Survey from the	ne Programs Menu .		
	3.	Press JQ-Code .			
Quick coding step-by-	1. Press Q-Code .				
step	2.	Enter a two-digit nun	nber on the keypad.		
	A two-digit code must always be entered on the keypad even if only a one-digit code was assigned.				
	For example: 4 -> enter 04.				
	 The code is selected, the measurement triggered and the measured data and code saved. The name of the selected code is displayed after the measurement. 				
	4.	4. Press JQ-Code again to end quick coding.			
Messages	The following are important messages or warnings that may appear.				
	Mes	sages	Description		
	Canr	not edit attribute!	Attribute with fixed status cannot be changed.		
	No c	odelist available !	No codelist in memory. Manual input for code and attributes are called automatically.		
	Code	e not found!	No code is assigned to the entered number.		

10	MapView Interactive Display Feature		
10.1	Overview		
Description	MapView is an interactive display feature embedded in the firmware. MapView provides a graphical display of the survey elements which allows for a better overall understanding of how the data being used and measured relates to each other.		
	Depending on the application and where in the application MapView is accessed from, different functionality is available.		
	The displayed data in all modes of MapView can be shifted by using both the arrow keys and the touchscreen.		
10.2	Accessing MapView		
Description	The MapView interactive display feature is provided as a page within applica- tions. It is accessed through the application itself. Depending on the applica- tion and from where in the application MapView is accessed, different MapView modes are available.		
Access	To view points on a map:		
	In Survey , change to the Map page.		
	To select points from a map - for apps where points can be selected from the database:		
	Press Map in the screen where points must be selected. Use the touch screen to select points.		
10.3	Configuring MapView		
Access	1. Select Settings from the Main Menu .		
	2. Select Screen from the Settings Menu.		
	 Press To scroll through the screens of available settings. 		
Access from the MapView toolbar	For TS07: Tap the icon on the MapView toolbar.		

10.4	MapView	Components
10.4.1	Screen Are	a
Standard screen	a Survey Survey b + 13 4 Meas 016230.001_en	Map •443 •443 •443 •443 •443 •443 •443 •443 •443 •443 •443 •443 •443 •443 •443 •443 •443 •443 •445 •a North arrow b Scale bar c Toolbar
Scale bar	Symbol	Description
	←120→+	Scale of the current screen. The minimum is 0.1 m. There is no maximum for the zoom but the scale cannot display val- ues greater than 99000 m. In this case the value displayed will be >99000 m.
North arrow	Symbol	Description
	↑ N	North arrow. North is always orientated towards the top of the screen.
Toolbar	Symbol	Description
	+ € O d r &	Icon toolbar. Refer to "10.4.2 Keys, Softkeys and Toolbar" for more information about the functionality of the icons in the toolbar.
Prism	Symbol	Description
	Ţ	Measured position. The orientation of the instrument is shown as dotted line.
Instrument station	Symbol	Description
	9	Position of the instrument station.
10.4.2	Keys, Soft	keys and Toolbar
Description	Standard fun View.	ctionality is provided by softkeys, keys and a toolbar within Map-

The softkeys are available regardless of the mode in which MapView was accessed and always perform the same functions.

On the right side of the screen, a toolbar with icons is available. Some functions of the toolbar can also be performed by using a softkey or key instead. Refer to the following table for a description of the toolbar functions and their respective softkey/key equivalents, if available.

Overview of keys, softkeys and icons

The softkeys described in this table are standard on all MapView screens. For descriptions of mode-specific softkeys, see appropriate chapters.

lcon	Key or Softkey	Description
4 ↓ ↓	Fit	The fit icon fits all displayable data, according to filters and the map configuration, into the screen area, using the largest possible scale.
⊕ `	Zoom +	To zoom into the map.
Q	Zoom -	To zoom out of the map.
Q	-	The windowing icon zooms to a specified area window. An area window can be drawn by dragging the stylus on the screen in a diagonal line to make a rectangular area or by tapping twice on the screen to define diagonally opposite corners of a rectangular area. This action causes the screen to zoom to the selected area.
P [₩] 4	Ctr.Tgt	To centre the target. Refer to "5.1 Work Set- tings".
	Ctr.St.	To centre the instrument. Refer to "5.1 Work Settings".
۲ <u>۵</u> ۲	-	To configure MapView. Refer to "10.3 Config- uring MapView".
-	Tap on screen with stylus, hold and move OR Left/right/up/ down arrow key	To move the view of a map up and down as well as left and right. This is particularly use- ful when you have zoomed in on a view, and want to move the view around to see other areas of interest.

10.4.3	Point Symb	Point Symbols	
Symbols	Symbol	Description	
		Fixpoint. Show in Map: Fixpoints or Show in Map: Meas & Fixpts must be selected in Screen & Audio Settings, Map page.	
		Fixpoint active	

Symbol	Description
V	Calculated station
	Station active
•	Measured point. Show in Map: Measurements or Show in Map: Meas & Fixpts must be selected in Screen & Audio Settings, Map page.
0	Measured point active

_			
10.5	Selecting Points		
Selecting a point	Availab	le for TS07.	
using the touch	1.	Press Map in the screen where points must be selected.	
screen step-by-step	2.	Tap on the point to be selected.	
	- B	When there are multiple points within the same area and the precise selection is unclear, tapping on the point will access Points Found .	
	3.	Points Found	
		The ID and the type of the points within range of the point selection is displayed.	
		Select the desired point.	
	ß	View to display the coordinate and job details of the selected point.	
	4.	Cont returns to previous screen with the focus on the selected point.	

11	Imaging & S	Sketching
11.1	Screenshot	
Description	 Screenshots of support cases The images composition 	can be taken from the display as additional information in s. an be linked to the station or to points stored in the job.
Requirements	 A TS07 must be used. In Work Settings, General page, set USER Key 1: Screenshot or USER Key 2: Screenshot. 	
Access	Press a user key configured with the option Screenshot .	
Screenshots	Screenshots	I 14:23 age Survey Secturings New Job € C Store
	KeyIBackIStoreIStoreI	Description To return to the last active screen. To store the screenshot with or without sketch. Decide if the screenshot is stored with the station, the last stored point, a selected point or without link.
	Key I Back 1 Store 1 Sketching	Description To return to the last active screen. To store the screenshot with or without sketch. Decide if the screenshot is stored with the station, the last stored point, a selected point or without link.
11.2 Description	KeyIBackTStoreTSketchingAvailable for TS07	Description To return to the last active screen. To store the screenshot with or without sketch. Decide if the screenshot is stored with the station, the last stored point, a selected point or without link.
 11.2 Description	KeyIBackTStoreTStoreTSketchingA sketch can be of	Description To return to the last active screen. To store the screenshot with or without sketch. Decide if the screenshot is stored with the station, the last stored point, a selected point or without link. To selected point or mage taken from any screen.
11.2 Description	KeyIBackTStoreTStoreTSketchingAvailable for TS07A sketch can be oThe image with the together with the Img_ddmmyy_hhm	Description To return to the last active screen. To store the screenshot with or without sketch. Decide if the screenshot is stored with the station, the last stored point, a selected point or without link. The selected point or without link is stored by pressing Store . The sketch is stored by pressing Store . The sketch is stored by pressing Store . The sketch is stored by pressing store.
11.2 Description Access step-by-step	Key I Back 1 Store 1 Back 1 Store 1 Store 1 Store 1 Store 1 Store 1 Store 1 </th <th>Description To return to the last active screen. To store the screenshot with or without sketch. Decide if the screenshot is stored with the station, the last stored point, a selected point or without link. To everlaid on an image taken from any screen. The sketch is stored by pressing Store. The sketch is stored e image in bmp format. File naming: The screenshot is already stored and possibly linked)</th>	Description To return to the last active screen. To store the screenshot with or without sketch. Decide if the screenshot is stored with the station, the last stored point, a selected point or without link. To everlaid on an image taken from any screen. The sketch is stored by pressing Store . The sketch is stored e image in bmp format. File naming: The screenshot is already stored and possibly linked)
11.2 Description Access step-by-step	Key I Back 1 Store 1 Store 1 Sketching 1 Available for TS07 A sketch can be o The image with the logether with the lmg_ddmmyy_hhm In data manager 1. In the M	Description To return to the last active screen. To store the screenshot with or without sketch. Decide if the screenshot is stored with the station, the last stored point, a selected point or without link. The selected point or without link. The sketch is stored by pressing Store . The sketch is stored a image in bmp format. File naming: The screenshot is already stored and possibly linked) ain Menu, select the Manage page.
11.2 Description Access step-by-step	Key I Back 1 Back 1 Store 1 Store 1 Sketching 1 Available for TS07 A sketch can be o The image with the logether set to the logether with the logether set to the lo	Description To return to the last active screen. To store the screenshot with or without sketch. Decide if the screenshot is stored with the station, the last stored point, a selected point or without link. Y. Y. overlaid on an image taken from any screen. ne sketch is stored by pressing Store. The sketch is stored e image in bmp format. File naming: mment (the screenshot is already stored and possibly linked) ain Menu, select the Manage page. crShots.
11.2 Description Access step-by-step	Key I Back 1 Back 1 Store 1 Store 1 Store 1 Store 1 Sketching 1 Available for TS07 A sketch can be o The image with the logether set of the set of th	Description To return to the last active screen. To store the screenshot with or without sketch. Decide if the screenshot is stored with the station, the last stored point, a selected point or without link. r. r. werlaid on an image taken from any screen. ne sketch is stored by pressing Store. The sketch is stored image in bmp format. File naming: ment (the screenshot is already stored and possibly linked) ain Menu, select the Manage page. crShots. job.
11.2 Description Access step-by-step	KeyIBack1Store1Store1Store1SketchingAvailable for TS07A sketch can be oThe image with the together with the lmg_ddmmyy_hhmIn data manager1.In the M2.Select So3.Select a4.Press Co	Description To return to the last active screen. To store the screenshot with or without sketch. Decide if the screenshot is stored with the station, the last stored point, a selected point or without link. To store the screenshot is stored with the station, the last stored point, a selected point or without link. To werlaid on an image taken from any screen. The sketch is stored by pressing Store. The sketch is stored image in bmp format. File naming: https://www.screenshot. The screenshot is already stored and possibly linked) ain Menu, select the Manage page. crShots. job. out.

When taking a new screenshot

- 1. Press a user key configured with the option **Screenshot**.
- 2. Click the icon 51 in the toolbar.

Overview of keys, softkeys and icons for sketching

•	lcon	Key or Softkey	Description
	ػۣڸ	-	To activate sketching. The icon 🥹 is displayed:
	<u>ک</u> ا	-	To quit sketching. The icon ⅔ is displayed.
	2	-	To change the line colour. Tap the icon to open a window displaying line colours for selection. The selected line colour is remembered.
	≡	-	To change the line width. Tap the icon to open a window displaying line widths for selection. The selected line width is remembered.
	←	-	To undo all changes since the last saving.
	⊕ 、	Zoom +	To zoom into the image.
	Q	Zoom -	To zoom out of the image.

11.3	Image	Image Management	
Access	1.	In the Main Menu, select the Manage page.	
	2.	Select ScrShots .	
	3.	Select a job.	
	4.	Press Cont .	

Screenshots



Кеу	Description
Prev	To display the previous image in the list of images. Available unless the beginning of the list is reached.
Next	To display the next image in the list of images. Available unless the end of the list is reached.
Cont	To store the image with the added link or a sketch created. If no sketch was created, then the image is not stored a sec- ond time to avoid a loss of quality.

Кеу	Description
Delete	To delete the image and all its links.
DelLnk	To delete only a link but not the image. Links can be selected from a list.
Info	To show the file name, job, creation date, modification date and links.
List	To list all images stored in the selected job.

12	Data Management		
12.1	Manage		

Select the Manage page in the Main Menu.

Job name, Manage page

The **Manage** page contains all functions for entering, editing, checking and deleting data in the field.

J101		❷ I ≱ ≞
Start N	lanage	
7	⁸ 🛕	9 UUU
Job	Fixpoints	Meas.Data
01	⁰²	>
Data Transfe	r Del.Data	

Menu item	Description
Job	To select, view, create and delete jobs. Jobs are a summary of data of different types, for example, fixed points, measure- ments or codes. The job definition consists of the job name and user. The system generates time and date at the time of creation.
A Fixpoints	To view, create, edit and delete fixpoints. Valid fixed points contain at least the point ID and the coordinates E, N or H. To select a code from the existing codelist. To view all screenshots linked to the fixpoint.
w ^w Meas.Data	 To view, edit and delete measurement data. Measurement data available in the internal memory can be searched for via a specific point search, or by viewing all points within a job. The PtID, hr, code and code details can be edited. If the details of a point have been edited, any new calculations will use the new point details. However, any previously stored calculation results based on the original coordinates of the point will not be updated.
Data Trans-	To export and import data. Refer to "12.2 Exporting Data".
X Del.Data	To delete individual jobs, fixpoints and measurements of a specific job or all jobs in the memory.Image: Constraint of the memory cannot be undone. After confirming the message all data is permanently deleted.
	To view, delete, rename and create folders and files stored on the USB memory stick. Only available if a USB memory stick is inserted.

Data Management

Menu item	Description
USB-Stick	Refer to "12.4 Working with a USB Memory Stick"and "B Directory Structure".
	To view, delete, rename and create folders and files stored on the SD card.
SD Card	
	To view, delete, rename and create folders and files stored on the internal memory. The internal memory has same
Int. Memory	folder structure like USB stick.
ĕ	To view, create, edit and delete codes. To each code a description and a maximum of 8 attributes with up to 16
Codes	characters each can be assigned.
	To view and delete data format files.
Formats	
ScrShots	To view, delete, link, unlink, sketch or view information of screenshots taken and stored. Refer to "11.2 Sketching" for sketching.

12.2 **Exporting Data**

Description

Job data, format files, configuration sets and codelists can be exported from the internal memory of the instrument. Data can be exported to:

- USB memory stick •
- SD card
- Configured interface (Bluetooth, RS232 serial, WLAN)

USB memory stick, SD card

A USB memory stick or SD card can be inserted and removed. No additional software is required for the transfer.

RS232 serial interface

A receiver, such as a laptop, is connected to the RS232 port. The receiver requires Leica Infinity or another third-party software.

If the receiver is too slow in processing data the data could be lost. F With this type of data transfer the instrument is not informed about the performance of the receiver (no protocol). Therefore the success of this type of transfer is not checked.

XML Export

The exporting of XML data has some special requirements.

- XML standards do not allow a mix of imperial and metric measurement systems. When exporting XML data, all measurements will be converted to the same measurement system as set for the distance unit. For example, if the distance unit is set to a metric unit (metre), the pressure and temperature units will be converted to metric units as well, even if they are set to imperial units on the instrument.
- The angle unit MIL is not supported by XML. When exporting XML data, measurements using this unit are converted to dec.deg.
- The distance unit ft-in/16 is not supported by XML. When exporting XML data, measurements using this unit are converted to feet.
- Points with Height coordinates only, are not supported by XML. These points are given the E and N values of O.

Access 1. Select the Ma

1.	Select the Manage page in the Main Menu .
2.	Select Data Transfer .
3.	Select Export .

Export

Export	© I 将 📮
Select	
То	USB-Stick
Data Type	Measurements <>
Job	Single Job <>
Select Job	J101 <>

Back | Search | List | Cont

Кеу	Description
Search	To search for jobs or formats within the internal memory.
List	To list all jobs or formats within the internal memory.

Description of fields

<u>t</u>

Field	Option	Descriptio	on		
То	Selectable list	Select the memory device.			
Data Type		Data type to be transferred Data transfer is possible to:			
		USB stick	SD card	Internal memory	RS232 interface
	Measure- ments	\checkmark	\checkmark	\checkmark	\checkmark
	Fixpoints	\checkmark	\checkmark	\checkmark	\checkmark
	Meas & Fixpts	\checkmark	\checkmark	\checkmark	\checkmark
	Road Data	\checkmark	\checkmark	\checkmark	-
	Code	\checkmark	\checkmark	\checkmark	-
	Format	\checkmark	\checkmark	\checkmark	-

	Field		Option	Descriptio	on		
			Configura- tion	\checkmark	\checkmark	\checkmark	-
			Backup	\checkmark	\checkmark	\checkmark	-
			Images	\checkmark	\checkmark	\checkmark	-
	Job		Selectable list	Select whe or a single	ther to ex job data	kport all jot file.	o-related data
	Selec	t Job	Selectable list	Displays th file.	ne selected	d job or roa	ad alignment
	Form	at	Selectable list	If Data Ty Select whe gle format	pe: Forma ether to ex	at . kport all for	mats or a sin-
	Form Name	at 2	Editable field	If Format : Name of t	Single Format	ormat. to be tran	sferred.
Export data step-by-	1.	Press	Cont in the Expo	ort screen a	fter select	ing the exp	port details.
step	2.	lf expo the de	ort is to a USB me esired file location	emory stick, n and press	SD card o Cont .	or internal i	memory, select
	3.	Select	the data format,	, enter the f	ile name a	and press (Cont or Send.
		DXF:			To expor ity. Fixed	rt data usir d format (X	ıg Leica Infin- :/Y/Z).
		DXF Ci	ustom:		To expor stick. Th definabl	rt data usir e DXF form e. Continue	ng an USB nat is user e with step 5
		ASCII:			America Informat format. bles and during ir 4	n S tandarc tion Interch Use and or I delimiter nport. Con	l C ode for hange. Free der of varia- can be defined tinue with step
		GSI:			Leica G eo format. predefin "5.3 Dat explanat	o S erial Int Select betv ed formats a Settings' tion of the	erface. Fixed veen three 5. Refer to 7 for an formats.
		XML:			E x tensib XML is a World W Fixed for	ole M arkup recommer 'ide Web Co rmat.	L anguage. Indation of the Insortium.
		HeXMI	L:		Hexagor Languag to the La tains ad which is relevant a geospa	n Extensible ge. HeXML andXML for ditional inf missing in for the dar atial enviro	e M arkup is an extension rmat. It con- ormation, LandXML and ta exchange in nment.

	4.	 Config. Delimiter Unit Incl. Header Data Fields PtID <> Height <> Code <> North <> Height <> Code <> 	
	5.	Ceneral Symbol Label Export Points All <> Show Identifier Yes <> Export Images No <> Dimension 2D <>	For data format is DXF Cus- tom: Define the point type export, image export, the X/Y/Z export, the size of the point symbols and the labelling plus coloring of additional point information. Define if identifiers are included for additional point information. Press Cont .
		Examples:	
		exported points without labels.	+
		Exported points with labels:	P1105.000.103.000 Tree Deciduous Tree 100.000 1.25. H
		Exported points with labels and identifier:	Pt10: Pt. 100000 Code: Tree, Code: Besc: Beckbuous TreeH: 100000 Monitor: 163, officiants 2: 1
	6.	A message will display confirming	the successful export of data.
- B	Measure instrume chronolo XML dat memory ies betw formanc	ement data are stored in chronologic ent.The XML data format and other ogically but sort the data in separate a format or other format files, the i r until the required data is found. The veen formats. The GSI data format h re.	cal order – line by line - on the format files do not output data e blocks. During the data export in nstrument has to search the whole erefore, the data transfer time var- las the best transfer speed-per-
- 	A '+', '-', in ASCII values a	'.' or alphanumerical characters sho files. These characters can also be p nd if so, will generate errors where	ould not be used as delimiter values part of the point ID or coordinate they occur in the ASCII file.
	Road Da only ava memory	ata, Format and Backup data type ilable for data exports to a USB mer . It is not possible via the RS232 ser	s, and the ASCII data format, are nory stick, SD card and internal rial interface.
	All jobs, folder cr	formats, codelists and configuration reated on the USB memory stick. Th	ns will be stored in the backup e job data will be stored as individ-

ual database files for each job, which can then be imported again. Refer to "12.3 Importing Data".

Exportable job data formats Job data can be exported from a job in dxf, gsi, csv and xml file types, or any other user-defined ASCII format. A format can be defined in the Format Manager of Leica Instrument Tools.

RS232 example job data output

Within the **Data Type** setting **Measurements**, a data set could be shown as follows:

11+00000D19	21022+16641826	22022+09635023
3100+00006649	5816+00000344	8100+00003342
8200-00005736	8300+00000091	8710+00001700

GSI-IDs		GSI-IDs continued		
11	PtID	41-49	Codes and attributes	
21	Horizontal direction	51	ppm [mm]	
22	Vertical angle	58	Prism constants	
25	Orientation	81-83	(E, N, H) Target point	
31	Slope distance	84-86	(E, N, H) Station point	
32	Horizontal distance	87	Reflector height	
33	Height difference	88	Instrument height	

Importing Data

Description

12.3

Data can be imported to the internal memory of the instrument via USB memory stick, SD card or internal memory.

Importable data formats

When importing data, the instrument automatically stores the file in a directory folder based on the file extension. The following data formats can be imported:

Data Type	File extension	Recognised as
GSI	.gsi, .gsi (road)	Fixpoints
DXF	.dxf	Fixpoints
LandXML	.xml	Fixpoints
ASCII	any ASCII file extension e.gtxt	Fixpoints
Format	.frt	Format file
Codelist	.cls	Codelist file
Configuration	.cfg	Configuration file
Backup	.db	Backup of fixpoints, meas- urements and configuration

1.	Select	the	Manage	page	in	the	Main	Menu	•
----	--------	-----	--------	------	----	-----	------	------	---

2.	Select Data Transfer .
3.	Select Import.

Import

니 Import	🕑 I 将 ⋿
Select	
From	Internal Memory <>
To	Instrument
FIIE	Single File ()

Back	Cont

Description of fields

	Field	Option	Description	
	From	Selectable list	Select the memory device.	
	То	Instrument	Only option	
	File	Selectable list	Import a single file or a backup folder.	
	 Impor code delete A back not ch ted, it impor sion, si 	ting a backup folder w lists on the instrument ed. kup can only be impor hanged by a firmware can happen that a ba ted. In this case, dowr save the data in the w	ill overwrite the existing configuration file and t, and all existing formats and jobs will be ted if the instrument database structure was update. If the instrument firmware was upda- ockup created before the update cannot be ngrade the firmware to the previous used ver- vay required and then reload the new firmware.	
Import data step-by- step	1. P t	Press Cont in the Impo he memory device.	ort screen to proceed to the file directory of	
	2. S	elect the file or backu	p folder to be imported and press Cont .	
	3. F tr v s a f l l l r F P	For a file: Define the Job name for the imported file, and, if requested, the file definition and layers, and press Cont to import. If a Job with the same name already exists in the internal memory, a message will appear with the options to overwrite the existing job, attach the new points to the current job, or rename the job for the file being imported. If new points are attached to the current job, and the same point ID already exists, the existing point ID will be renamed with a numerical suffix. For example, PointID23 will be renamed to PointID23_1. The maximum renamed suffix is 10, e.g. PointID23_10. For a backup folder: Take note of the warning message displayed and press Cont to proceed and import the folder.		



If the file is an ASCII file, the **Define ASCII Import** screen will appear. Define the delimiter value, the units and the data fields of the file and press **Cont** to continue.

5. A message will display once the file or backup folder has been successfully imported.

P

A '+', '-', '.' or alphanumerical characters should not be used as delimiter values in ASCII files. These characters can also be part of the point ID or coordinate values and if so, will generate errors where they occur in the ASCII file.

12.4 Working with a USB Memory Stick

B

- P

- Keep the USB memory stick dry.
- Use it only within the specified temperature range, -40°C to +85°C (-40°F to +185°F).

Always return to the Main Menu before removing the USB memory stick.

• Protect the USB memory stick from direct impacts.

Failure to follow these instructions could result in data loss and/or permanent damage to the USB memory stick.

Whilst other USB memory sticks may be used, Leica Geosystems recommends Leica industrial grade USB memory sticks and cannot be held responsible for data loss or any other error that may occur when using a non-Leica USB memory stick.

Insert a USB memory stick step-by-step



- 1. Open the compartment lid.
- 2. The USB host port is located underneath the top edge of the compartment.
- 3. Insert the USB memory stick into the USB host port.

	4.	The cap of a Leica industrial grade USB memory stick can be stored on the underside of the compartment lid.
	5.	Close the compartment lid and turn the knob to lock the compart- ment closed.
Format an USB mem- ory stick step-by-step	Format comple deleted	ting the USB memory stick before starting to store data is required if a etely new USB memory stick is used, or if all existing data needs to be d.
		The formatting function on the instrument only works for Leica USB memory sticks. All other USB memory sticks should be formatted on a computer.
		Despite an automatic defragmentation, the USB memory stick gets fragmented after a while. Please format the USB memory stick peri- odically to maintain the instrument performance.
	1.	Select the Manage page in the Main Menu.
	2.	Select the USB-Stick .
	3.	Press 🖡 Format.
	4.	A warning message will appear.
		By activating the format command all data will be lost. Make sure that all important data has been backed up before formatting.
	5.	Press Yes .
	6.	A message will display once the formatting is completed. Press Cont .
- 12.5	Work	ing with the SD Card
5	KeUsDcPro	ep the card dry. e it only within the specified temperature range. o not bend the card. otect the card from direct impacts.
- -	Failure damag	to follow these instructions could result in data loss and/or permanent e to the card.
Insert a SD card step- by-step	- dama	



The SD card is inserted into a slot inside the compartment below the Leica logo.

1. Turn the knob on the compartment cover to unlock.

2. Open the lid of the compartment.

	3.	To insert the SD card, slide it firmly into the SD slot until it clicks into position.		
		The card must be held with the contacts at the top and facing toward the instrument.		
		Do not force the card into the slot.		
	4.	Close the lid and turn the knob to lock.		
	5.	To remove the SD card, gently press on the top of the card to release it from the slot.		
Format an SD card step-by-step	Format new SI	ting the SD card before starting to store data is required if a completely Cord is used, or if all existing data needs to be deleted.		
	1 1 1	The formatting function on the instrument only works for Leica SD cards. All other SD cards should be formatted on a computer.		
		Despite an automatic defragmentation, the SD card gets fragmented after a while. Please format the SD card periodically to maintain the instrument performance.		
	1.	Select the Manage page in the Main Menu.		
	2.	Select the SD Card.		
	3.	Press 🖡 Format.		
	4.	A warning message will appear.		
		By activating the format command all data will be lost. Make sure that all important data has been backed up before formatting.		
	5.	Press Yes .		
	6.	A message will display once the formatting is completed. Press Cont .		
12.6	Work	ing with the Internal Memory		
Format the internal memory stick step-	Format existing	ting the internal memory before starting to store data is required if all g data needs to be deleted.		
by-step		Despite an automatic defragmentation, the internal memory gets fragmented after a while. Please format the internal memory periodically to maintain the instrument performance.		
	1.	Select the Manage page in the Main Menu.		
	2.	Select the Int. Memory .		
	3.	Press 🖡 Format.		
	4.	A warning message will appear.		
		By activating the format command all data will be lost. Make sure that all important data has been backed up before formatting.		
	5.	Press Yes .		
	6.	A message will display once the formatting is completed. Press Cont .		

12.7	Working with Bluetooth			
Description	Instruments can communicate with external devices via a Bluetooth connection. The instrument Bluetooth is a slave only. The Bluetooth of the external device will be the master, and therefore will control the connection and any data transfer.			
Establishing a connection step-by-	1. On the instrument ensure that the communication parameters are set to Bluetooth . Refer to "5.6 Interface Settings".			
step	 Activate Bluetooth on the external device. The steps required depend on the Bluetooth driver and other device specific configurations. Refer to the device user manual for information on how to configure and search for a Bluetooth connection. The instrument will appear on the external device as "TS0x_y_zzzzzzz", where x = the series (TS07), y = the angular accu- racy in arc seconds, and z = the serial number of the instrument. For example, TS07_3_1234567. 			
	3. Some devices ask for the identification number of the Bluetooth. The default number for a TS07 Bluetooth is 0000.			
	4. The instrument Bluetooth sends out the instrument name and serial number to the external Bluetooth device.			
	5. All further steps must be made in accordance to the user manual of the external device.			
12.8	Working with the SIM Card			
	 Keep the card dry. Use it only within the specified temperature range. Do not bend the card. Protect the card from direct impacts. 			
G.	Failure to follow these instructions could result in data loss and/or permanent damage to the card.			
Insert a SIM card step-by-step	$i = 0016651_{-001}$			
	The SIM card is inserted into a slot behind the lid with the logo, almost in the middle of the housing.			

1.	Turn the knob on the lid to unlock.
2.	Open the lid.

3.	 Hold the SIM card with the contacts facing to the instrument and the cut edge of SIM card facing downwards. Sliding in the SIM card differently could break the SIM card holder of the instrument.
4.	Slide the SIM card firmly into the slot until it clicks into position.
5.	Close the lid. Turn to lock.
6.	To remove the SIM card, gently press on the top of the card to release it from the slot.

13	Check & Adjust			
13.1	Overview			
Description	Leica Geosystems instruments are manufactured, assembled and adjusted to the best possible quality. Quick temperature changes, shock or stress can cause deviations and decrease the instrument accuracy. It is therefore recom- mended to check and adjust the instrument from time to time. This check and adjust can be done in the field by running through specific measurement pro- cedures. The procedures are guided and must be followed carefully and pre- cisely as described in the following chapters. Some other instrument errors and mechanical parts can be adjusted mechanically.			
Electronic adjustment	 The following instrument errors can be checked and adjusted electronically: Horizontal collimation error, also called line-of-sight error. Vertical index error, and simultaneously the electronic level. Compensator longitudinal and transversal index errors Tilting axis error. 			
Checking parts	 The following instrument parts can be checked: Circular level on the instrument and tribrach. Laser plummet. Screws on the tripod. 			
- 3	 During the manufacturing process, the instrument errors are carefully determined and set to zero. As mentioned, these errors can change and it is highly recommended to redetermine them in the following situations: Before the instrument is used for the first time. Before every high precision survey. After rough or long periods of transport. After long periods of work or storage. If the temperature difference between current environment and the temperature at the last calibration is more than 10°C (18°F). 			
13.2	Preparation			
	Before determining the instrument errors, the instrument has to be levelled using the electronic level. The tribrach, the tripod and the underground should be stable and secure from vibrations or other disturbances.			
-	The instrument should be protected from direct sunlight to avoid thermal warming. It is also recommended to avoid strong heat shimmer and air turbulence. The best conditions are early in the morning or with overcast sky.			
-	Before starting to work, the instrument has to become acclimatised to the ambient temperature. Approximately two minutes per °C of temperature differences of the start of the			

ence from storage to working environment, but at least 15 min, should be taken into account.

13.3	Adjusting Line-of-Sight and Vertical Index Error
	The procedures and conditions required to correct line-of-sight and vertical index errors are the same, therefore the procedure will only be described once.
Line-of-sight error	The line-of-sight error, or horizontal collimation error is the deviation from the perpendicular between the tilting axis and the line of sight.
	a Tilting axis b Line perpendicular to tilting axis c Horizontal collimation, or line-of-sight, error d Line-of-sight
Vertical index error	A vertical index error exists, if the 0° mark of the vertical circle reading does not coincide with the mechanical vertical axis of the instrument, also called standing axis.
	The V index error is a constant error that affects all vertical angle readings.
	 a Mechanical vertical axis of the instrument, also called standing axis b Axis perpendicular to the vertical axis. True 90° c Vertical angle is reading 90° d Vertical index error
	By determining the vertical index error the electronic level is adjusted automati- cally.
Access	1. Select Settings from the Main Menu .
	 On the Tools page, select Adjust.
	 3. Select: Hz-Collimation, or Vertical Index.

- Check and adjust step-by-step
- 1.
- Level the instrument with the electronic level. Refer to "4 Operation"-"Level up with the electronic level step-by-step".



message required.

Messages

Messages	Description
Hz-Angle is not suitable for adjustment!	Horizontal angle in face II deviates by more than 5° from the target point. Aim on the target point with an accuracy of min. 5°. Confirmation of the message required.
Timelimit exceeded! Please repeat Adjustment!	Time difference between measurements for results storage exceeds 15 minutes. Repeat the process. Confirmation of the message required.

Adjusting the Compensator

Compensator index error

13.4

a b b a a c c c c c c c c c c c c c c c
0016348_001

- a Mechanical vertical axis of the instrument, also called stand-ing axis
- b Plumb line
- c Longitudinal component (I) of the compensator index error
- d Transversal component (t) of the compensator index error

The compensator index errors (I, t) occur, if the vertical axis of the instrument and the plumb line are parallel but the zero points of the compensator and the circular level do not coincide. The calibration procedure electronically adjusts the zero point of the compensator.

A longitudinal component in direction of the telescope and a transversal component perpendicular to the telescope define the plane of the dual axis compensator of the instrument.

The longitudinal compensator index error (I) has a similar effect as the vertical index error and effects all vertical angle readings.

The transversal compensator index error (t) is similar to the tilting axis error. The effect of this error to the horizontal angle readings is 0 at the horizon and increases with steep sightings.

Access	1.	Select Settings from the Main Menu .
	2.	On the Tools page, select Adjust . K
	3.	Select Comp. Index .
Check and adjust step-by-step	1.	Level the instrument with the electronic level. Refer to "4 Operation" - "Level up with the electronic level step-by-step".
	2.	Press Store to measure the first face. No target has to be aimed at.
	3.	Store to release the measurement in the other face.

	If one or more errors are bigger than the predefined limits, the preduced must be repeated. All measurements of the current run a rejected and are not averaged with the results from previous run	oro- are 1s.		
	 Measure the target. The standard deviations of the determined adjustment errors can calculated from the second run onwards. 	n be		
13.5	Adjusting the Tilting Axis Error			
Description	The tilting axis error is caused by the deviation between the mechanical t axis and the line perpendicular to the vertical axis. This error affects horiz angles. To determine this error, it is necessary to point to a target located nificantly below or above the horizontal plane.	:ilting :ontal d sig-		
(3) (3)	The horizontal collimation error has to be determined before starting this pro- cedure.			
Access	1. Select Settings from the Main Menu .			
	2. On the Tools page, select Adjust .			
	3. Select Tilt Axis .			
Check and adjust step-by-step	1. Level the instrument with the electronic level. Refer to "4 Operat - "Level up with the electronic level step-by-step".	tion"		
	2. Aim at a point approximately 100 m from the instrument which is at least 27° (30 gon) above or beneath the horizontal plane.			
	3. Press Store to measure to the target point.			
	4. Change face and aim at the target point again	_		
	For checking the horizontal aim, the difference in Hz and are displayed.	d V		
	5. Press Store to measure to the target point.			
	The old and new calculated values are displayed.			

6. Either:

0016350_001

- Press **More** to measure another set to the same target point. The final adjustment values will be the calculated average from all the measurements.
- Press **Cont** to save the new adjustment data, or
- Press **ESC** to exit without saving the new adjustment data.

Messages

Adjust the circular

level step-by-step

13.6

The same messages or warning as in "13.3 Adjusting Line-of-Sight and Vertical Index Error" may appear.

Adjusting the Circular Level of the Instrument and Tribrach



- Place and secure the tribrach onto the tripod, and then secure the 1. instrument onto the tribrach.
- 2. Using the tribrach footscrews, level the instrument with the electronic level. To activate the electronic level, turn on the instrument, and, if tilt correction is set to **On**, the **Level & Plummet** screen appears automatically. Alternatively, press the 🐨 key from within any app and select Level.
- 3. The bubbles of the instrument and tribrach levels must be centred. If one or both circular levels are not centred, adjust as follows.

Instrument: If the bubble extends beyond the circle, use the Allen key supplied to centre it with the adjustment screws.

Tribrach: If the bubble extends beyond the circle, adjust it using the adjustment pin in conjunction with the adjustment screws. Turn the adjustment screws:

- To the left: and the bubble approaches the screw.
- To the right: and the bubble goes away from the screw.
- 4. Repeat step 3. on the instrument and tribrach until both circular levels are centred and no further adjustments are necessary.

After the adjustment, no adjustment screw should be loose.

1. Star
| 13.7 | Adjusting the Circular Level of the Prism Pole | | | | | | |
|--|--|---|---------------------------|--|--|--|--|
| Adjusting the circular
level step-by-step | 1. | Suspend a plumb line. | | | | | |
| | 2. | Use a pole bipod, to align the prism pole parallel to the plumb line. | 4b | | | | |
| | 3. | Check the position of the circular level on the prism pole. | | | | | |
| | 4. | a If the circular level is cen-
tred, no adjustment is nec-
essary. | | | | | |
| | | b If the circular level is not
centred, use an allen key
to centre it with the
adjustment screws. | 4a
T5_080 | | | | |
| | | After the adjustments, all adjusting | screws must have the same | | | | |

tightening tension and no adjusting screw should be loose.

Inspecting the Laser Plummet of the Instrument

F

13.8

The laser plummet is located in the vertical axis of the instrument. Under normal conditions of use, the laser plummet does not need adjusting. If an adjustment is necessary due to external influences, return the instrument to any Leica Geosystems authorised service workshop.

Inspect the laser plummet step-by-step

01431,021	360° 0 2.5 mm / 1.5 m 3 0° 3 0°
1.	Set up the instrument on the tripod approximately 1.5 m above the ground and level up.
2.	To activate the laser plummet, turn on the instrument, and, if tilt correction is set to On , the laser plummet will be activated automatically, and the Level & Plummet screen appears. Otherwise, press the rest key from within any app and select Level .
	Inspection of the laser plummet should be carried out on a bright, smooth and horizontal surface, such as a sheet of paper.
3.	Mark the centre of the red laser dot on the ground.
4.	Turn the instrument slowly through 360°, carefully observing the movement of the red laser dot.

- The maximum diameter of the circular movement described by the centre of the laser dot should not exceed 3 mm at a height of 1.5 m.
- 5. If the centre of the laser dot describes a perceptible circular movement or moves more than 3 mm away from the point which was first marked, an adjustment may be required. Inform your nearest Leica Geosystems authorised service centre. Depending on brightness and surface, the diameter of the laser dot can vary. At 1.5 m, it is about 2.5 mm.

13.9	Servi	cing the Tripod			
Servicing the tripod step-by-step	008706_00				
	The fol	lowing table explains the most common settings.			
		The connections between metal and timber components must always be firm and tight.			
	1.	Tighten the leg cap screws moderately, with the supplied allen key.			
	2.	Tighten the articulated joints on the tripod head enough to keep the tripod legs open when lifting the tripod off the ground.			
	-				

3. Tighten the allen screws of the tripod legs.

14	mySecurity				
Description	mySecurity is a cloud-based theft protection. A locking mechanism ensures that the instrument is disabled and can no longer be used. A Leica Geosystems service centre will inform local authorities if such an instrument turns up.				
	mySec	curity is activated in myWorld.			
Adding/removing instruments to/from	1.	Go to myWorld@Leica Geosystems (https://myworld.leica-geosystems.com).			
mySecurity	5	You must add your instruments to myProducts first, before the instruments can be added to mySecurity.			
	2.	 Select myTrustedServices/mySecurity. Available information for listed instruments: Activation date of the mySecurity service Renewal date of the mySecurity service Stolen status, in case of the instrument has been flagged as stolen 			
	3.	Click Add to add an instrument to mySecurity. Select the instrument from the selectable list. Click OK .			
	4.	4. Select an instrument. Click Remove to delete the instrument from mySecurity.			
Activating the theft protection	For an within	n active theft protection, the instrument must be connected to myWorld n a defined time interval.			
	If the ment nected	instrument is not connected within the defined interval, then the instru- is blocked and cannot be used. In this case, the instrument must be con- d to myWorld again and the theft protection must be reactivated.			
	1.	Click the check box to select an instrument.			
	2.	Click Details .			
	3.	For New mySecurity Renewal , set the start date of the theft pro- tection. Click In 3 months , In 6 months or In 12 months to define the connection interval.			
	4.	Click Set .			
	5.	Download and install the mySecurity Online Update program.			
	6.	The program scans for the instrument connection port automatically. In case automatic scanning fails, click Scan for a search of the port. Select the connection settings.			
	7.	Click Connect .			
		After the activation, the end date of the theft protection is displayed in the mySecurity Online Update program and on the instrument.			
	8.	Press Close .			
	9.	Click the Refresh button to update the screen information.			
	10.	Check the status, the activation date and the renewal date of the theft protection.			

Status information on the instrument	1.	Select Settings from the Main Menu .		
	2.	On the Tools page, select Info .		
	3.	Go to page 4/4 or Dates .		
	4.	mySec.Renewal Date : Displays the date when the instrument must be connected to mySe- curity. The date is transferred from myWorld to the instrument.		
	- B	Ten days before the mySec.Renewal Date , a reminder message is displayed each time the instrument is turned on.		
		When the mySec.Renewal Date has been exceeded, a message informs about the instrument lock. Go to myWorld to renew the theft protection.		
Report stolen instrument	1.	Go to myWorld@Leica Geosystems (https://myworld.leica-geosystems.com).		
	2.	Select myTrustedServices/mySecurity.		
	3.	Click the check box to select an instrument.		
	4.	Click Details .		
	5.	In the General section, click Report as Stolen.		
	6.	A warning comes up to confirm device as stolen. Click OK .		
	7.	The Status of the instrument changes to Stolen! . A Leica Geosystems service centre informs local authorities if such an instrument turns up.		
Locate stolen instru- ment	If a rep of the o	orted, stolen instrument is registered to myWorld, then the IP address computer is logged. The IP address is used to locate the instrument.		
	In myWorld/myTrustedServices/mySecurity , the Status of the instrument changes to Located .			
	Clicking The The A li	; Show Location shows: e date and time when the instrument was located e IP address of the computer ink to show the location on a map		

15	Care and Transport				
15.1	Transport				
Transport in the field	 When transporting the equipment in the field, always make sure that you either carry the product in its original container, or carry the tripod with its legs splayed across your shoulder, keeping the attached product upright. 				
Transport in a road vehicle	Never carry the product loose in a road vehicle, as it can be affected by shock and vibration. Always carry the product in its container and secure it.				
	For products for which no container is available use the original packaging or its equivalent.				
Shipping	When transporting the product by rail, air or sea, always use the complete orig- inal Leica Geosystems packaging, container and cardboard box, or its equiva- lent, to protect against shock and vibration.				
Shipping, transport of batteries	When transporting or shipping batteries, the person responsible for the prod- uct must ensure that the applicable national and international rules and regula- tions are observed. Before transportation or shipping, contact your local pas- senger or freight transport company.				
Field adjustment	Exposing the product to high mechanical forces, for example through frequent transport or rough handling, or storing the product for a long time may cause deviations and a decrease in the measurement accuracy. Periodically carry out test measurements and perform the field adjustments indicated in the User Manual before using the product.				
15.2	Storage				
Product	Respect the temperature limits when storing the equipment, particularly in summer if the equipment is inside a vehicle. Refer to "16 Technical Data" for information about temperature limits.				
Li-Ion batteries	 Refer to "16 Technical Data" for information about storage temperature range. Remove batteries from the product and the charger before storing. After storage recharge batteries before using. Protect batteries from damp and wetness. Wet or damp batteries must be dried before storing or use. A storage temperature range of 0 °C to +30 °C / +32 °F to +86 °F in a dry environment is recommended to minimize self-discharging of the battery. At the recommended storage temperature range, batteries containing a 40% to 50% charge can be stored for up to one year. After this storage period the batteries must be recharged. 				

15.3	Cleaning and Drying				
Product and accesso- ries	 Blow dust off lenses and prisms. Never touch the glass with your fingers. Use only a clean, soft, lint-free cloth for cleaning. If necessary, moisten the cloth with water or pure alcohol. Do not use other liquids; these may attack the polymer components. 				
Fogging of prisms	Prisms that are cooler than the ambient temperature tend to fog. It is not enough simply to wipe them. Keep them for some time inside your jacket or in the vehicle to allow them to adjust to the ambient temperature.				
Damp products	Dry the product, the transport container, the foam inserts and the accessories at a temperature not greater than 40°C /104°F and clean them. Remove the battery cover and dry the battery compartment. Do not repack until everything is completely dry. Always close the transport container when using in the field.				
Cables and plugs	Keep plugs clean and dry. Blow away any dirt lodged in the plugs of the con- necting cables.				

16	Technical Data							
16.1	Angle Measurement							
Accuracy	Available angular accuracies	Standard deviation Hz, V, ISO17123-3	Disp	Display resolution				
	["]	[mgon]	["]	[°]	[mgon]	[mil]		
	1	0.3	0.1	0.0001	0.1	0.01		
	2	0.6	0.1	0.0001	0.1	0.01		
	3	1.0	0.1	0.0001	0.1	0.01		
	5	1.5	0.1	0.0001	0.1	0.01		
	7	2	0.1	0.0001	0.1	0.01		

Characteristics

16.2

Absolute, continuous, diametric. Updates each 0.1 to 0.3 s.

Distance Measurement with Reflectors

Range	Reflector	Range	Α	Range	В	Range (
		[m]	[ft]	[m]	[ft]	[m]	[ft]	
	Standard prism (GPR1)	1800	6000	3000	10000	3500	12000	
	3 prisms (GPR1)	2300	7500	4500	14700	5400	17700	
	360° prism (GRZ4, GPZ122)	800	2600	1500	5000	2000	7000	
	Reflector tape 60 mm x 60 mm							
	Prism mode	150	500	250	800	250	800	
	Non-prism mode, R500	300	1000	500	1600	>500	>1600	
	Non-prism mode, R1000	600	1950	1000	3300	>1000	>3300	
	Mini prism (GMP101)	800	2600	1200	4000	2000	7000	
	360° Mini prism (GRZ101)	450	1500	800	2600	1000	3300	
	Shortest measuring	distance:		1.5m				
Atmospheric condi-	Range	Descri	ption					
tions	А	Strong heat sl	Strong haze, visibility 5km; or strong sunlight, severe heat shimmer					
	В	Light h light, s	Light haze, visibility about 20km; or moderate sun- light, slight heat shimmer					
	С	Overcast, no haze, visibility about 40km; no heat shimmer						

Accuracy

Accuracy refers to measurements to standard reflectors.

Distance meas- uring mode	std. dev. ISO 17123-4, standard prism	std. dev. ISO 17123-4, tape	Measurement time, typical [s]
Precise+	1 mm + 1.5 ppm	3 mm + 2 ppm	2.4
Precise&Fast	2 mm + 1.5 ppm	3 mm + 2 ppm	2.0
Tracking	3 mm + 1.5 ppm	3 mm + 2 ppm	< 0.15
Average	1 mm + 1.5 ppm	1 mm + 1.5 ppm	-

Beam interruptions, severe heat shimmer and moving objects within the beam path can result in deviations of the specified accuracy.

Characteristics

Туре	Description
Principle	Phase measurement
Туре	Coaxial, visible red laser
Carrier wave	658 nm
Measuring system	System Analyzer Basis 100 MHz - 150 MHz

Distance Measurement without Reflectors (Non-Prism mode)

Range

16.3

Pinpoint R500 (without reflector)

Kodak Gray Card	Range D		Range E		Range F	
	[m]	[ft]	[m]	[ft]	[m]	[ft]
White side 90% reflective	250	820	500	1640	>500	>1640
Grey side 18% reflective	100	330	150	490	>200	>820

Pinpoint R1000 (without reflector)

Kodak Gray Card	Range	Range D		Range E		Range F	
	[m]	[ft]	[m]	[ft]	[m]	[ft]	
White side 90% reflective	800	2630	1000	3280	>1000	>3280	
Grey side 18% reflective	400	1320	500	1640	>500	>1640	
Range of measurem	ent:	1.5 m t	to 1200 i	n			
Display unambiguou	s:	up to 1	.200 m				

Atmospheric conditions

Range	Description
D	Object in strong sunlight, severe heat shimmer
E	Object in shade, or overcast
F	Underground, night and twilight

Accuracy Standard ISO17123-4 Measure time, Measure time, measuring typical [s] maximum [s] 0m - 500m 2 mm + 2 ppm 3 - 6 15 15 >500m 4 mm + 2 ppm 3 - 6 Beam interruptions, severe heat shimmer and moving objects within the beam path can result in deviations of the specified accuracy. Standard deviation Measure time, typical [s] Tracking measuring* Tracking 5 mm + 3 ppm 0.25 * Accuracy and measure time depend on atmospheric conditions, target object and observation situation. Characteristics Description Туре Туре Coaxial, visible red laser Carrier wave 658 nm Measuring system System Analyzer Basis 100 MHz - 150 MHz Laser dot size Distance [m] Laser dot size, approximately [mm] at 30 7 x 10 at 50 8 x 20 16 x 25 at 100 16.4 Distance Measurement Reflector (>4.0km) Range Range A R500. Range B Range C R1000 [m] [ft] [m] [ft] [m] [ft] Standard prism 2200 7300 7500 24600 >10000 >33000 (GPR1) Reflector tape 600 2000 1000 3300 1300 4200 60 mm x 60 mm

Range of measurement:From 1000 m up to 12000 mDisplay unambiguous:Up to 12 km

Atmospheric condi-	Range	Description				
tions	A	Strong haze, visibility 5km; or strong sunlight, severe heat shimmer				
	В	Light haze, visibility about 20km; or moderate sun- light, slight heat shimmer				
	С	Overcast, no haze, visibility about 40km; no heat shimmer				
Accuracy	Measurement Mode	ISO17123-4	Measure time, typical [s]	Measure time, maximum [s]		
	P-Long (>4.0 km)	5 mm + 2 ppm	2.5	12		

Beam interruptions, severe heat shimmer and moving objects within the beam path can result in deviations of the specified accuracy.

Characteristics	Туре	Description		
	Principle	Phase measurement		
	Туре	Coaxial, visible red laser		
	Carrier wave	658nm		
	Measuring system	System Analyzer Basis 100MHz - 150MHz		
16.5	Conformity to Na	ational Regulations		
16.5.1	T503			
Conformity to national regulations	For products without • FCC Part 15 (app • Here is/ar othe tives The at th http	t radio transmitter or receiver: blicable in US) eby, Leica Geosystems AG declares that the product/s re in compliance with the essential requirements and er relevant provisions of the applicable European Direc- s. full text of the EU declaration of conformity is available ne following Internet address: ://www.leica-geosystems.com/ce.		
16.5.2	TS07			
Conformity to national regulations	 FCC Part 15 (app Hereby, Leica Ge TS07 is in compl European Direction The full text of the lowing Internet and Class 1 ef (RED) can out restriction The conformity for by the FCC part of prior to use and Japanese Radio In Compliance. This device in and the Japanese tion number 	rt 15 (applicable in US) , Leica Geosystems AG declares that the radio equipment type ; in compliance with Directive 2014/53/EU and other applicable an Directives. I text of the EU declaration of conformity is available at the fol- Internet address: http://www.leica-geosystems.com/ce. Class 1 equipment according to European Directive 2014/53/EU (RED) can be placed on the market and be put into service with- out restrictions in any EEA member state. nformity for countries with other national regulations not covered FCC part 15 or European Directive 2014/53/EU has to be approved o use and operation. se Radio Law and Japanese Telecommunications Business Law ance. is device is granted pursuant to the Japanese Radio Law (電波法) d the Japanese Telecommunications Business Law (電気通信事業法). is device should not be modified (otherwise the granted designa- on number will become invalid).		
Frequency band	Туре	Frequency band [MHz]		
	TS07, Bluetooth	2402 - 2480		
	TS07, WLAN	2400 - 2473, channel 1 to 11		

Output power	Туре		Output	Output power [mW]			
	Bluetoo	oth	<10				
	WLAN (802.11b)	50				
	WLAN	802.11gn)	32				
Antenna	Туре		Antenna	Gain [dBi]	Connector		
	Bluetoo	oth/WLAN	Internal Patch antenna	2 max.	-		
	GSM/U	MTS/LTE	Internal antenna	2 max.	-		
16.5.3	Dange	rous Goods R	egulations				
Dangerous Goods	Many products of Leica Geosystems are powered by Lithium batteries.						
Regulations	Lithium batteries can be dangerous under certain conditions and can pose a safety hazard. In certain conditions, Lithium batteries can overheat and ignite.						
		When carrying or shipping your Leica product with Lithium batteries onboard a commercial aircraft, you must do so in accordance with th IATA Dangerous Goods Regulations .					
		Leica Geosystems has developed Guidelines on "How to carry Leica products" and "How to ship Leica products" with Lithium batteries. Before any transportation of a Leica product, we ask you to consult these guidelines on our web page (http://www.leica-geosystems.com/dgr) to ensure that you are in accordance with the IATA Dangerous Goods Regulations and that the Leica products can be transported correctly.					
		Damaged or defective batteries are prohibited from being carrie transported onboard any aircraft. Therefore, ensure that the co of any battery is safe for transportation.					

16.6	General Technical Data of the Product

Telescope

Compensation

Туре Value Magnification 30 x Free Objective aperture 40 mm 1.55 m/5.08 ft to infinity Focusing Field of view 1°30'/1.66 gon. 2.7 m at 100 m Setting range Angular accuracy Setting accuracy ["] ["] [] [mgon] [gon] 1 0.5 0.2 ±4 0.07 2 0.5 0.2 ±4 0.07 3 1 0.3 ±4 0.07 5 1.5 0.5 ±4 0.07 7

2

0.7

±4

0.07

Level	Туре	Value
	Circular level sensitivity	6'/2 mm
	Electronic level resolution	2"
Control unit	Туре	Description
	TS03 (Greyscale) and TS07 (Color&Touch):	640 x 480 pixels (VGA), 9 lines, keyboard illu- mination
Instrument ports	Name	Description
	RS232	5 pin LEMO-0 for power, communication, data transfer This port is located on the rotation part of the instrument.
	SD card port	SD card port for data transfer
	USB host port	USB memory stick port for data transfer
	USB device port	Cable connections from USB devices for com- munication and data transfer
	Bluetooth	Bluetooth connections for communication and data transfer
	WLAN (TS07)	WLAN connection for Internet access, com- munication and data transfer
	LTE (optional)	Internet access

Pin assignments of the 5 Pin LEMO-0 port



- Pin 1: Power input Pin 2: not used а
- Ь
- Pin 3: Single ground С
- d Pin 4: RxD
- (RS232, receive data, In) е Pin 5: TxD
 - (RS232, transmit data, Out)

Instrument dimensions

0016621_001





Weight

Туре	Value
Instrument	4.3 kg - 4.5 kg (depending on hardware con- figuration)
Tribrach	760 g
Battery GEB331	110 g
Battery GEB361	340 g
Туре	Description

١

Tilting axis height

Туре	Description
Without tribrach	196 mm
With tribrach (GDF111)	240 mm

Recording	Model	Memo Type	ry	Capacity [MB]	Number of measurements		
	TS03	Interna memor	l Y	800	90,000		
	TS07	Interna memor	l y	800	90,000		
Laser plummet	Туре			Description			
	Туре			Visible red lase	r class 2		
	Location			In standing axis	s of instrument		
	Accuracy			Deviation from 1.5 mm at 1.5	plumb line m instrument height		
	Diameter of	laser point	:	2.5 mm at 1.5	m instrument height		
AutoHoight plummat	-			D 1.4			
Autoneight pluinnet	Туре			Visible red lace	r daga J		
				In standing avid	r CldSS Z		
		condcy		1.5 mm at 1.5	m instrument height		
	Diameter of	meter of laser point		2.5 mm at 1.5 m instrument height			
	Height accuracy ^{1,2}			1.0 mm			
	Measureme	Neasurement range ³		0.7 m to 2.7 m			
	Measureme	nt time, typ	oically	ally < 3 s			
	1 Star	ndard devia [.]	tion (1 s	igma) over mea	surement range		
	Object in shade, sky overcast, Kodak Grey Card (18% reflective), bal- anced tribrach foot screws						
	³ Instrument height from tilting axis						
	Avoid dirt on cover glass.						
	Avoid line-of-sight obstructions. The full spot needs to be on target.						
	िङ्ग For an u	best perfor upgrade of	mance u the screv	se the new Leic w is recommence	a tripods. For older tripods, led.		
Power	Туре			Description			
	External sup (via serial in	ply voltage terface)		Nominal voltag Range 12.0 V -	e 13.0 V DC 15.0 V		
Internal battery	Туре	Battery	Voltage	e Capacity	Operating time, typically*		
	GEB331	Li-lon	11.1 V	2.8 Ah	≤ 15 h		
	GEB361	Li-Ion	11.1 V	5.6 Ah	≤ 30 h		
	* Base may	ed on a sing be shorter	gle meas if batter	surement every ry is not new.	30 s at 25°C. Operating time		

	remperature				
specifications	Туре	Operating ten [°C]	perature	Storage temperature [°C]	
	All instruments	-20 to +50		-40 to +70	
	Battery	-20 to +50		-40 to +70	
	USB memory stick	-40 to +85		-50 to +95	
	Protection aga	ainst water, dus	t and sand		
	Туре	Protection			
	All instruments	IP66 (IEC 60529))		
	Humidity				
	Туре	Protection	· · ·		
	All instruments	Max 95% non condensing. The effects of condensation are to be effectively counterac- ted by periodically drying out the instrument.			
Arctic model	Operating ter	mperature [°C]	Stora	ze temperature [°C]	
	-35 to +50		-40 to	+70	
Electronic Cuide Light	T		Description		
EGL	Working range		5 m to 150 m	(15 ft to 500 ft)	
	Position accura	ЭСУ	5 cm at 100 m	(1.97" at 330 ft)	
_		,		· · ·	
Automatic corrections	The following a	utomatic correcti	ons are made:		
Automatic corrections	The following at • Line of sig	utomatic corrections of the series of the se	ons are made:		
Automatic corrections	The following at Line of sig Tilting axis Farth curv	utomatic correction th error s error ature	ons are made:		
Automatic corrections	The following at Line of sig Tilting axis Earth curve Standing a	utomatic correction ght error s error ature axis tilt	ons are made:		
Automatic corrections	The following at Line of sig Tilting axis Earth curve Standing a Vertical inc	utomatic correctio sht error error ature axis tilt dex error	ons are made:		
Automatic corrections	The following at Line of sig Tilting axis Earth curve Standing a Vertical inc Refraction	utomatic correctio ght error ature axis tilt dex error ator index error	ons are made:		
Automatic corrections	The following at Line of sig Tilting axis Earth curv Standing a Vertical ind Refraction Compensa Circle ecce	utomatic correction with error ature axis tilt dex error ator index error entricity	ons are made:		
Automatic corrections	The following at Line of sig Tilting axis Earth curve Standing a Vertical ind Refraction Compensa Circle ecce	utomatic correction with error ature axis tilt dex error entricity ction	ons are made:		
Automatic corrections	The following at Line of sig Tilting axis Earth curv Standing a Vertical ind Refraction Compensa Circle ecce Scale Correct By entering a so into account. Atmospheri Reduction t	utomatic correction ght error ature axis tilt dex error entricity ction cale correction, re- tic correction. to mean sea level distortion.	ons are made: ductions propc	ortional to distance can be taken	
Automatic corrections	The following at Line of sig Tilting axis Earth curv Standing a Vertical ind Refraction Compensa Circle ecce Scale Correct By entering a so into account. Atmospheri Reduction t	utomatic correction ght error ature axis tilt dex error entricity ction cale correction, re- tic correction. to mean sea level distortion.	ons are made: ductions propo	ortional to distance can be taken	

The atmospheric correction includes:

- Adjustments for air pressure
- Air temperature

For highest precision distance measurements, the atmospheric correction should be determined with:

- An accuracy of 1ppm
- Air temperature to 1°C
- Air pressure to 3mbar

Atmospheric corrections °C

Atmospheric corrections in ppm with temperature [°C], air pressure [mb] and height [m] at 60% relative humidity.



Atmospheric corrections °F

Atmospheric corrections in ppm with temperature [°F], air pressure [inch Hg] and height [ft] at 60% relative humidity.



16.8

Reduction Formulas

Reflector types

The reduction formulas are valid for measurements to all reflector types:

- To prisms
- To reflector tape
- Reflectorless measurements

Slope distance - corrections

Available formats depend on the instrument.

Format		Description	
• • •	Instrument display DBX ASCII GSI	•	Corrections for the atmospheric ppm are applied to the slope dis- tances according to the formu- las.
•	XML export	•	Output without corrections for the atmospheric ppm ppm is stored as metadata Corrections are applied during later input, for example to Leica Infinity

Formulas



The instrument calculates the slope distance, horizontal distance, height difference in accordance with the following formulas:

$$\Delta = D_0 \cdot (1 + ppm \cdot 10^{-6}) + AC$$

∠ Displayed slope distance [m]

- D₀ Uncorrected distance [m]
- ppm Atmospheric scale correction [mm/km]

AC Additive constant of the reflector [m]

 $\underset{_{TS,112}}{\rightharpoonup} = Y - A \cdot X \cdot Y$ $\square = X + B \cdot Y^2$ TS_113 Horizontal distance [m] \square Height difference [m] \square ⊿ * |sinζ| Υ ⊿ * cosζ Х ζ Vertical circle reading А $(1 - k / 2) / R = 1.47 * 10^{-7} [m^{-1}]$ $(1 - k) / (2 * R) = 6.83 * 10^{-8} [m^{-1}]$ В 0.13 (mean refraction coefficient) k R 6.378×10^6 m (radius of the earth)

Earth curvature (1/R) and mean refraction coefficient (k) are automatically taken into account when calculating the horizontal distance and height difference. The calculated horizontal distance relates to the station height and not to the reflector height.

17 Software Licence Agreement Software Licence This product contains software that is preinstalled on the product, or that is Agreement supplied to you on a data carrier medium, or that can be downloaded by you online according to prior authorisation from Leica Geosystems. Such software is protected by copyright and other laws and its use is defined and regulated by the Leica Geosystems Software Licence Agreement, which covers aspects such as, but not limited to, Scope of the Licence, Warranty, Intellectual Property Rights, Limitation of Liability, Exclusion of other Assurances, Governing Law and Place of Jurisdiction. Please make sure, that at any time you fully comply with the terms and conditions of the Leica Geosystems Software Licence Agreement. Such agreement is provided together with all products and can also be referred to and downloaded at the Leica Geosystems home page at http://leica-geosystems.com/about-us/compliance-standards/legal-documents or collected from your Leica Geosystems distributor. You must not install or use the software unless you have read and accepted the terms and conditions of the Leica Geosystems Software Licence Agreement. Installation or use of the software or any part thereof, is deemed to be an acceptance of all the terms and conditions of such Licence Agreement. If you do not agree to all or some of the terms of such Licence Agreement, you must not download, install or use the software and you must return the unused software together with its accompanying documentation and the purchase receipt to the distributor from whom you purchased the product within ten (10) days of purchase to obtain a full refund of the purchase price.

Appendix A	Menu Tree		
	Depending on local firmware versions the menu items may differ.		
Nenu tree	Depending on local firmware versions the menu items may differ. Setup Setup Setout Apps Setout Apps Setout Setout Tie Dist Tie Dist Traverse Ref.Line Ref.Line Ref.Line Ref.Arc Ref.Line Ref.Arc Ref.Line Ref.Dings Vork Ref.Dings Vork Regional Data Settings EDM FIP Adjust EDM FIP Adjust Statup Ref.Ding PIN		
	 Meas.Data Data Transfer Del.Data USB-stick SD card Int. Memory Codes Formats ScrShots 		

Description On the USB memory stick, files are stored in certain directories. The followin diagram is the default directory structure. Directory structure I APPLICATION DATA Alignment files (*.db) I CODES Codelists (*.cls) I DB I JOB FOLDER Databases (*.db) I I JOB FOLDER Databases (*.db) I I IMAGES Image files (*.bmp), stored in a subfolder per job. I DOWNLOAD I FORMATS I GPS Format files (*.frt) I GPS Image files (*.frt) I GPS Image files (*.frt) I SYSTEM Log files created from apps I LICENSE Licence file (*.key) I I ThreadId.txt I I ThreadId.txt I I Firmware files (FlexField.fw and Flex-field_EDM.fw) I I Firmware files (*.cfg) I I Firmware files (*.cfg)	Appendix B	Directory Structure On the USB memory stick, files are stored in certain directories. The following diagram is the default directory structure.		
Directory structure APPLICATION DATA Alignment files (*.db) CODES Codelists (*.ds) DB Image files (*.db) JOB FOLDER Databases (*.db) IMAGES Image files (*.bmp), stored in a subfolder per job. DOWNLOAD Image files (*.frt) GPS Format files (*.frt) GPS Image files (*.frt) SYSTEM Logfiles created from apps LICENSE Licence file (*.key) SYSTEM Log files (ErrorLog_*.txt and Loader-Log_*.txt) ThreadId.txt ThreadId.txt ThreadId.txt ThreadId.txt ThreadId.txt ThreadId.txt ThreadId.txt ThreadId.txt ThreadId.txt ThreadId.txt	Description			
	Directory structure	APPLICATION DATA CODES DB JOB FOLDER IMAGES DOWNLOAD FORMATS FORMATS GPS IMAGES JOBS LICENSE SYSTEM 	 Alignment files (*.db) Codelists (*.cls) Databases (*.db) Image files (*.bmp), stored in a subfolder per job. Format files (*.frt) GSI, DXF, ASCII and LandXML files (*.*) Logfiles created from apps Licence file (*.key) Log files (ErrorLog_*.txt and Loader-Log_*.txt) ThreadId.txt Firmware files (FlexField.fw and Flex-Field_EDM.fw) Configuration files (*.cfg) Language files (xx_Lang-xx.ui) 	

849684-1.0.0en

Original text (849684-1.0.0en) Published in Switzerland © 2018 Leica Geosystems AG, Heerbrugg, Switzerland

Leica Geosystems AG

Heinrich-Wild-Strasse CH-9435 Heerbrugg Switzerland Phone +41 71 727 31 31

www.leica-geosystems.com



