System 1200 OSGB36(15) Coordinate System Upload

The following guide outlines the process required to upload the OSGB36(15) Coordinate System into a Leica System 1200 instrument.

Step	Instruction	Screenshots
1	Make sure that the following files are in the correct location on the CF-Card: OSTN15GB.csc CF:\Data\GPS\Cscs\ OSGM15GB.gem CF:\Data\GPS\Geoid\ TRFSET.DAT CF:\DBX\ These files can be found in the following location on www.Leica-Geosystems.co.uk or www.uk.smartnet-eu.com	
2	With the CF-Card back in the System 1200, from the 'Main Menu' navigate to '**Tools**'(**6**), to enter the 'Tools Menu'…	
3	From the 'Tools Menu' select (**2**) '**Transfer Objects**', to enter the 'Transfer Objects menu'…	
4	In the 'Transfer Objects Menu' select (**03**) '**Coordinate Systems**' to be taken to the 'Transfer Coord System' screen, where coordinate systems can be uploaded to the instrument…	
5	Set on the 'Transfer Coord Systems' screen: 'From : CF Card' 'To : System Ram' Then select the OSGB Coordinate System and press Cont to upload to the instrument. *Note: Ok any warning messages and accept to overwrite files if prompted.* Once this stage is complete the coordinate system will be ready for use.